

Douglas County Surveyor's Record of  
Government Corners Renewed

23 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

$\frac{1}{4}$  Section Corner to Sections 10 and 11. 65  
Found - Orig. 10", now 36" W. Oak N.22°W. 447.5 ft. I open  
& find good scribing "1/2".

Orig. 20", now 44" W. Oak N.22°W. 447.5 ft. Shows #138  
good scars, I do not open.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$  S11/S10 T23S R5W.  
New BT's: 10" R. Fir bears S.26 $\frac{1}{2}$ °E. 111.0 ft. scribed  $\frac{1}{4}$  S11 CS BT.  
6" R. Fir bears S.11°W. 198.4 ft. scribed  $\frac{1}{4}$  S10 CS BT.

James W.  
Byron,

Jan. 25,  
1960  
C.S. 49/42

**RE-RENEWED CORNER NO. #138**

Corner to Sections 5 and 6 only. 66

Set 1" x 1" x 36" T. Iron.

Scribed: 8" Fir S.01°E. 26.2 ft.  
6" Fir S.06°W. 27.5 ft.

Standard  $\frac{1}{4}$  Corner to Section 5. 67

Set 1" x 1" x 36" T. Iron scribed:

16" Fir S.32°W. 34.9 ft.

Found - Orig. 10" Fir S.28°W. 201 lks., now 36"

$\frac{1}{4}$  Corner to Sections 5 and 6. 68

Set 1" x 1" x 36" T. Iron.

Scribed: 16" Fir S.50°W. 9.8 feet.

Found: 16" Fir S.85°E. 10.0 ft., scribed  $\frac{1}{4}$  S B.T. when 10".

SEE THIS CORNER (INFO ADDED TO RECORD 3/21/84 D.R.)

$\frac{1}{4}$  Corner to Sec. 19, T23-5W. & Sec. 24, T23-6W. 69

Found - G.L.O. Brass Cap Set 1943.

40" Fir S.33°E. 67 lks. (down)

36" Fir N.70°W. 147 lks. (a stump)

New BT's: 10" Fir N.70°E. 40.6 ft.

10" L. Cedar N.2°W. 49.2 ft.

**RE-RENEWED CORNER NO. #131**

Wilford N.  
Haines  
For Yoncalla  
Lumber Co.  
Aug. 1961  
M 23 - 33

Sec. Cor. to Secs. 13 & 24, T23-5W. & Secs. 18 & 19, T23-4W. 70

Found - Iron Pipe set in 1954, bent over, broken & buried in ground. Rev. #12

24" W. Fir S.75 $\frac{1}{2}$ °W. 20.4 ft. scribing still visible in partly  
covered scar.

40" D. Fir N.60 $\frac{1}{2}$ °W. 46.2 ft., good bark scribing visible.

Metal disc Mkd: "RE 2741" nailed to tree.

No trace of other bearing trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T23S	S13	S18
R5W	S24	S19 R4W

New BT's: 33" D. Fir S.7 $\frac{1}{2}$ °E. 199.3 ft. Mkd: T23S R4W S19 CS BT.

22" In. Cedar N.61°E. 223.6 ft. Mkd: T23S R4W S18 CS BT.

Corner is in fence corner, fences North - South & West.

Hilo E. Godfrey, Deputy County  
Vernon Tracy and Mike Stone  
April 25, 1963  
C. S. File No. 53/9

$\frac{1}{4}$  Sec. Corner to Sec. 24, T23-5W. & Sec. 19, T23-4W. 71

Found - 1 $\frac{1}{4}$ " Iron Pipe & uprooted & partly rotted Fir N.20°W. 26.4 ft.

Cut open & found good scribing "1/2".

Laurel sprouts, with rotten Laurel log lying on ground, S.35°E.

6.6 ft. Did not look for scribing in Laurel

DID NOT SET BRASS CAP - Iron Pipe in good condition.

New BT's: 8" D. Fir S.60°W. 13.3 ft. Mkd:  $\frac{1}{4}$  S24 CS BT.

9" Yew Tree N.12°E. 85.4 ft. Mkd:  $\frac{1}{4}$  S19 CS BT.

S. W. Corner D. L. C. No. 47. 72

Found - Orig. Stone with "C4" visible.

Set - 5/8" Iron Rod over the stone from which a:

28" W. Oak BT. with face rotted out, but with old axe  
marks bears N.5°E. 20.5 ft.

New BT's- 12" D. Fir, I scribed "SWC DLC 47" bears S.55°W. 54.5 ft.

30" D. Fir, I scribed "SWC DLC 47" bears N.21°E. 110.7 ft.

BRUCE A.  
SHANER  
for-D.M. Webb  
Map M 27 - 35  
Feb. 1964

FD. OK - R. Kimball  
11/80 M 86-73  
12/83  
M 75-78  
D. Benge

&