

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T.S. R 5

R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

122

Section Corner for Secs. 9, 10, 15 and 16

Found - A 1960 County brass cap on a 1 1/2" outside dia. I.P. protruding 9" above ground. Ren. #63

A 3/4" Iron rod protruding 8" above ground, top bent 4" North bears S.50 3/4°E., 10.9 ft. Ren. #19

(All bearings & distances to 1960 County brass cap)

14" now down & rotted, indeterminable size Oak. no scars, blazes or scribing found., bears S.46°E., 83.2 ft. Agrees well with record (Orig BT)

16" now possible stump hole found, no other evidence found, bears N.75°E., 71.94 ft. Agrees well with record. (orig. BT)

24" now 29" B. Oak with a fully healed double blaze bears N.83°E., 15.5 ft. (Brg. & Dist. per Ren. #63; BTs scribed in Ren. #19)

15" now 17" D. Fir with a fully healed double blaze bears N.65°W., 4.4 ft. (Brg. & Dist. per Ren. #63; BTs scribed in Ren. #19)

15" now 24" D. fir with a fully healed double blaze bears S.18°W., 27.2 ft. Ren. #63

7" now 16" D. fir with a fully healed double blaze bears S.49°E., 47.9 ft. Ren. #63

3/4" Iron rod protrudes 8" above ground, top bent 4" North, (bearings & distances taken to plumb position) bears S.50 3/4°E., 10.9 ft. designated as corner per Ren. #19.

(Rec. S.46°E., 11.6 ft. computed from Johnson's tie to orig. southeast BT in Ren. #19 & Byron's tie to orig. southeast BT in Ren. #63).

New Accessories:

5/8" x 30" Iron rod with DCSO alum. cap stamped "BO 1 1987" set flush with ground bears N.34°E., 14.5 ft.

5/8" x 30" I.R. with DCSO alum. cap stamped "BO 2 1987" set flush with ground bears S.47 1/2°W., 64.5 ft.

5/8" x 30" I.R. with DCSO alum. cap stamped "BO - 1987" set flush with ground bears N.37°W., 54.2 ft.

Corner lies approx. 150 ft. northeast of house and 9 ft. east of gravel driveway. Brass cap/I.P. to be destroyed in near future, a garage is to be located at corner position.

3/20/87

Southwest Corner DLC #40

123

Found - A large stone with top measuring 12" x 14". We did not dig up stone to take depth measurement. No distinguishing marks found. (Orig.) Ren. #108

A 5/8" iron rod set by W. Haines (M34-46) protrudes 6" above ground along north edge of stone bears North 0.7 ft. from center of stone. (Rec. North 0.5 ft. per M102-5).

32" now 24" dia. 3 ft. high D. fir stump with visible scribing in a partially healed double blaze "SWC DLC 40 BT" bears N.74°E., 11.4 ft. (agrees w/rec.) Bearing & distance taken from center of orig. stone. (BT per Ren. #106)

26" now a shattered stump of indeterminable size, no scribing or blazes found, bears N.42°W., 14.2 ft. (agrees w/rec.) bearing and dist. taken from center of orig. stone.

14" now 16" dia. madrone with shallow bark scribing "SWC DLC 40 CS BT" bears N.34°E., 46.2 ft. (Rec. N.34°W., 46.1 ft. bearing recorded in wrong quadrant and dist. is to 5/8" I.R.) Bearing and dist. taken from center of orig. stone.

New BT - 26" dia. 4 ft. high D. fir stump with a boat spike through a BT tag set on top. Boat spike stamped "BO 1" bears West, 11.1 ft. Bearing & dist. taken from center of orig. stone.

Corner lies at south west corner of Yoncalla Cemetery at the intersection of a east-west and north fence lines.

4/21/87

Douglas County Surveyors Office
Randall Smith, Party Chief
Terry Franssen, Witness
March 20, 1987
C.S. 62/40

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April 21, 1987
C.S. 62/40

Fd. I.R. 9/92
D. BENTZ 1992-0081
F. I.R. # BTs
1991-0058
B. ROGERS

RE-RENEWED
#124