

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 T. S. R 5 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORG. 91881

Section Corner for Secs. 9, 10, 16 and 15
CORNER REPORT ONLY

127

Found - A DCSO 2½" dia. brass cap set flush in concrete garage floor.
B.C. from Ren. #63. Brass cap set by Charles Canfield
property owner. (Note, not all stamping on brass cap visible,
some overlap of concrete.)

All Bearing objects and bearing trees found to have relationship
with brass cap as recorded in Ren. #124

Brass cap is flush in concrete of garage floor 3 ft. from east wall,
15.7 ft. from south wall, in middle bay of three car garage.

4/11/89

1/4 Corner for Sections 8 and 17.

128

Found - 3/4" iron rod with plastic cap marked "LS 1808" protrudes 1 ft.
above ground. (Per M 107 - 61)

12" chinquapin now 3 ft. tall broken and rotted hardwood stump
of indeterminate size, in a cluster of small chinquapins
No scribing, blazes or axe marks found, bears N.32°W., 22.4 ft.
(agrees with record). Orig. BT.

14" now stumphole with tipped out rotted chinquapin of indeter-
minable size, no scribing, blazes or axe marks found. Stump
hole bears S.68°W., 40.9 ft. (agrees with rec.) Orig. BT.

Set - 3/4" iron rod set by Robert Dean perpetuated by bearing trees
described below:

10" dia. Chinquapin double blazed and scribed "1/4 S8 CS BT" bears
N.34°W., 21.4 ft.

10" dia. D. fir double blazed and scribed "1/4 S17 CS BT" bears
S.33°E., 17.8 ft.

8" dia. D. fir double blazed and scribed "1/4 S17 CS BT" bears
S.46½°W., 27.3 ft.

Creek to the west looks to have eroded west. Orig. call is in bottom of
draw.

4/17/89

1/4 Corner for Section 7; and Sec. 12 of T.23-6

129

Found - 2½" dia. 1943 GLO brass cap on a 1" O.D. x 36" long iron
pipe found loose at bottom of creek. 1943 D. resurvey.

8" now 14" dia. cedar with illegible scribe amrks visible on a
partially healed rotted blaze, we open further. No other marks
found, ring count indicates blaze dates back to about 1943

GLO D. resurvey BT bears N.43°E., 21.2 ft. (Rec. N.44°E., 21.7')

14" fir bearing S.23°W., 34.3 ft. NOT FOUND.

Set - GLO BC/IP reset at record bearing and distance from 14" dia.
cedar (S.44°W., 21.7 ft.) BC/IP now protrudes 7" above creek
bottom. The marks "RESET 1990" are added to brass cap.

New BTs - 25" dia. D. fir double blazed and scribed "1/4 S12 CS BT" bears
S.74½°W., 29.3 ft.

13" dia. hemlock double blazed and scribed "1/4 S12 CS BT" bears
N.32½°W., 44.1 ft.

9" dia. hemlock double blazed and scribed "1/4 S7 CS BT" bears
S.83°E., 37.8 ft. Tree has a pistol butt; bearing and distance
go to center of tree at bottom blaze.

4/24/90

S. 1/4
1/4 Corner for Section 6; and Sec. 1 of T.23-6

130

Found - Corner is a 1½" iron post with brass cap. (1986 BLM, No record)

14" cedar bears N.52°W., 6.3 ft. well healed face and BLM

BT tag. See Haines Map M 48-3

32" Cedar bears N.19½°E., 25.3 ft. well healed face and BLM

BT tag.

We paint faces and wrote BT on trunk of all BTs with flourescent orange
paint. Corner sits on steep westerly slope 2 chaines west of bald knob
There is a BLM blazed line running south, and BLM boundary tags running
west from corner.

6/90

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April, 1989
C. S. 62/63

Fd
04/24
Doris Baker
For water house
12/93 4118-43
Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April 24, 1990
C.S. 64/9

Ken Hoffine, LS #2291
Gary Angiolet, witness
For: Lone Rock
Timber Co.
June, 1990
C.S. 63/104