

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 6 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Corner to Sections 19 and 20.

Found - G. L. O. Brass Cap at Corner. *See Ren. # 49*

The 26" Fir S.  $46\frac{1}{2}^{\circ}$ E. 19.8 ft. is uprooted & down,  
underneath several other down trees.

The 8" Hemlock N.  $36^{\circ}$ W. 10.6 ft., scribing visible, is 1  
leaning badly & will probably be destroyed when down  
timber is cleared out of the area.

New BT's: 10" Hemlock N.  $9^{\circ}$ W. 57.8 ft. Mkd:  $\frac{1}{4}$  S19 CS BT. - *SEE REN. # 49*  
18" D. Fir N.  $42^{\circ}$ E. 41.2 ft. Mkd:  $\frac{1}{4}$  S20 CS BT.

44

Milo E.  
Godfrey &  
Crew  
5/17/63  
C.S. File  
No. 52/102

Corner to Sections 2 and 1 only, T23-6W. (on S. Line T22-6W).

Found - GLO Brass Cap, set in 1943.

48" Fir S.  $13\frac{1}{2}^{\circ}$ E. (not S.  $26\frac{1}{2}^{\circ}$ E.) 71.9 ft., very plain axe scar.

54" Fir S.  $67^{\circ}$ W. 134.0 ft., uprooted & down.

New BT's: 12" White Fir S.  $62^{\circ}$ W. 27.0 ft. Mkd: T23S R6W S2 CS BT.

8" White Fir S.  $66^{\circ}$ E. 14.7 ft. Mkd: T23S R6W S1 CS BT.

*FOR TRAIL CORNER SEE C.S. 61/5 (INFO ADDED TO RECORD 3/21/64)*

45

Milo E. Godfrey, Deputy  
Wm. Steffel & M. Stone  
Feb. 26, 1964  
C. S. File No. 49/143

Closing Corner Sections 35 and 36, T22-6W. (on N. Line T23S R6W)

Found - G.L.O. Brass Cap set in 1943.

36" Fir Snag, dead & rotting, N.  $80^{\circ}$ E. 24.4 ft., scribing  
visible "T22S R6W S36 CC".

32" White Fir N.  $60^{\circ}$ W. (not S.  $60^{\circ}$ W.) very plain scar visible.

New BT; 11" White Fir N.  $33^{\circ}$ E. 97.3 ft. Mkd: T22S R6W CC S36 CS BT.

46

Section Corner to Sections 6 - 5 - 7 - 8.

Found - Gov't. Brass Cap set in 1957.

Stump of 110" Fir N.  $12^{\circ}$ E. 9.3 ft. (Orig. BT).

10" Cedar S.  $42\frac{1}{2}^{\circ}$ W. 70.0 ft., alive & standing, good condition.

6" Hemlock N.  $64^{\circ}$ E. 49.5 ft., alive but leaning badly,  
may not stand long. *Ren. # 14*

S.E. & N. W. Trees marked in 1957 are now gone.

New BT's: 12" D. Fir S.  $73\frac{1}{2}^{\circ}$ E. 79.0 ft. Mkd: T23S R6W S8 CS BT.

6" Hemlock N.  $45^{\circ}$ E. 56.0 ft. Mkd: T23S R6W S5 CS BT.

No trees near to N. W.

47

Milo E.  
Godfrey & Crew  
March 20,  
1964  
C. S. File  
No. 52/102

Sec. Cor. to Secs. 7 & 18, T23-6W. & Secs. 12 & 13, T23-7W.

Found - G.L.O. Brass Cap, 1957 survey.

Dead White Fir Snag bears N.  $39^{\circ}$ W. 39.6 ft., all scribing  
visible on open blaze.

White Fir, uprooted & down, bears S.  $30^{\circ}$ W. 33.7 ft.,  
scribing visible.

Doug. Fir, uprooted & down, bears S.  $68^{\circ}$ E. 25.7 ft. Face  
down, but old blaze had been chopped open. (Orig. BT.)

No other BT's. found at present time.

New BT's: 13" W. Fir S.  $81^{\circ}$ W. 30.8 ft. Mkd: T23S R7W S13 CS BT.

6" W. Fir N.  $42\frac{1}{2}^{\circ}$ W. 46.8 ft. Mkd: S12 CS BT.

8" Hemlock N.  $84\frac{1}{2}^{\circ}$ E. 42.2 ft. Mkd: T23S R6W S7 CS BT.

6" White Fir S.  $53^{\circ}$ E. 70.8 ft. Mkd: S18 CS BT.

48

Milo E.  
Godfrey &  
Crew  
May 8, 1964  
C. S. File  
No. 52/102

$\frac{1}{4}$  Sec. Cor. to Secs. 19 and 20.

The bearings & distances to the BT's. marked by the County  
Surveyor's Office, 1963 where changed by the Cadastral Surveyor  
and are as follows: *See former Ren. No. 44.*

17" Fir bears N.  $30^{\circ}$ E. 68 ft. mkd.  $\frac{1}{4}$  S20 CS BT.

11" Hemlock bears N.  $2^{\circ}$ W. 87 ft. mkd.  $\frac{1}{4}$  S19 CS BT.

New BT: 24" Fir N.  $85^{\circ}$ E. 35.6 ft. mkd:  $\frac{1}{4}$  S20 BT. The marks on the  
tree marked by Eggan in the 1957 resurvey by BLM  
were destroyed.

49

BLM, Floyd A.  
Brooks.  
May 1964  
C. S. File  
No. 52/102

BOOK  
By K. Hoff  
11/20/79  
8/94

RENEWED  
NO. 172