

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

72

Section Corner for Secs. 5, 6, 7 and 8.

Found - A 1955 GLO brass cap set 11" above ground and properly marked.
At the NW edge of BC, a 1" angle iron with a 1" B.C. set 4" above ground and marked "Wilford N. Haines" 239 survey point
Drain, Ore. Ren. #14

A 16" OBT, now 63" Fir stump tipped halfway over, bears N.12°E., 9.2 ft. with bark scribing over a well healed blaze "T23S R6W SS CS BT".

A White fir (Rec. Hemlock) 6" now 10" bears N.64°E., 49.5 ft. with a single well healed blaze. Vol. 30 Pg. 12713

A 10" now 14" Cedar bears S.42 1/2°W., 70.0 ft. with visible scribing "T23S R6W S7" in partly healed single blaze. Ren. #47

A 12" now 17" D. Fir bears S.72°E., (Rec. S73 1/2°E.) 79.0 ft. with a well healed double blaze.

A 6" now 14" White fir (Rec. Hemlock) bears N.45°E., 56.0 ft. with a well healed single blaze.

No new monument set.

New BT - A 5" Hemlock bears N.39°W., 42.8 ft. scribed "T23S R6W S6 CS BT" in a double blaze.

Corner is 150 ft. south of Brush Cr. Road.

3/9/78

73

S 1/16 for Secs. 6 and 5.

Found - A 1" T Iron with 1" brass cap set 3" above ground marked "Wilford N. Haines" 239 Survey Point, Drain, Oreg.

A 9" Fir with Haine's washer is down, broken stump bears N.44°W., 12.1 ft. with scribing "1/16 S6 BT" on single blaze.

A 7" Fir is down, broken stump bears S.69°E., 2.3 ft. with scribing "1/16S BT in single blaze.

Set - A 1" I.P. with brass cap set 6" above ground and marked: "Douglas County Surveyor" T23S R6W S 1/16 S6 S5 1978.

I place Haines' T Iron and brass cap under North lip of Douglas County Surveyor brass cap.

New BT's-A 10" W. Fir bears N.34°W., 92.2 ft., I double blaze and mark "S 1/16 S6 CS BT".

A 6" W. Fir bears N.55°E., 26.9 ft., I double blaze and mark "S 1/16 S5 CS BT".

Corner is at East edge of clearcut unit, at top of steep climb 1/4 mi. North of Brush Cr. Rd.

3/2/78

Center 1/4 Corner for Sec 12

Found - 1/2" iron rod. Ren. #59

18" D. Fir, healed over face, bears S.86°E., 70.5 ft.

18" D. fir BT, healed over face, bears N.45°W., 37.0 ft.

Set - Brass cap mkd. "T 23 S, R 6 W, W.M. C 1/4 S12 R.L.S. 430, 1981". This corner was set by Wilford Haines Dec. 1967. M 35 - 11 Ren. #59.

6/81

74

Section corner for Secs. 3, 2, 10 and 11.

Found - A 1943 GLO brass cap on 2" I.P. properly mkd. protruding 1.25 ft. above ground.

No original bearing trees found.

A 25" cedar now 34" bears N.31 3/4°E., 58.1 ft. with well healed double blaze.

A 50" fir, now 56" bears S.79°E., 17.8 ft. with a well healed previously chopped open scar.

Other BTs fall in slide area. Found no trace of BTs at record bearing and distances.

Set - Left 1943 cap in position to perpetuate 1943 resurvey.

New BTs - 7" ash bears S.43°W., 33.4 ft. Bark scribed "T23S R6W S10 CS BT" horizontal down tree trunk.

7" fir bears N.32°W., 14.7 ft. scribed "T23S R6W S3 CS BT" in a double blaze.

Location if approx. 200 ft. southerly of Andrew Creek.

5/25/82

75

R. B. Kimberling
Peter L. Earle
Douglas County Surveyors Office
March 2 & 9, 1978
C.S. 59/46

Bruce Shaner
For Woolley Enterprises
June 1981
79 - 78

Karen Reed, Douglas
County Surveyors
Office
Terrie Plouff
May 25, 1982
C.S. 61/36