

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 6

R.W.W.M.

ROSE CHAPMAN CO. EUGENE, ORE. 97401

82

1/4 Corner for Sections 12 and 13

Found - Corner is an iron post with 2 1/2" brass cap in good condition.
BLM 1943.

22" D.F. bears S.37°W., 11.5 ft. well healed face. put up a
BT tag. (BLM record is S.41°W., 19 lks.)

13" western red cedar bears N.55°E., 16.0 ft. Put up a Lone
Rock Timber location tag. (BT not of record)

We painted faces and wrote BT on trunk of all BTs with flourescent
orange paint. Corner lies on 50% east slope near top of spur ridge approx.
500 ft. south of road and 400 ft. west of creek.

3/90

Section Corner for Secs. 1, 2, 11 and 12

83

Found - Corner is an iron post with brass cap. 1943 BLM

A 15" D.F. with visible scribing and BLM BT tag that reads

T23S R6W Sec. 12, dist. 20 lks. bearing N.59 3/4°W. No Record

35" cedar snag with no visible scars and a BLM BT tag that reads
T23S R6W Sec. 1, dist. 62 lks. bearing S.49 1/2°W. (Orig. BT)

38" D.F. stump that has been tinned and treated with a BLM
BT tag that reads T23S R6W Sec. 1, dist. 46 lks. bearing
S.23 1/2°W. 1943 BLM BT.

49" D.F. well healed face and BLM BT tag that reads T.23S R6W
Sec. 2 dist. 98 lks. bearing S.27 1/2°E. 1943 BLM BT.

38" D.F. well healed face and BLM BT tag that reads T23S R6W
Sec. 12 dist. 283 lks. bearing N.25 1/2°W. (Rec. 273 lks. S.35°E)

We paint faces and wrote BT on trunks of all BTs with flourescent orange
paint. Corner sits on bench approx. 80 ft. north and apporx. 120 ft.
west of gravel road.

3/90

1/4 Corner for Section 24; and Sec. 19 of T.23-5

84

Found - Corner is a brass cap 0.5 ft. above ground. Corner has been
bent nearly 40° from plumb in a west direction. Ren. #35

36" fir stump bears N.70°W., 95.0 ft. scribing visible (1943)
1943 40" SE bearing tree is a blowdown badly decayed tree.

New Accessories:

Painted face and wrote BT on tree trunk of BTs with flourescent
orange paint.

Put Lone Rock Timber location tag on a 11" D.F. bearing S.25°W.,
6.8 ft.

Put Lone Rock Timber location tag on a 8" D.F. bearing S.22°E.,
9.5 ft.

Corner lies on steep west slope approx 2p chains west of gravel road, 15-
20 year old timber west and a clearcut to the east.

6/90

Center 1/4 Corner for Section 24

85

Found - Corner is a Haines T-iron 1.5 ft. above ground 1.0 ft. N.1°W. of
nail in rotten log for truce corner position. Ren. #36

20" D.F. bears S.9°W., 22.2 ft. well healed face and BT tag.

32" D.F. bears S.68°E., 30.5 ft. well healed face and BT tag.

New Corner- Put metal fence post in at truce corner location 1.0 ft.
S.1°E. of Haines T-Iron.

Painted faces and wrote BT on tree trunks of BTs. with flourescent orange
paint. Corner lies of small northwesterly side ridge. Just west of very
steep slope leading to flat ridge top with old dirt logging road.

6/90

Closing Corner for Section 36, T22-7 and Sec. 31 of T22-6 only.

86

CORNER REPORT ONLY

Found - corner is a 1956 GLO brass cap 1.0 ft. above ground in good
condition.

18" D.F. bears N.38 1/2°E., 60.0 ft. well healed face. WE tag.

42" D.F. bears N.39°W., 49.5 ft. well healed face and BT tag.

38" D.F. stump (covered with tin) bears N.16°W., 23.5 ft. scribing
visible and BT tag. NO RECORD

Haines T-Iron bears S.38 1/2°E., 14.0 ft. Ren. No. 9

Painted faces and wrote BT on tree trunks of BTs with flourescent orange
Paint. Corner sits on 40% west slope approx. 100 ft. east of Brush Ck. Rd.

10/90

Ken Hoffine, L.S. 2291
For: Lone Rock Timber Company
1990
C.S. 63/104

Ken Hoffine
For: Lone Rock
Timber Co.
Gary Angiolet
Oct. 1990
C.S. 63/127

RE-RENEWED BY THE COUNTY #93