

Douglas County Surveyor's Record of
Government Corners Renewed

T.23S T. S. R.6W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

101

Ken Hoffine
For: Lone Rock Timber
Feb. 1993
C.S. File 63/149

1/4 Corner for Sections 10 & 15.
Found - BLM Brass Cap in good condition.
Rotten remains of down log with partial scribing in burned
face bears S.65°E., 25.0 ft. (rec. S65½°E., 27.1 ft.)
Stump hole bearing N.18°W., 21.0 ft.
11" D.Fir bears N.35°W., 22.4 ft.
15" D.Fir bears S.30°W., 27.9 ft.
12" Hemlock bears S.40°E., 12.0 ft. I tag.
Note - Corner lies in stand of young trees approximately 600 ft.
east of Andrews Creek Rd. From metal fence post near north
end of the BLM Clearcut.

102

Ken Hoffine
For: Lone Rock Timber
April. 1993
M 117-3

Center 1/4 Section 23
Set - 5/8"x40" I.R. With 2½" aluminum cap mkd "Lone Rock Timber
T23S R6W S23 C1/4 1993 PLS 2291".
19" D.Fir bears N.10½°W. 46.58'. I scribe C1/4 S23 BT & tag
22" D.Fir bears N.84°W. 42.81'. I scribe C1/4 S23 BT & tag.
22" D.Fir bears S.36½°E. 28.73'. I scribe C1/4 S23 BT & tag.
20" D.Fir bears South 10.36'. I scribe C1/4 S23 BT & tag.
BLM location tag on a 40" D.Fir stump, bears S.54°E., 56.5'
for a BLM administrative staff compass survey for which
an approximate point for the C 1/4 bears N.47°E. 16.65'
from our aluminum cap C 1/4.
Note - Corner sits on steep North slope approximately 130 feet
North of landing at end of road. BLM clearcut to east. 4-93

103

Donald Peel
C.S. File 63/153
Mar. 27 1993

Sec. Cor. for Sec's. 18 & 19; 13 & 24 T.23-6
Found - Evidence of three original B.T.'s.
Rotted remains of 28" Fir. (Pitch stub & back ring, rotted
off at ground level - no marks. bears N.81 3/4°W., 16.5'
36" Fir stump, (I chopped open to visible scribe "T23SS24")
bears S.62°W., 17.2 ft.
Rotted remains of a 32" Fir or possibly a double Fir as
there was some bark on the inside of the rotted clump of
wood (no marks). Bears S 55½°E., 10.5 ft.
1943 BT. (37" Fir snag - visible scribe) bears S.22½°W.,
78.3 ft.
Set - 2"x42" iron pipe with Brass Cap mkd:
T.23 S.
R6W R5W
S13|S18
S24|S19
PLS 752
1993

New Accessories -
11" Fir - N.49½°E., 28.0 ft. scribed "T.23S R5W S18 BT"
14" Fir - S.28°E., 27.6 ft. scribed "T23S R5W S19 BT"
20" Fir - S.33½°W., 12.5 ft. scribed "T23S R6W S24 BT"
15" Fir - N.82½°W., 23.9 ft. scribed "T23S R6W S13 BT"
Note - The 1943 G.L.O. monument was set at proportionate distance.
"No remaining evidence of original corner". I found
evidence of three of the original (1853) bearing trees.
I advised the B.L.M. of finding said B.T.s and they sent
someone to verify the find. They advised me to set my own
corner monument based on the 1853 B.T.s., and they would
accept my monument.
Also found 1943 G.L.O. Brass cap and 37" Fir snag,
S.34°W., (solar) (rec. S45°W) 69.7 ft. (chopped in to
visible scribe)

104

O.F. Thiel
4/1902
C.S. File 64/48

SE Township Corner
Set - A fir post for Township corner
Mkd - Black Oak N.19°W., 62 lks.

RE-REVIEWED CORNER NO. 265