

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S T. S. R 7 W R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97401

142

Cont.

plainly visible on some letters. Our finding of scribing on the SE tree and no markings on the NW tree is contrary to the information contained in Ren. #105. It is also inconsistent with information shown on the corner renewal request card submitted on October 29, 1973 by D. Burkhardt, B.L.M. Forester who states he found good scribing "S 1/4" on NW tree. Furthermore, record bearings and distances from these apparent BT's place the corner point approx. 3 ft. NW of the present location of the squared wood stake. This possible corner location falls on an E-W cutting line, both apparent BT's have been tagged previously, and there are several cruisers initials chopped in the apparent BT's and nearby trees. Therefore, based on the discrepancies noted concerning the markings found and not found on the NW tree and the apparent young age of the scribe found on the SE tree, we do not feel we have sufficient evidence to monument the corner at this time.

5/2/74

143

Section corner to sections 14,13 23,24

Found- No trace of 1" x 1" x 36" iron set by Haines in 1959. Ren. #60
Set - Iron pipe with brass cap attached marked:

County Surveyor's Office	S14	S13
1974	S23	S24
	T23S	R7W

From two original bearing trees as follows:

An Orig. 24" now 52" D. Fir bears at record bearing and distance S 80°W 19.8 ft. Tree has a good scar, I do not open.

An orig. 16" now 30" D. Fir bears N53°E, 33.0 ft. (Record N50°E 33.0 ft) Scribing is visible on previously opened blaze.

A 7" now 10" D. Fir Ren. #60 bears N. 89°E, 18.6 Ft. (Record N82°15'E 17.2 ft.) Tree is well-healed.

Found fragmented scribing and copper washer at Haine's NW bearing tree Ren. #60, which is now down and shattered.

New BT- 7" white fir bears N29°E 7.7 ft., scribed "T23S R7W S13 CSBT"

5-8-74

144

1/4 Corner for Sections 17 and 20.

Found - Brass cap, firmly set and marked as in Ren. #57 .
Also found, the Maple BT mkd. by Wood in 1925 and the W.Oak BT mkd. by Byron in 1958.

Exact measurements were not taken at this time as the purpose of this visit was to verify that this corner was undisturbed at the request of an adjoining land owner.

8/26/74

S.W. Corner DLC #44

Corner set from information as described in 1961 survey by Don Garrett M42-11 CS File 55/2

Found- Bolt set firmly in ground shown to me by Mr. Fisher, owner of the property. Mr Fisher indicated that he had helped Garrett locate the bolt, and that Garrett had used it as the SW corner of the DLC. Remains of charred wooden post 1 ft. directly below bolt.

33 " dia. W.Oak bears north 557.7 feet. Tree has two blazed on west side.

Note: No original bearing trees found.

Renewal; Set brass cap at SW Corner DLC No.44 stamped:

COUNTY SURVEYORS OFFICE
1975

T 23 S R 7 W

D.L.C.#44
S W cor.

Bolt set on north side of cap. Cap set approx. 1 ft. above ground level, in mound of stone approx 1 ft. high and 2 1/2 ft dia. at base.

A white oak, 39" dia. bears N67°E, 146.4 ft. distance. Tree is blazed and scribed. "T 23 S R 7 W SW cor. DLC 44 CS BT"

12/2/75

145

Gary Langlitz
P. Earle
C.S. 56/51
5/2/74

Gary Langlitz
P. Earle
C.S. 56/51
5-8-74

Gary Langlitz
P. Earle
8/26/74
C.S. 57/2

L.E. Monrean
P.L.E.
J.H.C.
12/2/75
CS 57/39

RE-RENEWED CORNER NO. #159

JUN 75

1/76