

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23 T. S. R 7 R.W.W.M.

KORE-CHAPMAN CO. EUGENE, ORE. 97401

173

1/4 Corner for Section 1; and Section 6 of T.23-6

Found - Corner is a 1957 GLO brass cap 0.6 ft. above ground in good condition.

FD. OK  
3-91 MIII-72  
- - -  
FD. OK 2-93  
BY Hoffine  
C.S. 63/149

Haines T-Iron bears N.15°E., 16.7 ft. Ren. No. 49  
31" D. fir highstump bears S.37°E., 70.9 ft. metal cover and BT tags.

50" D. fir bears N.85°W., 142.8 ft. well healed face, Haines washer, put up location tag. (NO RECORD)

15" Chinquapin bears N.75°W., 133.0 ft. No scar. (BLM)

New BTs - Put up Lone Rock Timber location tag and blazed 14" D. fir bears N.38°W., 15.85 ft.

Put up Lone Rock Timber location tag and blazed 12" D. fir bears S.79°E., 14.10 ft.

Painted faces and wrote BT on tree trunks of bTs with flourescent orange paint. Corner sits onvery steep SE slope approx 100 ft. from top of flat ridge.

11/90

Ken Hoffine;  
For: Lone Rock  
Timber Co.  
Gary Angiliet,  
Witness  
C.S. 63/127

174

Section Corner for Section 1; and Section 6 of T.23-6

CORNER REPORT ONLY

Found - Corner is a 1956 GLO brass cap 1 ft. above ground in good condition.

Haines T-Iron bears S.37 3/4°E., 13.3 ft. Ren. No. 48

29" D. fir bears S.25°W., 63.8 ft. well healed face and BT tag. BLM

32" D. fir bears S.65°W., 61.1 ft. well healed face, Haines brass washer. NO record

50" D. fir bears N.86°E., 54.5 ft. well healed face. Haines brass washer, and we put up a Lone Rock Timber location tag. (NO REC)

Paint faces and wrote BT on tree trunks of BTs with flourescent orange paint. Corner lies on 40% west slope approx. 105 ft. east of Corner of Sec. 36 and 31 closing corner and approx. 205 ft. east of brush Creek Rd.

10/90

FD. OK 2/93 BY Hoffine  
C.S. 63/149

FD. OK 3-91  
MIII-72  
DCSO 2-564/23  
FD. Monument &  
References -  
2/14/92

STAMPED IN ERROR  
RENEWED SEE CORNER 1990

Center 1/4 Corner for Section 31

175

Found - A 2 1/2" 1983 brass cap on a 1 7/8" O.D. 36" long iron pipe out of ground and leaning against the northwest BT. Ren. #161

A 1/2" dia. 60" long iron rod loosely set and leaning northerly protrudes 28" above ground.

A broken piece of concrete collar is buried in loose ground found around base of iron rod.

an 18" Fir now an 18" DBH D. fir scribed "C 1/4 S31 BT" on a partially healed double blaze bears N.47°W., 19.0 ft. dist. (Record N.45°W., 19.0 ft.)

A 14" Fir now a 16" DBH 7 ft tall Fir stump scribed "C 1/4 S31 BT" on a partially healed double blaze bears S.28°W., 29.1 ft. (Record S.30°W., 29.1 ft.)

Set - Found brass cap is set in ground at intersecting record distance as measured from center of root crowns of found BTs. Monument is firmly set and protrudes approx 3" above ground. The brass cap is further marked to read "RESET 1991".

Found iron rod is loosely set on north edge of above mon. and protudes approx 3 1/2 ft. above ground.

New BTs - An 8" long boat spike with a 1 1/8" dia. top stamped "BO 1" is set flush in the top of a 52" dia. 3 1/2 ft. tall D. fir stump and bears N.81 1/2°E., 39.8 ft. distant.

A 26" DBH Fir scribed "C 1/4 S31 CS BT" on a double blaze bears N.07°W., 37.4 ft. distant.

Monument lays 600 ± ft. north from the end of BLM Rd. #23-7-6.6 on a nearly flat bench of a gradual northerly slope.

4/18/91

Douglas County  
Surveyors Office  
Stephen Flause  
T. Franssen  
April 18, 1991  
C.S. 64/13