

Douglas County Surveyor's Record of  
Government Corners Renewed

23 T. S. 8 R. W. W. M.

KONE-CHAPMAN CO., EUGENE, ORE. 31881

(continued over)

New BT: 12" R. Fir bears S.80°W. 62.5 ft. scribed  $\frac{1}{4}$  S24 CS BT. 15

$\frac{1}{4}$  Corner to Sections 23 and 24 16

Set by proportionate measurement.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$  S23/S24 T23S R8W

New BT's: 17" R. Fir S.26°E. 34.8 ft. scribed  $\frac{1}{4}$  S24 CS BT.

14" R. Fir N.13°W. 57.1 ft. scribed  $\frac{1}{4}$  S23 CS BT.

*Fd. O.K. Feb. 1967 V.R.T. & 2/81 by L. Roberts M 81-14*

Section Corner to Sections 22 - 23 - 26 - 27. 17

Found - Sandstone Rock Slab 14" x 10" x  $\frac{1}{4}$ " with 2 notches on present south face. Stone has apparently slid down hillside about 16" to 18" from corner.

Rotten Fir Snag N.26°E. 48.8 ft., scribing visible "23 R8 S2" on remaining portion of old face.

Rotten Fir Snag, S.75°E. 19.8 ft. scribing visible on remaining portion of old face "R8W".

Fir Tree, alive, now 48", S.25 $\frac{1}{2}$ °W. 91.1 ft., shows good scar.

Stump Hole with young maple around it. N.30°W. 70.6 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962

S22 | S23 T23S  
S27 | S26 R8W

Set Rock with notches alongside.

New BT's: 30" D. Fir N. 8°W. 29.2 ft. Mkd: T23SR8W S22 CS BT.

8" D. Fir N.32°E. 22.5 ft. Mkd: T23S R8W S23 CS BT.

16" D. Fir S.8°W. 41.7 ft. Mkd: T23S R8W S27 CS BT.

9" D. Fir South 37.3 ft. Mkd: T23S R8W S26 CS BT.

Closing Corner for Sections 6 and 5., T23-8W. 18

Found - 58" Fir N.36°W. (not N.44°W.) 29.6 ft., cut open & fd. good scribng.

34" Fir S.20°W. 27.1 ft., shows very good axe scar.

Badly rotted W. Fir Stump N.40°E. 34.3 ft., portion of flat face & axe marks but no scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T22S  
CCS 6/S 5 T23S R8W

New BT: 10" D. Fir S.74°E. 27.0 ft. Mkd: T23S R8W CC S5 CS BT.

Note - Found  $\frac{1}{4}$ " I. Pipe 15" above ground with cap stamped N.86°E.

3.2 ft. from corner as set above. This corner probably set by Long Bell.

Sec. Cor. to Sections 31 and 32 only, T22-8W. North Line of T23-8W. 19

Found -  $\frac{1}{4}$ " Iron Pipe, 15" above ground with cap stamped S31/S32

S 6

60" Fir N.70°W. 13.9 ft. (to face) with fairly plain bark scribing "S31 T22S R8W".

Rotten Remains of Fir Stump N. 8°E. 23 ft, too far gone to find marking.s

New BT: 5" B. Fir N.38°E. 31.5 ft. Mkd: S32 CS BT.

Closing Corner to Sections 4 and 3. 20

Found - Old Fir Stump S.52 $\frac{1}{2}$ °E. 179.5 ft., cut open & fd. it had been opened many years ago & grown over, axe notch at bottom of badly burned old face, no scribing found.

Stump hole with Fir Roots S.31°W. 91.1 feet.

Note - These 2 BT's. were same trees used as BT's. for Stan. Cor., Secs. 3 & 4, which was 60 lks. E. of this Corner.

This location is 10 ft. longer than record dist. from CC.

Secs. 33 & 34, T22-8W. as set by Cadastral Survey, 1963.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T23S R8W C C S 4/S 3

New BT's: 31" Black Oak S.84°E. 137.5 ft. Mkd: T23S R8W CC S3 CS BT.

17" White Oak N.13°W. 23.8 ft. Mkd: T23S R8W CC S3 S4 CS BT.

No tree near in Section 4.

Note - Corner lies 5 ft. South of E. & W. Fence Line.

Brass Cap at C.C. Secs. 33 & 34 bears N. 87°W. 221.7 ft.

James W. Byron  
For J. H. Connon  
Oct. 1960  
C.S. File No. 52/57

Milo E. Godfrey, Deputy  
Vernon Tracy and Mike Stone  
August 24, 1962  
C. S. File No. 49/49

Milo & Crew  
Jan. 22, 1963  
C.S. 52/14

Jan. 1963  
E. S.  
File  
No. 52/14

Milo E. Godfrey  
Wm. Stoffel & Mike Stone  
Oct. 2, 1963  
C. S. File No. 52/14

*FOUND  
March 1967  
V.R.T.*