

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

26  
S. W. Corner of Geo. Paine D. L. C. No. 39.  
Re-establish corner from an Original Oak BT., 30" diam.,  
chopped out scar and found scribe marks. #32  
Ran N.65°W. 308.9 ft. and set and Iron Binder Shaft 1" x 50",  
Also an Oak Post.  
An Ash, down & rotten, bears S.80°W. 132 feet.  
Marked New BT: An Oak 12" S.86°30'W. 32.3 feet.

J. W. Cole, Deputy  
Smick - Haines - Wlt.  
Warren Cheever  
Feb. 29, 1921.  
C.S. 1015, pg. 59, 60  
E.S. 20, pg. 28

27  
N. W. Corner of Geo. Paine D. L. C. No. 39.  
Set this Corner from tie given to Section Corner.  
Set an Iron Flow Coulter, also an Oak Post.  
Marked - An Oak 24" diam. S.14.2°E. 104.5 feet. 33  
An Oak 24" diam. S.73°20'E. 112.5 feet.

28  
1/4 Corner to Sections 17 and 20.  
Found - Orig. 12", now 28" Fir N.30°W. 59.4 ft., open & find  
partial "S" & notch at bottom of face. BT. is down.  
No trace other Orig. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S 17 T23S  
Office, 1965 S 20 R8W  
New BT's: 16" D. Fir N.8°E. 36.2 ft. Mkd: 1/4 S17 CS BT.  
6" D. Fir S.3°E. 15.4 ft. Mkd: 1/4 S20 CS BT.  
Note - This corner lies on S. edge of Jeep Road bears S.55°E.

Vernon "Ray" Tracy  
Terry Connell  
June 1965  
C. S. File No. 54/12

29  
Section Corner to Sections 17 - 18 - 19 - 20.  
Found - 4" Sq. Post at Corner. #100  
Orig. 24", now 26" Hemlock N.4°E. 8.6 ft., laying  
face down.  
Orig. 18", now 28" Hemlock S.76°E. 14.5 ft., open, face  
badly rotted.  
Orig. 16", now 24" Maple. S.13°W. 29.0 ft., shows good scar.  
Did not open.  
Orig. 24", now 31" Hemlock N.22°W. 31.7 ft., open & shows,  
"W" scribe. This BT. burned at base.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R8W S 18 | S 17  
Office, 1965 S 19 | S 20  
New BT's: 15" Hemlock N.25°W. 33.0 ft. mkd: T23S R8W S18 CS BT.  
20" Cedar N.81°E. 11.5 ft. Mkd: T23S R8W S17 CS BT.  
Old BT: 28" Hemlock S.76°E. 14.5 ft. Mkd: T23S R8W S20 CS BT.  
This corner lies in bottom of small ravine, course South.

30  
North 1/4 Corner to Section 1 only, T24-8W.  
(South Boundary T23-8W.)  
Found - 3" Sq. Post at Corner.  
Orig. 15", now 40" Fir N.16 1/2°W. 40.3 ft., open & shows "  
1/4 S" scribe, now Snag 85.0 ft. high.  
Orig. 12", now 20" badly rotted stump, S.85°W. 52.8 ft.,  
shows "1/4 S" Scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T24S 1/4 S 1 R8W  
New BT's: 11" D. Fir S. 1° E. 15.7 ft. Mkd: 1/4 S1 CS BT.  
8" D. Fir S.67°W. 18.5 ft. Mkd: 1/4 S1 CS BT.

Vernon R.  
Tracy &  
Crew  
August  
1965  
C. S.  
File  
No. 49/84

Aug. 6, 1965

FR. OK. by:  
L. ROBERTS  
MARCH, 1982  
M 91-74