

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

31

Wit. Cor. to Sec. Cor. Secs. 1 and 12, T23-8W. and
Secs. 6 and 7, T23-7W.
Found ~~7~~ Orig. 20", now 30" W.Oak N. 70° E. 52.8 ft., chopped open
open approx. 40 yrs. ago, hollow, down, no scribe found.
10", now 15" W.Oak N. 53° W. 29.0 ft., Open & find "CS" scribe.
This BT. marked by Cole, 1921, recorded in Vol. 3, Pg.89,
Co.Surv.Records.

No trace of other orig. BT's, nor $\frac{3}{4}$ " I.R. set by Cole.
Set - Brass Cap at Wit.Cor.Mkd: County Surveyor's Office, 1965
20 ft. North & T23S R8S W.C.

S 1	S 6
S 12	S 7

 R7W
 $\frac{3}{4}$ " I.R. for Cor.
in Creek Bottom

New BT's: 11" W.Oak N. 64° W. 22.0 ft. Mkd: W C T23S R8W S1 CS BT.
10" W.Oak N. 33° E. 21.3 ft. Mkd: W.C.T23S R7W S6 CS BT.
24" B.Oak S. 7° E. 40.5 ft. Mkd: W.C.T23S R7W S7 CS BT.
14" W.Oak S. 65° W. 44.6 ft. Mkd: W.C.T23S R8W S12CS BT.

32

S. W. Corner D. L. C. No. 39.
Found - BT. as mkd. by Cole, recorded Ren. #1, T23-7W. REN. #26
12", now 27" W.Oak S. 86 $\frac{1}{2}$ ° W. 32.3 ft. Open & find "C" scribe.
No trace of "Iron Binder Shaft".

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1965
T23S R8W / S.W. DLC 39

New BT's: 10" Ash N. 14° W. 6.0 ft. Mkd: SW DLC 39 CS BT.
14" Ash N. 49° E. 18.5 ft. Mkd: SW DLC 39 CS BT.

This corner lies 3.0 ft. West of old fence, course N. 18° E.

33

N. W. Corner D. L. C. No. 39.
Found - 24", now 28" W.Oak S. 73° E. 112.5 ft. Open & find "C" Scribe.
24", now 31" W.Oak S. 14° E. 104.5 ft., shows good scar. Do not open.
No trace of plow coulter set for corner monument, as recorded
Ren. #27.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1965
N.W. D.L.C. 39 T23S R8W

Note - Since BT's. are alive & in good condition, we do not mark
new ones. Corner lies at Fence Corner, course S. 17° W. & S. 75° E.
Dec. 21, 1965

34

Closing Corner to Secs. 1, T24-8W. & Sec. 6, T24-7W.
Found - County Brass Cap, properly mkd., See Ren. #80, T23-7W. SEE ALSO #113
T23S R8W

S 36/	R7W
T24S S 1/S 6	

All BT's. down & dead or gone completely.

New BT's: 8" W.Fir East 32.8 ft. Mkd: "CC T24S R7W S6 CS BT.
6" D.Fir S. 53° W. 74.2 ft. Mkd: "CC S 1 CS BT".

Note - This corner lies 30 ft. south of old logging road.

April 18, 1966

35

Wit. Corner to $\frac{1}{4}$ Corner to Sections 7 and 18.
Found - Orig. 40", now 54" D. Fir Corner Tree, no scribing found.
Orig. 14", now 18" Maple N. 25° E. 12.5 ft., Open, center rotted
away, no scribing found.

Orig. 12", now 18" D. Fir S. 58° W. 19.8 ft. Open & find
poor " $\frac{1}{4}$ " S" on burned face. Since distances E. or W.
would be too large to set Wit. Cor., we run North 55.0 ft. and
Set - Brass Cap for Wit. Cor. Mkd: County Surveyor's Office, 1966

Wit. Cor. T23S R8W

S 7	S 18
55' S. to Corner.	

New BT's: 23" D. Fir N. 76° E. 71.1 ft. Mkd: W.C. $\frac{1}{4}$ S 7 CS BT.
23" D. Fir S. 74 $\frac{1}{2}$ ° E. 52.2 ft. Mkd: W.C. $\frac{1}{4}$ S18 CS BT.

Note - Actual Corner location & BT's. will be destroyed by road
construction. Witness Corner lies on steep, south slope.

Vernon "Ray" Tracy
Mike Stone & Jerry Layne
Dec. 1965 and January 1966
C. S. File No. 52/125

Vernon "Ray"
Tracy & Crew
April 1966
C.S. File
No. 49/41

Vernon "Ray" Tracy
Mike Stone and Jack Heritage
April 20, 1966
C. S. File No. 54/12