

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 97001

Vernon "Ray" Tracy  
Jack Heritage & E. West  
December, 1966  
C. S. File No. 54/12

Section Corner to Sections 5 - 6 - 7 - 8. 41

Found - Unrecorded 1½" I. P. with cast iron Cap blazed on top & marked.  
Orig. 50" Fir N. 1° E. 14.5 ft. (face) Find old axe mark in remains of bark at base of badly decayed stump.  
Orig. 24" Fir S. 31° W. 19.8 ft. (to hole) remains of turned-out tree. No scribe found.  
Orig. 24", now 30" Fir, badly decayed stump, N. 79° W. 31.7 ft. (face) Find "BT" bark scribe in very poor condition at base of stump.  
No trace of BT. to SE.  
New BT's: 17" R. Cedar N. 45° E. 17.9 ft. mkd. T23S R8W S 5 CS BT.  
13" D. Fir N. 56° W. 17.3 ft. mkd. T23S R8W S 6 CSBT.  
17" Hemlock S. 11° W. 13.8 ft. mkd. T23S R8W S 7 CS BT.  
14" D. Fir S. 75° E. 15.0 ft. mkd. T23S R8W S 8 CS BT.  
Note - This corner lies approx. 100 ft. South of road, course E - W.

Closing Corner to Sections 7 and 18 only, T23-8W. 42

Found - Orig. 24", now 30" W. Fir, 14' high snag, N. 27° E. 58.1 ft., previously opened & shows Scribe. Also BT scar visible.  
Orig. 24", now 42" Fir, Alive, N. 57° E. 24.4 ft., shows old scar on edges where someone attempted to cut in & expose scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23 S R9W S 7 R8W  
Office, 1966 CC S 18  
New BT's: 12" Hemlock N. 36° E. 27.8 ft. mkd. T23S R8W S 7 CC CS BT.  
15" D. Fir S. 37° E. 9.3 ft. mkd. T23S R8W S18 CS CS BT.  
Note - This corner lies in flat, swampy area on edge of dense vinemaple.

¼ Corner to Sections 21 and 28. 43

Found - Orig.? 30", now 38" Cedar, S. 55° W. 5.9 ft. (not S.55°E.), now badly burned & hollow. No scribe found.  
No trace of any tree as described to S.E.  
Orig. 40", now 45" Fir Snag 30' high, N. 79° E. 17.8 ft. Open & find "S" scribe & reverse.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R8W  
Office ¼ S 21  
1966 S 28  
New BT's: 11" Hemlock N. 42° W. 20.6 ft. mkd. ¼ S21 CS BT.  
11" Hemlock S. 70° E. 38.2 ft. mkd. ¼ S 28 CS BT.  
(This tree is most southerly, two hemlocks joined at base.)  
Note - This corner lies approx. 50 ft. west of spur, sloping N.E.

¼ Corner to Sections 34 and 35. 44

Found - Corner Stone 16" x 14" x 4" mkd. "¼" on N. face.  
Orig. 36", now 48" Fir, Dead, N. 45° E. 15.8 ft. Open & find "4S" scribe on burned face.  
Orig. 4" Fir, now only rotted remains. S. 56½° W. 40.3 ft. Find axe notch, no scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyors T 23 S R 8 W  
Office, 1966 ¼ S 34/S 35  
New BT's: 10" Hemlock N. 53° E. 29.8 ft. mkd. ¼ S 35 CS BT.  
7" D. Fir N. 52° W. 16.7 ft. mkd. ¼ S 34 CS BT.  
Note - Corner lies on gentle, north slope approx. 215 ft. S. of Creek.

Sec. Corner to Sections 20 - 21 - 28 - 29. 45

Found - Orig. 60", now 76" Fir, N. 76° W. 45.5 ft. Open & find "B" scribe & reverse, face apparently burned before blaze healed over.  
No trace of other original bearing trees.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R8W  
Office S 20 S 21  
1966 S 29 S 28  
New BT's: 16" Hemlock N. 79° W. 13.9 ft. mkd. T23S R8W S20 CS BT.  
12" Hemlock S. 31½° W. 24.4 ft. mkd. T23S R8W S29 CS BT.  
9" Hemlock S. 25° E. 19.0 ft. mkd. T23S R8W S28 CS BT.  
16" Hemlock N. 54° E. 26.3 ft. mkd. T23S R8W S21 CS BT.  
Note - This corner lies on top of small spur, sloping to N.W. in heavy timber.