

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R.W.W.M.

EDGE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 T 23 S S 11 CC S 14

New BT's: 5" Maple S. 74° W. 26.4 ft. mkd. CC S14 CS BT.
7" D.Fir S. 54° E. 12.6 ft. mkd. CC S11/S14 CS BT.

Note - This corner lies on very steep, N. slope. Sec. Cor. of S12 & S13, T23-8 bears N. 110.2 ft., see below.

71

Sec. Corner to Sections 12 and 13 only, T23-8W.

Found - Badly, broken Sandstone with 2 notches on one piece & possible notch on edge.

Orig. 30", now 50" Fir, S. 1° W. 16.5 ft. Alive, prev. opened & rehealed. Open & find axe notch & burned face with possible scribe mark. Rigg count 100+ years to face, opened 70+ years ago.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 T 23 S S 12 S 13

New BT's: 12" Maple N. 78° E. 26.8 ft. mkd. T23S R8W S12 CS BT.
5" D.Fir S. 25½° E. 27.8 ft. mkd. S13 CS BT.

Note - This corner lies on small bench 110.2 ft., N. of Cl. Corner, above.

72

Sec. Cor. to Sections 34 & 35 only, T23-8W.

Found - Orig. 8", now 12" Fir, N. 75° E. 20.5 ft. Open & find "W S" scribe & reverse. Alive.

N.W. & S.W. BT's. down, bark scribe visible on N.W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 S 34/S 35 T 23 S R8W T 24 S

New BT's: 12" D. Fir N. 75° E. 20.5 ft. Rescribed "T23S R8W S35 CS BT".
17" D.Fir N. 63° W. 69.6 ft. mkd. T23S R8W S34 CS BT.

Note - This cor. lies approx. 66 ft. E. of spur ridge, course S. and approx. 182 ft. E. of corner of Sections 2 & 3, T24-8W, see below.

73

Section Corner to Sections 3 and 2, T24-8W.

Found - Orig. 14", now 30" W.Fir S. 17° W. 87.1 ft. Open & find frag. scribe on mostly rotted face. Tree now snag.

Orig. 18", now 42" Fir N. 7° W. 33.7 ft. Alive, shows good scars. We do not open.

No trace of S.E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 S 3/S 2 T 23 S R8W T 24 S

New BT's: 5" W.Fir S. 19° W. 8.2 ft. mkd. S3 CS BT.
7" D.Fir S. 39° E. 11.6 ft. mkd. T24S R8W S2 CS BT.

Note - Corner lies on steep, west slope, approx. 116 ft. W. of top of spur, course S. & approx. 182 ft. W. of Sec. Cor. of Secs. 34 & 35, T23-8W

74

¼ Corner to Section 35 only, T23-8W.

Found - Orig. 40", now 46" Fir N. 71° W. 9.2 ft., now badly decayed Snag. We open & find "¼ S" scribe.

Orig. S.W. BT., down & rolled out of place.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 S 35 T 23 S R8W T 24 S

New BT's: 11" Hemlock N. 38½° W. 21.6 ft. mkd. ¼ S35 CS BT.
15" D. Fir N. 30° E. 21.2 ft. mkd. ¼ S35 CS BT.

Note - This cor. lies on gentle, northerly slope of spur ridge, approx. 215.0 ft. East of ¼ S2, T24-8W., see below.

75

¼ Corner to Section 2 only, T24-8W.

Found - Orig. 60", now 66" Fir, N. 40° E. 10.6 ft. Alive, we chop open & find "BT" scribe & reverse.

Orig. 5", now 22" Cedar, S. 25° E. 28.4 ft. Alive, shows faint scar, Do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 S 2 T 23 S R 8 W T 24 S

New BT's: 21" Cedar S. 29° W. 20.7 ft. mkd. ¼ S 2 CS BT.
22" Cedar S. 25° E. 28.4 ft. (OBT) Mkd: ¼ S 2 CS BT.

Vernon "Ray" Tracy
Jack Heritage & E. West
February, 1967
C. S. File No. 54/12