

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 23 S. T. S. R. 8 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Jack Heritage & E. West
February and March, 1967
C. S. File No. 54/12

81

$\frac{1}{4}$ Corner to Section 6 only, T23-8W. (West)
Found - Orig. 8", now 12" Hemlock, very badly decayed Stub, N. 45° W.
17.8 ft. Open & find reverse scribe in decayed log on ground.
Orig. 20", now 34" Fir, Alive, S. 1° E. 17.8 ft. (record S. 10° E.)
Shows scar. Do not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R 8 W
Office, 1967 $\frac{1}{4}$ S 6
New BT's: 9" Hemlock N. 74 $\frac{1}{2}$ ° E. 10.8 ft. mkd. $\frac{1}{4}$ S6 CS BT.
14" Hemlock N. 47° E. 19.0 ft. mkd. $\frac{1}{4}$ S6 CS BT.
Note - This corner lies on top of small spur ridge, course N.W.
Also unrecorded 1 $\frac{1}{2}$ " I. Pipe bears N. 71° W. 3.9 ft.

82

Sec. Corner to Sections 14 - 15 - 22 - 23.
Found - Orig. 24", now 48" Fir, Alive, N. 5° E. 15.2 ft., shows scar.
Do not open.
Orig. 24" Fir, now only decayed remains, S. 20° E. 12.5 ft.
Find old axe mark & partially burned face with frag. scribe marks.
Orig. 24" Fir, now badly decayed stump, S. 45° W. 33.0 ft.
Hole in ground where N.W. BT. would have been.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office S 15 | S 14
1967 S 22 | S 23
New BT's: 17" W. Fir S. 50° W. 24.1 ft. mkd. T23S R8W S22 CS BT.
14" D. Fir S. 43 $\frac{1}{2}$ ° E. 24.0 ft. mkd. T23S R8W S23 CS BT.
11" D. Fir N. 41° E. 54.8 ft. mkd. T23S R8W S14 CS BT.
15" W. Fir N. 26° W. 40.2 ft. mkd. T23S R8W S15 CS BT.
Note - Corner lies on gentle S. Slope.

83

$\frac{1}{4}$ Corner to Sections 18 and 19.
Found - Orig. Sandstone 24" x 18" x 12" & mkd. "X $\frac{1}{4}$ ". Tipped out of place.
Orig. 20", now 30" Fir, Alive, S. 5° W. 10.6 ft., shows good
scar. Do not open.
Orig. 24", now 36" Fir, Alive, N. 75° W. 11.2 ft. Open & find
"4S" scribe & reverse.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office $\frac{1}{4}$ S 18
1967 S 19
(Reset Rock alongside)
New BT's: 30" D. Fir S. 32° dE. 22.2 ft. mkd. $\frac{1}{4}$ S19 CS BT.
5" Hemlock N. 75° E. 22.4 ft. mkd. $\frac{1}{4}$ S18 CS BT.
Note - This corner lies 1 ch. W. of ravine, course South.

84

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - Stone, 12 x 8 x 6, Sandstone, at Corner, no markings.
Orig. 14" Fir, now down, S. 73° W. 22.4 ft., scribing "S".
Orig. 48", now 56" D. Fir, N. 53° E. 20.5 ft., scribing "4S"
on bark & good BT face.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office $\frac{1}{4}$ S 4
1967 S 9
New BT's: 6" D. Fir N. 61 $\frac{1}{2}$ ° E. 46.5 ft. mkd. $\frac{1}{4}$ S4 CS BT.
21" D. Fir S. 79° W. 12.4 ft. mkd. $\frac{1}{4}$ S9 CS BT.
Note - Corner lies on steep, south slope, approx. 200 ft. S. of ridge.

85

Sec. Corner to Sections 9 - 10 - 15 - 16.
Found - Orig. 30", now 40" Fir, Alive, N. 25° E. 51.5 ft., shows good scar.
We Rescribe: "T23S R8W S10 CS BT."
Orig. 24", now 36" Fir, Alive, S. 80° E. 15.2 ft., shows good scar.
We Rescribe: "T23S R8W S15 CS BT."
Orig. 12", now 30" Fir, Alive, S. 20° W. 42.9 ft., shows faint scar.
We Rescribe: "T23S R8W S16 CS BT."
Orig. 36", now 42" Fir, Alive, N. 3° W. 42.2 ft., Alive, shows
bark scribe. We rescribe: "T23S R8W S9 CS BT."
Note - We used Orig. BT's. because no small trees in area.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office S 9 | S 10
1967 S 16 | S 15
Note - Cor. lies on very steep, S.E. slope 200' W. of bottom of Ravine.