Douglas County Surveyor's Record of Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

86

¼ Corner to Sections 22 and 23.
Found - Orig. 50", now 58" Fir, Alive, N. 36° W. 22.4 ft., shows scars, we open & find good "S" scribe & reverse & axe notch. No trace of other Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T 23 S R 8 W ¼ S 22 / S 23
New BT's: 6" D. Fir N. 31° W. 8.3 ft. mkd. ¼ S22 CS BT.
7" D. Fir S. 74° W. 5.4 ft. mkd. ¼ S22 CS BT.
7" D. Fir. N. 24° E. 16.5 ft. mkd. ¼ S23 CS BT.
7" D.Fir S. 50° E. 13.3 ft. mkd. ¼ S23 CS BT.
Note - This corner lies on SE. slope approx. 165 ft. N. of snall creek. This area is mostly reproduction & a few large burned trees and snags.

- - - - - - -

87

¼ Corner to Sections 14 and 23.
Found - Orig. 12", now 42" Fir, Alive, N. 56° E. 9.2 ft.(Record N.64°E.) shows lower scar, upper scar chopped open 16" deep to burlwood.
Orig. 8", now 13" Laurel, S. 72° E. 32.3 ft., lower blaze previously opened & shows "BT" scribe. Open upper blaze and find "¼S" scribe and reverse.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 T 23 S R 8 W ¼ S 14 / S 23
New BT's: 12" D.Fir N. 41½° E. 25.1 ft. mkd. ¼ S 14 CS BT.
11" D.Fir S. 26° Ed. 42.2 ft. mkd. ¼ S23 CS BT.
Note - This corner lies on westerly slope approx. 27.5 ft. E. of small creek.

- - - - - - -

88

¼ Corner to Sections 13 and 24.
Found - No trace of corner tree.
Orig. 18", now 30" Fir, alive, N. 16° W. 9.2 ft., prev. opened & face burned. No scribe found.
Orig. 20", now 36" Fir, now stump, S. 64° W. 33.0 ft. Open & find "¼S" scribe & reverse.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 T 23 S R 8 W ¼ S 13 / S 24
New sBT's: 27" D.Fir N. 30° E. 36.4 ft. mkd. ¼ S13 CS BT.
12" D.Fir S. 27° W. 77.3 ft. mkd. ¼ S24 CS BT.
Note - This corner lies 15' West of top of spur, sloping South.

FD. OK 2/81 L. ROBERTS M 86-64

Vernon "Ray" Tracy
Jack Heritage and E. West
February and March, 1967
C. S. File No. 54/12

- - - - - - -

89

¼ Corner to Sections 3 ~~and 2~~ ONLY. 1/11/83 - SEE M90-29 FOR SUBD. OF SEC. 6 NEW CORNERS BY L. ROBERTS L.S. 1629 OCT-DEC. 1982.
Found - Orig. Corner Stone mkd: "¼" on W. face, fell apart on removal.
Orig. 50", now 55" Fir S. 64° E. 61.4 ft. Alive, shows "¼S" bark scribe in fair cond. Top of tree gone, approx. 100' high.
Orig.12", now 32" Cedar, Alive, S. 2° W. 38.3 ft. No scar. Rescribe: "¼ S 3 CS BT".
Set - Brass Cap in place of Rock Mkd: County Surveyor's Office, 1967 T 23 S R 8 W. ¼ S 3 | S 2
New BT: 10" D. Fir S. 28° E. 25.3 ft. mkd. ¼ S 2 CS BT.
Note - This corner lies on steep, south slope 20 ft. N. of small creek, course S. 70° E. Put pieces of Cor. Stone in Brass Cap hole.

RE-RENEWED. SEE CORNER NO. #128

- - - - - - -

90

Section Corner to Sections 10 - 11 - 14 - 15.
Found - Orig.40", now 52" Fir, Alive, N. 5° E. 29.7 ft., shows good scars. Do not open.
Orig. 5",now 15" W.Fir, Down, N. 24° W. 19.8 ft. find "R8W" & frag. scribe on rotting face.
Orig. BT. to SW gone. - S.E. BT. lying face down & on corner point.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 T 23 S R 8 W S 10 | S 11 / S 15 | S 14
New BT's: 8" D.Fir N. 66° W. 40.8 ft. mkd. T23S R8W S10 CS BT.
14" Chinq. S. 73° W. 38.4 ft. mkd. T23S R8W S15 CS BT(Scrb. 4' above ground because of log)
12" Chinq. S. 16° E. 11.1 ft. mkd. T23S R8W S14 CS BT.
Note - Brass Cap lies on west slope on S. side of 24" Log.

- - - - - - -