

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 97881

Vernon "Ray" Tracy
Jack Heritage & E. West
March, 1967
C. S. File No. 54/12

1/4 Corner to Sections 14 and 15. *FD. OK - 4/23/73*
Found - Orig. 40", now 50" Fir, Alive, S. 3° E. 58.1 ft., prev. opened & shows "4S" scribe & axe notch.
No trace of Orig. N.W. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office, 1967 1/4 S 15 | S 14
New BT's: 20" D. Fir N. 51° E. 7.6 ft. mkd. 1/4 S14 CS BT.
16" D. Fir N. 86° W. 26.8 ft. mkd. 1/4 S15 CSBT.
Note - This corner lies 40 ft. N. of top ridge, course E. & W.
Best route to corner is by jeep trail, if dry, on top of ridge, line tag on North side road.

91

1/4 Corner to Sections 10 and 15.
Found - Orig. 24", now 48" Cedar, Alive, badly injured on W. side, S. 5° W. 16.5 ft., "1/4" scribe visible on badly decayed blaze.
Orig. 40", now 54" Fir, Alive, poor condition, N. 5° W. 28.4 ft., shows "1/4 S" bark scribe in poor condition & BT. scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office 1967 1/4 S 10 | S 15
New BT's: 12" Hemlock N. 61° W. 27.7 ft. mkd. 1/4 S10 CS BT.
14" Hemlock S. 49° W. 15.2 ft. mkd. 1/4 S15 CS BT.
Note - Corner lies on moderate, changing to steep, N.E. slope, approximately 100 ft. W. of creek, course N.E.

92

1/4 Corner to Sections 4 and 3.
Found:- Orig. 8", now 26" Fir, Alive, S. 23° W. 19.8 ft. Open & find good "4" scribe & reverse.
No trace of other Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 8 W
Office, 1967 1/4 S 4 | S 3
New BT's: 8" Hemlock S. 26° E. 6.5 ft. mkd. 1/4 S 3 CS BT.
8" Hemlock N. 78° W. 16.1 ft. mkd. 1/4 S 4 CS BT.
Note - This corner lies on top of small spur, sloping W. in dense undercover of D. Fir, W. Fir, & Hemlock.

93

1/4 Corner to Section 9 and 10.
Found - Orig. 50", now 58" Fir, N. 30° E. 7.3 ft. Alive, bark scribe "1/4 BT" in fair condition.
Orig. 36", now 46" Fir S. 72° W. 21.1 ft. Alive, bark scribe, "1/4 BT" in fair condition.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R8W
Office, 1967 1/4 S 9 | S 10
New BT's: 9" Hemlock N. 75° W. 21.6 ft. mkd. 1/4 S 9 CSBT.
7" Hemlock N. 64° E. 34.3 ft. mkd. 1/4 S 10 CS BT.
Note - This corner lies on S. slope, approx. 50 ft. N. of small creek, course E. Line north of corner to top of ridge is bench-like moderate in ascent.

94

1/4 Corner to Sections 3 and 10.
Found - Org. 48", now 58" fir, S. 70° W. 23.1 ft., now down & slid downhill 30 ft. No scar showing, probably face down.
Orig. 10", now 30" Fir N. 32° W. 21.1 ft., Alive, we chop open and find "B" scribe & reverse.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R8W
Office 1967 1/4 S 3 | S 10
New BT's: 7" Hemlock S. 48° W. 35.1 ft. mkd. 1/4 S10 CS BT.
8" Chinquapin N. 59° E. 14.6 ft. mkd. 1/4 S 3 CS BT.
Note - This corner lies on steep, southerly slope approx. 10 ch. East of top of main ridge, course NE - SW.

95

May 8, 1967

May 8, 1967