

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97881

96

Section Corner to Sections 3 - 4 - 9 - 10.

Found - Orig. 40", now 48" Fir, Alive, N. 58° E. 46.2 ft., shows bark scribe.
Orig. 24", now 28" Fir, Alive, S. 16° E. 7.9 ft., shows bark scribe.
Orig. 50", now 54" Fir, Alive, S. 35° W. 26.4 ft., shows scribe & scar.
Orig. 10" (?), now 48" Fir, Alive, N. 56° W. 11.9 ft., shows bark scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T 23 S R 8 W
S 4 S 3
S 9 S 10

V. Tracy
&
Crew
C.S.
File
No.
54/12

Rescribed Orig. BT's: Orig. 48" Fir N. 56° W. 11.9 ft. remarked:
"T23S R8W S4 CS BT" in bark.

Orig. 28" Fir S. 16° E. 7.9 ft. remarked:
"T23S R8W S10 CS BT" in abark.

New BT's: 7" D. Fir S. 15° W. 26.8 ft. mkd. T23S R8W S9 CS BT.
10" D. Fir N. 17° E. 19.7 ft. mkd. T23S R8W S3 CS BT.

Note - This corner lies on top of spur sloping N.W.

June 20, 1967 -
MICROFILM TO HERE 10/67

97

1/4 Corner to Section 29 and 30.

Found - Orig. 12", now 30" Hemlock, Alive, S. 66 1/2° W. 18.5 ft., Opened
this tree in spring of this year & did not find any scribe
& did not find any scribe. Did not feel this was Orig. BT.

However, later this year, Coos Bay B. L. M. found fragmentary scribe
and axe notch. We now verify this to be Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T 23 S R 8 W
1/4 S 30 S 29

New BT's: 26" D. Fir N. 87° W. 21.6 ft. mkd. 1/4 S30 CS BT.
20" Hemlock S. 31° E. 30.8 ft. mkd. 1/4 S29 CS BT.

Note - This corner lies on very steep easterly slope.
No trace of other original BT.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
October, 1967
C. S. File No. 54/12

98

1/4 Corner to Sections 19 and 30.

Found - Orig. Corner Stone in place & mkd. "X & 1/4".

Orig. 20", now 28" Hemlock N. 69° E. 12.5 ft., down with
"4" scribe visible on open blaze.

Orig. 14", now 26" Cedar Snag, S. 48° E. 24.4 ft., shows scar.
Do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T 23 S R 8 W
1/4 S 19 S 30

(reset rock alongside)

New BT's: 7" Hemlock S. 9° W. 10.4 ft. mkd. 1/4 S30 CS BT.
16" Cedar N. 2° W. 49.5 ft. mkd. 1/4 S19 CS BT.

Note - This corner lies on N. E. slope of spur, sloping N.

10/24/67

SEPT-68

Closing Corner for Secs. 3 and 4, T24S., R. 8W.

The Orig. field notes describe the BT's for the corner as

3 Hemlocks. The BT's. found at this corner are all D. Firs, and
the bearings & distances do not match up in any manner. The Cadastral
Surveyor in a letter to us dated 2/19/70 suggested that the corner be
re-established in the following manner. "Select a common point faced
by the blazes on all of the BT's. If the trees were blazed properly
at the time of marking, the point so determined should fall close to
a point 2.06 chs. west of the cor. of Secs. 33 & 34, south boundary
of T. 23S., R. 8W."

Set - An Iron Pipe with brass cap at this point which is 136.7 ft.
west of the Brass Cap for Secs. 33 & 34, T23S., R. 8W.

The Old BT's. are now: 36" D. Fir N. 4° W. 30.5 ft.

36" D. Fir N. 57° E. 30.8 ft.

20" D. Fir S. 78° E. 36.2 ft.

10" D. Fir N. 2° W. 15.0 ft.

9" D. Fir S. 77° E. 11.0 ft.

12" D. Fir S. 46° W. 17.9 ft.

RE-RENEWED CORNER NO. #122

Howard W. Johnstone
For Roseburg Lumber
March 30, 1970
C. S. File No. 55/144

99

MARCH 71