

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97401

34

1/4 Corner common to Sections 26 and 35.

Found - GLO Record, Sandstone, found badly decomposed in upright position--no etchings on stone remaining.

6" chinquapin S.3°E. 18 lks., gone.

4" Fir N. 64° E. 19 lks., now 12" fir windfall--chopped open--scribe visible.

Set - 4' x 3/4" pipe and square post, re-referenced with "W" nail & Weyerhaeuser tags: 14" hem N. 8° E. 23.3 ft.

68" fir S. 52° W. 28.2 ft.

(Note - ("W" nail drive into notch cut low on a tree, with dist. & bearing to "W" nail stamped on Weyerhaeuser tag. Tag nailed high on same tree.)

Donal L. Peel
For Weyerhaeuser
Co.
March, 1967
U. S. File
No. 55/30

MICROFILM TO HERE

10/67

35

1/4 Corner to Sections 13 and 24.

Found - Orig. 36", now 46" Fir, badly decayed snag, N.65°W. 17.2 ft., no scribe found.

Orig. 18", now 18" Cedar, turned out, S.62 1/2°W. 9.2 ft., shows "1/4 S BT" scribe on burned face.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W
Office S 13
1967 S 24

New BT's: 15" Hemlock N. 23° W. 13.1 ft. mkd. 1/4 S13 CS BT.

New BT's: 12" Hemlock S. 28° W. 17.4 ft. mkd. 1/4 S24 CS BT.

Find also 1/2" I. Pipe with steel sign 7"x11 1/2" stamped "T23S R9W N 1/4 Sec. 24", set between 13 & 24 established 6-6-66 George C. Barton & Crystal M. Barton, unrecorded 1.0 ft. West of true corner.

10/24/67

V. "Ray"
Tracy &
Crew
10/24/67
C.S. File
No. 54/60

36

Sec. Cor. to Secs. 32 & 33, T22-9W. & Secs. 4 & 5, T23-9W.

Found - Orig. 40", now 36" Fir, burned stump, N.65°W. 9.2 ft., fragmentary scribe marks on old axe blaze.

Orig. 36", now 26" Fir burned stump, S.30°W. 49.5 ft., possible scribe on burned blaze.

No trace other original BT's., area apparently burned before BT's. healed over.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S S 32 | S 33
Office, 1967 R9W T23S S 5 | S 4

New BT's: 14" D. Fir N. 53°W. 11.6 ft. mkd. T22S R9W S32 CS BT.

12" D. Fir N. 16° E. 9.2ft. mkd. T22S R9W S33 CS BT.

7" D. Fir S. 72° E. 6.0 ft. mkd. T23S R9W S 4 CS BT.

11" D. Fir S. 16° W. 13.9 ft. mkd. T23S R9W S 5 CS BT.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
December, 1967
C. S. File No. 54/60

37

Sec. Cor. to Secs. 34 & 35, T22-9W. & Sec. 3 & 2, T23-9W.

Found - 1 1/2" I. Pipe & Iron Cap at corner, unrecorded.

Orig. 60", now 66" Fir, alive, N.60°E. 46.9 ft., frag. bark scribe.

Orig. 30", now 32" Fir, decayed stump, S.50°W. 29.7 ft. (not 9.9 ft.) no scribe.

Orig. 14", now 28" Fir Stump, S.20°E. 65.3 ft., opened & find "B".

No trace original bearing tree to northwest.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S 34 | S 35
Office, 1967 T23S S 3 | S 2

(Deposit old corner pipe alongside)

New BT's: 7" D. Fir N. 49° E. 30.0 ft. mkd. T22S R9W S35 CS BT.

14" D. Fir N. 55° W. 50.1 ft. mkd. T22S R9W S34 CS BT.

15" Hemlock S.79°W. 43.6 ft. mkd. T23S R9W S 3 CS BT.

17" D. Fir S. 40° E. 39.9 ft. mkd. T23S R9W S 2 CS BT.

F.D. B.C.
W. H. H. H.
R. H. H. H.
197.6

38

Sec. Cor. to Segs. 33 & 34, T22-9W. & Secs. 4 & 3, T23-9W.

Found - Orig. 24", now 42" Fir, alive, N.50°E. 23.8 ft. (slope), bark scribing visible in poor condition.

Orig. 30", now 40" Fir, alive, S.30°W. 59.4 ft., bark scribe vis.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S S 33 | S 34
Office, 1967 T23S R9W S 4 | S 3

New BT's: 12" Hemlock N. 2° W. 32.2 ft. mkd. T22S R9W S33 CS BT.

8" Maple N. 8° E. 18.5 ft. mkd. T22S R9W S 34 CS BT.

8" Hemlock S.16°W. 82.7 ft. mkd. T23S R9W S 4 CS BT.

8" Hemlock S.28°E. 74.2 ft. mkd. T23S R9W S 3 CS BT.

Note This corner lies on very steep, westerly slope approx. 175 ft. west of ridge top.

RE-RENEWED

SEE FILE NO. #90