

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

44

$\frac{1}{4}$ Corner common to Sec. 31, T22-9W. & Sec. 6, T23-9W.
Found - Orig. Post, now missing, from which a:
20" Fir bears N. 18 lks.; now 26", face opened, knife
scribes 4S visible at correct age.
24" Fir bears S. 23 lks.; now 28" snag, knife scribe 1/-S BT
visible at correct age.
Creek, course North, bears East 325 lks.;, now in place.
Restored: Set $1\frac{1}{2}$ "x36" gal.iron pipe with 3" bronze cap mkd:
"Ore.St.Bd. of Forestry $\frac{1}{4}$ S31 S6 1967 RS359", 30 in.
in ground, and from which a:
20"Hemlock bears S.69 $\frac{1}{2}$ °W. 42.2 ft. to face; scribed $\frac{1}{4}$ S6 BT RS359.
Set 4"x4"x72" white painted cedar post 1.2 ft. S. of corner pipe.

45

$\frac{1}{4}$ Corner to Sections 5 and 6.
Original - Post, now missing, from which a:
48" Fir bears N.65°E. 46 lks.; now 48" Fir, orig. bark
scribes $\frac{1}{4}$ S BT visible.
48" Fir bears S. 80° W. 36 lks.; now 60" windfall.
Restored - Set $1\frac{1}{2}$ "x36" galv.iron pipewith 3" br. cap. mkd."Ore.St.Bd.
of Forestry $\frac{1}{4}$ S6 S5 1967 RS359" 34" in ground, and
from which a:
14" Hemlock bears N.16°W. 18.0 ft., to face; scribed $\frac{1}{4}$ S6 BT.
13" Hemlock bears S. 86°E. 26.0 ft.,to face; scribed $\frac{1}{4}$ S5 BT.
Set 4"x4"x72" white painted cedar post 1.1 ft. S. of corner pipe.
Ore.St.Forestry Dept. metal location poster on the 14" BT.

46

Section Corner common to Sections 5 and 6.
Original - Post, now missing, found original lines blazes N) from which:
14"Hemlock bears N.87°E. 58 lks.; now a rotted windfall.
24" Hemlock bears S.65°E. 80 lks.; now a rotted windfall.
48" Fir bears S.82°W. 138 lks.; now 72" with face overgrown.
48" Hemlock bears N.72°W. 84 lks.; now a 48" rotted stump, remains
of orig. axework around face.
Found 32" Hemlock bears S.77 $\frac{1}{2}$ °W. 33.9 ft. with scribes T23S,R9W S5 BT
facing SW (68 years overgrowth.)
Stream, 1 lk., course N.10°W., bears N.orth 523 lks.; now in place.
Survey by Oscar Thiel(1899)reported destroying SE and SW BTs.
Stream, 3 lks. course N.60°W., East 425 lks.; now in place.
North $\frac{1}{4}$ cor. 7 bears N.89°45'W. 725 lks.; now in place.
County Road bears N.89° 45'W. 210 lks.; remains now in place.
Restored - Set $1\frac{1}{2}$ "x36" galv. iron pipe with 3" br. cap mkd. "Ore.St.
Bd. of Forestry T23S R9W S6 S5 1967 RS359", 34" in ground,
in mound of rock, and from which a:
20" Hemlock bears N.67°E. 41.6 ft. to face; scribed T23SR9WS5 BT.
24" Hemlock bears N.54°W. 45.4 ft. to face; scribed T23SR9WS6 BT
RS 359.
Set -4"x4"x72" white painted Cedar post 1 ft. NW. of corner pipe.
Ore.St.Forestry Dept. metal location poster on the 20" Hemlock BT.

47

$\frac{1}{4}$ corner for Section 7. (N. Side)
Original - Post, now missing, from which a:
8" Hemlock bears S.63°E. 35 lks.; now a 22" windfall, face
exposed, scribes 4 S 7 visible.
72" Fir bears N.70°W. 49 lks.; now a 96" school marm, face
closed, axe work visible in bark.
Restored: Set $1\frac{1}{2}$ "x36" galv. iron pipe with 3" br. cap mkd."Ore.St.Bd.
of Forestry $\frac{1}{4}$ S7 1967 RS359", 34" in ground, and from which a:
12" Hemlock bears S.29°W. 23.5 ft. to face; scribed $\frac{1}{4}$ S7 BT
RS359.
Set 4"x4"x72" white painted cedar post 1 ft. NW of corner pipe.
Ore.St.Forestry Dept. metal location poster on the 96" Orig. BT.

Ore.St. Board of Forestry
Arnold G. Gibson
October & November, 1967
C. S. File No. 55/68