

Douglas County Surveyor's Record of  
Government Corners Renewed

T.23 T. S. R.9 R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97401

Robert B. Ward Jr.  
L.S. #1091  
For: Champion Int.  
May 1991  
M 113 - 34 A & B

Center 1/4 for section 30.

Set - 2 1/2" dia. brass cap corner monument, marked C1/4 - S30

99

BT's- 11" fir bears N.49°W., 8.3 ft. (scribed "C1/4 S30 BT")  
13" fir bears N.21°E., 10.6 ft. (scribed "C1/4 S30 BT")

LS 1091  
1991 #102

7/91

Section Corner to Sections 25 and 36 only.

100

Found - A 2 1/2" D.C.S.O. Brass Cap (1967, properly marked) on 1 1/2" O.D. iron pipe, protruding 11" above ground. See Renewal No. 22.

Accessories Found -

28" now rotted D. Fir stump of indeterminable size, no blazes or scribing found, bears S.82°W., 12.5 ft. (rec. S.89°W., 12.5' orig. BT)  
20" now 36" dia. D. Fir with a fully healed double blaze bears N.80°W., 33.0 ft. (agrees with rec.) original BT.  
24" now 26" dia. 10' tall D. Fir snag with a fully healed double blaze, bears S.75°W., 17.4 ft. (agrees with rec. Ren. 22)

New Accessories -

12" dia Hemlock double blazed and scribed "T23S R9W S25 CS BT" bears N.30°W., 22.8 ft.  
5" dia. D. Fir double blazed and scribed "X BT" bears N.79°E., 23.0'

Note - Cor. lies on very steep N.E. slope approx. 540 ft. south of creek.

8/6/92

1/4 Cor. Secs. 12 & 13

Found - A 1969 BLM Brass Cap, from which:

26" Hemlock w/ healed face bears N.51°W 36.9' (rec. 58 1/2 lks)  
57" DF with healed face bears N.50°E., 30.5' (rec. 47 lks.).  
26" Hemlock w/visible scribes bears S.75°E., 30.5' (rec. S.78°E., 45 1/2 lks.).

New BT- 13" Hemlock, bears N.69°E., 21.4', scribed "1/4 S12 BT"

5/94

FDOK  
H.S. Smalley  
10/97  
M124-6A  
101

Clyde Mulkins, LS 2008  
For; IP Timberlands  
Operating Co  
4/94  
M 118-71

Center 1/4 for Section 30 Condition report only

102

Found - 2 1/2" brass cap See renewal #99

11" Fir, bears N.49°W., 8.3 ft.  
13" Fir, bears N.21°E., 10.6 ft.  
11" Fir, bears S.8°E., 27.8 ft.  
9" Fir, bears S.24°W., 24.2 ft.

Note - All BT's blazed and scribed "C 1/4 S30 BT" in M113-34 A&B.  
- Corner lies on a southeast slope @ cutting corner.

Wayne Donovan  
June 27, 1995  
C.S. 63/161-29

1/4 Corner for Sections 30 & 29 Condition report only

103

Found - 2" brass cap by County Surveyor's Office See renewal #64

44" Fir stump, bears N.26°W., 55.3 ft. (w/BT tag) not of record  
7" Fir snag, bears N.3 3/4°E., 18.2 ft. (w/BT tag)  
30" Fir stump, bears N.27 1/2°E., 13.0 ft. (visible scribing)  
36" Fir stump, bears N.85 3/4°E., 41.2 ft. (w/BT tag) not of rec.  
18" Fir, bears S.49 3/4°W., 53.9 ft. (w/BT tag)  
10" Fir, bears S.80°E., 26.7 ft. (blazed and scribed "1/4 S29 BT")

Note - All BT's from M113-34 A&B.  
- Corner lies on a flat area southeast of cat road.

Wayne Donovan  
June 27, 1995  
C.S. 63/161-30

Section 23 & 26 1/4 Cor.

104

Mon. Fd.- 5/8" I.R. with yellow plastic cap mkd. "PE 6245" bent, protrudes 17" above ground.

Bent fence post protrudes 30" above ground. Has a BLM tag attached date 1973.

Accessories Fd. -

6" now 35" D.Fir, with a previously opened blaze, scribing visible "4", bears S.5°E., 23.8'.  
30" now 28" dia. 4' high brokend and rotted D.Fir stump, bears N.38°E., 13.1' to center.  
37" now 37" dia. 5' high D.Fir stump, wiht a partially haled single blaze, scribing visible "1/4", bears N.16°W., 16.2'.

(Cont. Next Page)

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
10/3/95  
C.S. 64/64