

Douglas County Surveyor's Record of  
Government Corners Renewed

23 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

James W. Byron, Deputy County Surveyor  
M. Godfrey  
S. Bilow  
August, 1957  
C. S. File No. 49/60

Meander Corner to Sections 2 & 11. On West Side of Lake. 27  
Found - 1/2" Iron Pipe at Cor. & I believe both BT's., each checks bearing, distance, size, age, & specie as recorded - 1906 Survey. The 10" now 16" Alder N.60°W. 2.6 ft., alive but well rotted. Face(open), I find no scribe mks. The 12" now 24" Maple S.69°W. 33.0 ft. I open & find rotted face but do find what I believe to be a 1 1/2" Section of curved(negative) scribe mark.  
Set Brass Cap & Rock Mound at Side of 1/2" Iron Pipe marked: M.C. II 2  
T23S, R10W, County Surveyor's Office, 1957.  
New BT's: 14" R. Fir bears N.51°W. 62.8 ft. scribed M.C. S2 T23S R10W CS BT  
12" Hemlock " S.51°W. 63.0 ft. scribed M.C.S11 T23S R10W CS BT

Section Corner to Secs. 24 & 25, T23S,R10W, & Secs.19 & 30, T23S,R9W. 28  
Found - 1" Iron Pipe at Corner. - REN. No. 1 R10W R9W  
Set Brass Cap at Corner mkd: (Cap set at Side 1" I.P.  $\frac{24}{25} | \frac{19}{30}$  T23S Fnd. OK. by L. SMITH 9-29-81 M 89-40  
County Surveyor's Office, 1957.  
New BT's: 16" R. Fir bears S.64 1/2°W. 42.6 ft. scribed T23S R10W S25 CS BT.  
4" R. Fir bears N.89°W. 38.4 ft. scribed S24 CS BT.  
7" R. Fir bears S.68 1/2°E. 25.0 ft. scribed S30 CS BT. FND. OK 5/9/1 M115-34 AB  
No Trees near in N. E. Quad.  
Note - On steep South slope 63.0 ft. North of existing Road.  
Statement by H.A. Carlson in file.

1/4 Section Corner to Sections 24 & 25. 29  
Found - 1" Iron Rod at Corner, check bearing & dist. to Frear's N.58 3/4°W. 36.9 ft. BT., which shows visible scribe marks. - REN. No. 2  
Frear's N.32°E. 61.0 ft. BT. is down & in Creek, scribe marks visible.  
Set Brass Cap at Corner marked: 1/4 S  $\frac{24}{25}$  T23S, R10W, County Surveyor's Office, 1957.  
New BT's: 28" Myrtle N.58 3/4°W. 37.8 ft. (to Center of Tree) scribed 92  
1/4 S 24 CS BT.  
27" Myrtle N.2°W. 58.0 ft. scribed 1/4 S 24 CS BT.

Reference 1/4 Section Corner to Sections 12 & 13. 30  
Found - Both BT's. as renewed by Frear, 1930. REN. #3  
Also found his 1/2" I.R. 10" Under Road Surface. 57  
See Reference Points & Hubs marked on sketch in file.

Closing Corner Common to Sections 2 & 3 (North Side) 31  
Original - Post (now missing) from which a:  
20" Hemlock bears S.58°E. 64 lks.; now missing, pieces of broken up stump, with back cast of scribe 2 visible, found nearby.  
24" Alder bears S.86°W. 23 lks.; now missing, possible orig. log nearby, no markings found.  
Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R10W S35 T23S R10W S2 S3 CC 1958 RS 359," 33 in. in ground, in mound of stone, & from which a:  
24" Hemlk stp. bears S.47°W. 92.5 ft.; scribed T23S R10W S3 BT.  
18" Hemlk bears N.38 1/2°W. 58.5 ft.; scribed RS 359.  
Set 4x 4x 72" white painted Cedar post 1.0' SE of pipe.  
Oregon State Board of Forestry metal location poster on 18" Hemlock BT.  
South 1/4 Cor. of Sec. 35 bears N.88° 50'E. 88.3 ft. (prop. distance)  
Center of road bears S.39°E. 79.0'.

Witness Corner for Center 1/4 Cor. for Sec. 2 (on West side of Loon Lake) 32  
Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY WC C 1/4 S2 579.3 ft. 1958 RS 359," 33" in ground, in mound of stone, and from which a:  
42" Fir bears N.50 1/2°W. 137.3 ft.; scribed X BT.  
18" Myrtle (clump) bears S.15°E. 57.5 ft.; scribed X BT RS 359.  
A 27' x 16' x 7 1/2' high Rock bears S.12 1/2°E. 67.3 ft.  
Set 4x 4x 72" white painted Cedar post 1.5 ft. SW. of pipe.  
Oregon State Board of Forestry metal location poster on 18" Myrtle BT.  
Also poster on 4x 4x 72" white painted Cedar post N.89°44'W 29.0 ft. on (over)

OREGON STATE BOARD OF FORESTRY  
Arnold G. Gibson  
Present & Witnessed by E. Driver  
D. Timmons - R. Witham  
F. Peachee  
April 4, 1958  
C. S. File No. 42/353 - Map File M 10 - 19.