

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 10 R. W. W. M.

44

Arnold G. Gibson
Elbert Driver, Transitman
ORE. ST. BD. OF FORESTRY
August 21, 1959
C. S. File No. 42/422

$\frac{1}{2}$ Corner common to Sections 21 and 22.
Original: Post (found, down and rotted) from which a:
16" Fir bears N.8°W. 23 lks.; now 30", face covered.
16" Fir bears S.78°E. 10lks.; now 17" x 58" high
Stub, portion of face exposed, scribed 22 visible.
Restored: Set $1\frac{1}{2}$ " x 36" galvanized Iron Pipe with 3" Bronze Cap
mkd "OREGON STATE BOARD OF FORESTRY $\frac{1}{2}$ S21 S22 1959 RS359",
33" in ground, & from which a:
31" Fir bears S.56°W. 10.9 ft.; scribed RS359.
26" Fir bears S.86°E. 27.7 ft.; scribed $\frac{1}{2}$ S22 BT.
Oregon State Board of Forestry metal location poster on
original 16" Fir BT.

45

Arnold G. Gibson
George Shore, Transitman
Ore. St. Bd. of Forestry
January 15, 1959
Filed Jan. 28, 1960
C. S. File No. 42/422

$\frac{1}{2}$ Corner for Section 14, (West Side).
Orig. - Post, now missing from which a:
8" Fir bears S.5°E. 84 lks.; now missing.
8" Fir bears S.2°W. 109 lks.; now missing.
Retracement by Levi C. Walker, June, 1905
Post, now missing, from which a:
12" Fir bears S.77°E. 23 lks.; now 31", face exposed
by unknown party, face rotted, orig. axe work visible.
10" Fir bears N.80°W. 44 lks.; now 27" x 6' stub, face
exposed by unknown party, orig. axe work visible on small
portion of face on down log, most of face destroyed
when tree blew down.
Summit of divide, South 37 lks.; now in place.
Restored: Set $1\frac{1}{2}$ " x 36" gal. I. P. with 3" bronze cap mkd: "OREGON
STATE BOARD OF FORESTRY $\frac{1}{2}$ S14 1959 RS359", 33" in gr,
in mound of stone, and from which a:
30" Fir bears S.60°E. 36.9 ft.; scribed $\frac{1}{2}$ S14 BT #359.
20" Fir bears N.57 $\frac{1}{2}$ °E. 50.1 ft. scribed $\frac{1}{2}$ BT.
Oregon St. Bd. of Forestry metal location poster on 16" Fir S.88°W 40.2 ft.
Set 4" x 4" x 72" white painted Cedar post 1.5 ft. NW of pipe.

46

Arnold G. Gibson
Geo. E. Shore, Jr., Transitman
Dated April 27, 1960
C. S. File No. 42/422

Closing Section Corner common to Sections 33 and 34. - S. Bary.
Orig. - By W. H. Byars. See Resurvey below.
Resurvey by Levi Walker in 1905.
Hemlock Post, now missing, from which a:
30" Fir bears N.6°E. 29 lks.; now 30" windfall scribed S34
T23 RLOW on exposed face.
16" Fir bears N.73°W. 66lks.; now 18" scribed 33 BT
on exposed face.
Restoration by Elliott Survey of 1936 - ~~Ben. #15~~
4" x 5" Hemlock Post, found, not in place, from which a:
24" Fir bears N.18°W. 15 ft., orig. 30" BT.
18" Fir bears S.62°W. 82 ft.; now 24", bearing S.76°W. 24.2 ft.,
scribed 33 in exposed face.
Restored: Set $1\frac{1}{2}$ " x 36" gal. I. P. with 3" br. cap mkd: "Ore. St. Bd. of
Forestry CC T23S RLOW S33 S34 S3 T24S RLOW 1960 RS359",
33" in gr., in mound of stone, and from which a:
48" Fir bears N.38°E. 29.6 ft.; scribed CC T23S RLOW S34 RS359 BT.
32" Fir bears N.18 $\frac{1}{2}$ °W. 28.9 ft.; " CC S33 T23S RLOW BT.
Or. St. Bd. of Forestry metal location poster on 18" Fir BT.
Set 4" x 4" x 6' white painted Cedar Post 1.5' South of pipe.

47

James W. Byren
Milo Gedfrey
S. Blaw
March 1958
C. S. 49/90

M. C. Sections 11 and 12.
Found - Laurel Tree, new 20", growing out of old Laurel Stump.
Dead Fir Snag, new 33", bark scribing "S 12 B", appears
about 20 yrs. old. Old scar below bark scribing facing
corner - N.20°E. 15.2 ft. from Laurel. 63
Tree to N.W. (N.30°W. 11.9 ft.) uprooted & down, nearly all in
Lake with "S" bark scribed on it.
36" Fir N.40°W. 17.7 ft. with bark scribing "MC S12 T23S RLOW BT",
plainly visible, scribing about 20 yrs. old.
Blaze & Scribe Laurel Tree "MC S 11/12 CS" for corner. Rescribe Fir
Snag to N.E. "MC S12 CS BT" in bark below old scar. No live
trees near to East of Meander Corner.