

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 10 R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byren, Deputy
Mile Gedfrey
S. Bilow
March 1958
C.S. File No. 49/90

48

Meander Corner to Sections 11 and 12.
Found - Fir Tree, now 32", S.19°W. 39.0 ft. This tree has been
chopped open exposing face and scribe marks "S11 T23 R10".
Ring cound shows this tree to have been scribed approx. 20 yrs. ago.
Fir Tree, now 16", N.78°E. 28.5 ft., showing good scar. Did
not chop this tree open. *Ren. #24*
This corner falls in read fill in slide area.
At Corner Set Fir Post 4" x 4" x 10" scribed "MC S11" on West Side,
"MC S12" on East Side and "CS" on South Side.

64

May 17, 1960
C.S. 42/422

49

1/4 Corner common to Sections 33 and 34.
Orig: Post (now missing - found hole where rotted out) from which a:
24" Hemlock bears S.69°E. 39 lks.; now 32", face overgrown.
36" Fir bears N.74°W. 51 lks.; now 42", scribes BT visible.
Restored: Set 1 1/2" x 36" gal. I. P. with 3" Bronze Cap Mkd. asusual:
Orig. 24" Hemlock bears S.69°E. 25.7 ft.; scribed RS359 BT (near bottom)
Orig. 36" Fir bears N.74°W. 33.7 ft.; scribed BT (near bottom)
Ore. St. Bd. of Forestry metal location poster on Orig. 24" Hemlk BT. *Ren. #16*
Deug. Co. Forest App. tag on Orig. 24" Hemlock BT.
Set 4" x 4" x 6' white painted Cedar post N.45°E., 1.5 ft. from pipe.

Arnold G. Gibson, 359
Dept. of Forestry
C. S. File No. 42/422

June 10, 1960
C.S. 42/422

50

Angle Point corner common to Sec. 34, T23S R10W. & Sec. 3, T24S R10W.
Original - Maple post, now missing, from which a:
24" Fir bears N.78°E. 10 lks.; now 34", scribes S34 T23S ROW visibl
30" Fir bears S.65°E. 7 lks.; now 36", scribes S 3 visible.
16" Fir bears S.74°W. 20 lks.; now rotted 2 ft. high stub.
24" Fir bears N.15°W. 28 lks.; now 30" rotted stub, axe work remng.
Note - Surveys in 1896 and 1905 reported destroying corner and defacing
the BT's. Apparently the portion of the face covered by
overgrowth was not chopped out then.
Restored - Set 1 1/2" x 36" galv. iron pipe with 3" br. cap mkd. "Ore.St.
Bd. of Forestry T23S R10W AP S34 S3 T24S 1960 RS 359",
32" in ground, and from which a:
30" Fir bears S.85°W. 26.2 ft.; scribed RS359.
Oregon State Board of Forestry metal location poster on orig. 30" Fir BT.
Set 4x4x72" Wh. painted Cedar Post 1.5 ft. NE of pipe.

Aug. 23,
1960
C.S. 42/422
49/80

51

Closing Section Corner common to Sections 33 and 34.
Established - Set 1 1/2" x 36" I.P. with 3" brnz. cap mkd, "Ore.St.Bd.of
Forestry T23S R10W CC S33 S34 S3 T24S R10W 1960 RS359",
30" in gr. S.0°31'E. 3.7 ft. from Orig. CC which I mark AM
on the pipe cap and AM on each of the bearing trees.
(See PRIOR REN. #46)

Dec.
14,
1961
See Also C. S. 49/80

SEE ALSO
M133, 14
(Ren. #18)

52

1/4 Corner common to Sections 27 and 34.
Orig. - Fir Post, now missing, from which a:
13" Fir bears S.53°E. 14 lks.; now 17", exposed scribes S34.
13" Fir bears N.59°W. 19 lks.; now 25", face grown over.
Restored: Set 1 1/2" x 36" Gal. iron pipe with 3" bronze cap Mkd:
"Ore.St.Bd.of Forestry 1/4 S27 S34 1961 RS359", 32" in gr.,
in mound of stone, and from which a:
21" Fir bears N.16°W. 51.1 ft.; scribed RS359.
Ore. St. Bd. of Forestry metal location poster on Orig. 13" Fir
BT. N.W.
Set 4" x 4" x 72" white painted Cedar Post 1.5 ft. NE of pipe.

OVER