

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 10 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

71  
Closing Corner common to Sections 6 & 7.  
Original - Post, now missing, from which a:  
6" Fir bears N. 38 $\frac{1}{2}$ ° E. 16 lks.; now 17", exposed scribe C.  
30" Fir bears S. 24° E. 133 lks.; now destroyed by road,  
portions of the stump still in road berm.  
Ridge, course S. 50° W., bears South 2.08 chs.; in place.  
Restoration by A. R. Evans, February, 1952, See Ren. #4, T23-9W.  
4"x4"x36" Fir Stake, found in place, from which a:  
8" Fir bears S. 42° E. 28.1 ft.; now 9" fir, in place, face  
pitched over.  
Restored - Set 1 $\frac{1}{2}$ "x36" galv. iron pipe with 3" br. cap mkd. "Ore.St.Bd.  
of Forestry T23S S1S6S7 CC R10W R9W 1967 RS359", 34" in  
ground, in place of Evans post, in mound of rock & from which:  
24" Fir bears N. 71° E. 20.0 ft., to face; scribed T23SR9WS6CCBT  
RS359.  
Set - 4"x4"x72" white painted cedar post 1 ft. West of corner pipe.  
Ore.St.Forestry Dept. metal location poster on 24" Fir N. 39° W. 9.5 ft.  
(See Corner Below for true corner, set 3/15/68)

72  
True Closing Corner for Sections 6 & 7, T23-9W.  
Set - S. 88° 37' 06" W. 40.24 ft. of Corner above, Ren. #71.  
Set - Ore.St.Bd. of Forestry, 1 $\frac{1}{2}$ "x36" Galv. I.P. with 3" Bronze Cap.  
20" Fir N. 31 $\frac{1}{4}$ ° E. 17.7 ft. (RS359) Yellow Metal Location Poster.  
20" Fir S. 82° E. 23.3 ft.  
White Painted Cedar Post bears S. 10° E. 1.0 ft.

73  
 $\frac{1}{4}$  Corner Section 6, T23-9W.  
Set - Ore.St.Bd. of Forestry 1 $\frac{1}{2}$ " x36" Galv.I.P. with Bronze Cap.  
24" Fir N. 62  $\frac{3}{4}$ ° W. 38.5 ft. ( $\frac{1}{4}$  S6 BT)  
21" Fir S. 80° E. 28.4 ft.  
25" Fir S. 27 $\frac{1}{2}$ ° E. 31.4 ft. (RS359) Yellow Metal Location Poster  
Ridge top crs. NE., south 65.0 ft.  
White Painted Cedar Post bears N. E. 1.0 ft.

74  
Closing Township Corner for Section 1, T23-10 & Sec. 6, T23-9W,  
reestablished.  
Set - Ore.St.Bd. of Forestry 1 $\frac{1}{2}$ " x 36" Galv. I.P. with Bronze Cap.  
26" Fir N. 72 $\frac{1}{4}$ ° E. 27.5 ft.  
42" Fir S. 38 $\frac{1}{4}$ ° W. 12.8 ft. (RS359) Yellow Metal Location Poster.  
46" Fir S. 60° E. 34.8 ft.  
White Painted Cedar Post bears NW. 1.0 ft.

75  
 $\frac{1}{4}$  Corner to Sections 1 and 12, T23 - 10W.  
Set - 2 $\frac{1}{2}$ " Bras Cap Mkd: SEEK, Inc.  
T 23 S R 10 W  
 $\frac{1}{4}$  S 1  
S 12  
1968  
Found - Hub and Tack with bearing Trees (4) Ren. #5.  
New Bearing Tree: 12" Maple S. 72° E. 13.0 ft. mkd:  $\frac{1}{4}$  S12.  
6" Gross in Rock Wall N. 76° W. 20.5 ft. mkd:  $\frac{1}{4}$  S1.  
SEE ALSO REN. #5

76  
East  $\frac{1}{4}$  Corner, Section 12.  
Set - 2 $\frac{1}{2}$ " Brass Cap Mkd: SEEK, Inc.  
T 23 S R 10 W  
 $\frac{1}{4}$  S 12  
1968  
Bearing Tree: 30" Fir N. 18° W. 28.0 ft. mkd:  $\frac{1}{4}$  S12.  
36" Fir S. 78° W. 19.7 ft. mkd:  $\frac{1}{4}$  S12  
77  
Witness Corner- Center  $\frac{1}{4}$ , Section 12.  
Set - 5/8" Iron Rod 128.48 ft. S. 0° 46' 42" E. of Center of Section.  
Bearing Trees: 18" Fir S. 28° E. 36.8 ft. mkd: W.C. C  $\frac{1}{4}$  S12.  
6" Fir N. 10° W. 5.0 ft. mkd: W.C. C  $\frac{1}{4}$  S 12.

Ore.St.Bd. of Forestry  
Arnold G. Gibson  
Oct. 26, 1967  
C.S. File No. 55/68

C. S. File No. 55/68

SEPT. 28

Wm. C. Stiles  
For Jackson Beaman  
Sept. 1968 C.S. 55/89 M 36 - 42