

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 10 W. R. W. W. M.

Ore. St. Bd. of Forestry  
Arnold G. Gibson  
12/16/68  
C.S. File No. 55/101

Section Corner Common to Secs. 34 & 35, T22 & 23 S., R.10W.  
Original Stone 5'x4'x3' (found with 4 in. "X", 8" from the N. end  
& 4 notches on the west) from which a:  
28" Fir bears N.80°E. 12 lks.; now 28" burned windfall,  
scribes T S R O B visible.  
36" Fir bears S. 6° W. 15 lks.; now a 52" windfall.  
30" Fir bears N.82°W. 10 lks.; now a 36" windfall.  
Stone 3' high bears N.20°W. 30 lks.; now a 30' high bluff in place.  
Spur, course N.15°E., bears west 60 lks.; now in place.  
Rewitnessed - Marked 2 notches on the E. of Orig. Stone, from which a:  
50" Fir bears N.6°E. 116.0 ft.; scribed T22S R10W S35 BT RS 359.  
30' Bluff bears N.31°W. 15.0 ft.; marked XBO.  
Set 4"x4"x72" white painted cedarpost 2 ft. N.W. of Cornerstone.  
Ore.St.Forestry Dept. metal location poster on 50" Fir N.6°E. 116.0 ft.

78

1/4 Corner to Sections 15 and 16.  
Orig. - Fir Post, missing, from which a:  
10" Fir bears S.0 1/2°E. 79 lks.; now 39" stump, in place, scribe visible.  
8" Fir bears N.67°W. 69 lks.; now 36" stump, in place, face open,  
no scribe visible.  
Set - 1 1/2"x36" galv. iron pipw with 3" br. cap mkd: Ore.St.Bd.of Forestry  
1/4 S15 S16 1969 RS359", 34" in ground, and from which a:  
14" Fir bears N.83 1/2°E. 25.4 ft., to face; scribed 1/4 S15 BT RS359.  
14" Fir bears N.30°W. 23.9 ft., to face; scribed 1/4 S16 BT.  
Set 4"x4"x72" white painted Cedar Post 1.4 ft. S.50°W. of corner pipe.  
Ore.St.Forestry Dept. metal location poster on 14" Fir BT N30W.

79

12/3/69

Section corner common to Sections 14 and 23, T23S, R10W, W.M. Doug.Co., Ore.  
Orig.-Fir Post (destroyed by Levi Walker in 1906) from which a:  
60" Fir bears N30°E 8 lks.; now 60" stump in place, bottom of face  
with axe work visible.  
24" Fir bears S45° E 154 Lks.; now 40" stump in place, old axe  
work visible.  
60" Fir bears S45°W 6 lks.; (obliterated by Levi Walker) now 55"  
stump in place.  
50" Fir bears N55°W. 36 lks.; (obliterated by Levi Walker) now  
missing, point falls in old cut road.  
Restoration by Levi Walker 1906. Fir post (missing) from which a:  
Closing corner 15 and 22 bears N 1.57 chs.; in place.  
Set - 1 1/2"x36" galv. i.p. with 3" bronze cap mkd. "ore.St.Bd. of For.  
T23S S14 S23 S22 R10W 1970 RS359", 34" in ground at corner point  
and from which a:  
8" Fir bears N82°E 11.4 ft. to face; scribed T23S R10W S14 BT RS359.  
5" Fir bears S46°E. 68.1 ft. to face; bark scribed T23S R10W S23 BT.  
Set - 4"x4"x72" white painted Cedar post 1.3 ft. N of corner pipe. Ore.  
St. For.Dept. metal location poster on 8" Fir BT N82°E 11.4ft.

80

118

6/18/70

Ore. St. Bd. of Forestry  
Arnold G. Gibson  
May, 1970  
C.S. File No. 55/154

Closing corner common to Sections 15 and 22, T23S, R10W, W.M.  
Orig.-Fir post (missing) from which a:  
6" Fir bears N27°W 27 lks.; only decayed root system remaining.  
12" Hemlock bears S85°W 38 lks.; now 30" in place, scribes 23 S2 BT exp.  
Set - 1 1/2"x36" galv. i.p. with 3" bronze cap marked "Ore.St.Bd. of For. T23S  
S15 CC S22 R10W S14 1970 RS359", 34" in ground, and from which a:  
30" Hemlock (orig.) bears S85°W 25.1 ft.; scribed RS359.  
25" Hemlock bears N63°W 67.1 ft.; scribed T23S R10W S15 CC BT.  
Section corner 14 and 23 bears South 1.57 chs.  
Set - 4"x4"x72" white painted Cedar post 2.0 ft. N30°W of corner pipe.  
Ore.St.For.Dept. metal location poster on orig. Hemlock S85°W 25.1 ft.

81

6/18/70

119