

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Witness Corner for 1/4 Corner to Sections 24 and 25.
1/4 Corner Found, See Ren. #29, (Corner Point now falls in Lake Creek)
Established Witness Corner 26.18 ft. West of True Corner.
Set OSBF P/C 34" E. G.
38" Myrtle N. 47 1/2° W. 37.6 ft., YMLP
29" Myrtle S. 83 1/2° W. 65.0 ft. (RS359)
4" x 4" x 72" White Painted Cedar Post S. 79 1/2° W. 2.4 feet.

92

Ore. St. Bd. of Forestry
Gibson, A.
Map File M 47

6/29/72

S.E. Corner, Section 10 only.
Section Corner Reestablished

Set - Ore. State Bd. of Forestry I. P. with 3" Cap, 12" in ground.
BT's - 20" Fir, N. 16° W., 183.4 ft. with yellow metal location poster.
16" Fir, N. 50° W., 149.1 ft. (RS359)
4" x 4" x 72" White painted cedar post North 2.0 ft.

93

Section Corner for Sections 11, 14 and 15 only.
Section Corner reestablished

Set - O.S.B.F. Iron Pipe with 3" Bronze cap, 34" in ground.
BT's - 9" Fir, N. 77° E., 23.5 ft. with yellow metal location poster.
10" Fir, S. 28 1/2° E., 44.0 ft. (RS359).
4" x 4" x 72" White painted cedar post N. 80° E., 2.8 ft.

94

Center 1/4 Corner Section 14.

Set - O.S.B.F. Iron Pipe with 3" Bronze cap 36" in ground.
BT's - 15" Fir, N. 26° E., 21.8 ft. with yellow metal location poster.
6" Fir, S. 66 1/4° E., 19.6 ft. (RS359)
4" x 4" x 72" White Painted cedar post N. 50° E., 3.0 ft.

95

1/4 Corner, Sections 14 and 23.

1/4 Corner reestablished.
Set - O.S.B.F. Iron pipe with 3" Bronze cap 34" in ground.
BT's - 11" Fir, N. 31° E., 10.8 ft. (RS359)
9" Fir, S. 01° E., 8.3 ft. with yellow metal location poster.
4" x 4" x 72" White painted cedar post N. 62° W., 1.7 ft.

96

Standard Corner common to Secs. 34 and 35, only, on south line

Found: 3/4" pipe set by Weyerhaeuser and remains of all original B.T.'s
Ren. #66
Set: 1 1/2" Iron pipe flanged on bottom projecting 1 foot out of ground from which a 10" hemlock bears N. 10° E., 212 ft. scribed " S 35 x" in single blaze.
A 24" Hemlock bears N. 80° W., 24.4 ft. scribed " X S 34"
Compass Declination 20°

97

Clell Goodwin
Lenora Ladig
CS 57/30
June 17, 1975

Section Cor. for Sec. 10 only. (Southeast)
Original - No evidence of orig. corner found.
Reestablished by A. Gibson, 1972 Ren. #93

1 1/2" x 36" G.I.P. (missing, in recently logged area) from which a:
20" Fir bears N. 16° W., 183.4 ft.; now 22" stump in place, scribes T23S R10W S10 BT visible.
16" Fir bears N. 50° W., 149.1 ft.; now 18" stump in place, scribes T23S R10W S10 BT RS359 visible.
4" x 4" x 72" WPCP bears North 2.0 ft.; found, knocked out of place by recent logging.
Restored - Set 1 1/2" x 36" galv. iron pipe with 3" bronze cap mkd. "OREGON STATE BOARD OF FORESTRY T23S R10W S10 S11 1976 RS359", 34 inches in ground.
Reset - 4" x 4" x 72" white painted cedar post N. 20° W., 1.6 ft. from corner pipe. Oregon State Forestry Dept. metal location poster on 4" x 4" x 72" WPCP.

98

Arnold G. Gibson for
State of Oregon Dept of Forestry.
Witness: Rase R. Johnson
June 14, 1976
C.S. 58/31

State of Oregon, Department of Forestry
Arnold G. Gibson
December 8, 1972
M 49 - 20

RENEWED, SEE CORNER NO. #104

RENEWED, SEE CORNER NO. #98

RENEWED, SEE CORNER NO. #99

RENEWED, SEE CORNER NO. #121

Jan 1973

Jan 15

1/10