

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

99

Arnold G. Gibson for: State of Oregon, Dept. of Forestry
Witnessed by James M. McIntosh
June 14, 1976
C.S. 58/31

Section corner common to Secs. 11 and 14 only.
No evidence of original corner found.
Restoration by A. Gibson, 1972 Ren. #94
1 1/2"x36" G.I.P. (found in place) from which a:
9" Fir bears N.77°E., 23.5 ft.; missing, in new road location.
10" Fir bears S.28 1/2°E., 44.0 ft.; missing, in new road location.
4"x4"x72" WPCP bears N.80°E., 2.8 ft.; found, in place.
Rewitnessed - From above 1 1/2" x 36" G.I.P. a:
14" Fir bears S.1°W., 111.9 ft. to face; scribed T23S R10W S14
BT RS359.
15" Fir stump bears S.31°E., 108.5 ft. to face; scribed T23S
R10W S14 BT.
Oregon State Forestry Department metal location poster on 4"x4"x72" WPCP
N.80°E., 2.8 ft.

100

Section corner common to Secs. 11 and 15 (North end)
Original post (missing) from which a:
24" Fir bears S.9°E., 85 lks.; now 63" stump in place, face
burned away.
24" Fir bears S.57°W., 63 lks.; now 46" stump in place, scribes
T and parts of backcast on burnt face exposed.
Restoration by A. Gibson, 1972 Ren. #89
1 1/2" x 36" G.I.P. (found in place) from which a:
13" Fir bears S.26 1/2°W., 76.2 ft.; missing, in new cat road
location.
56" Fir bears S.84°E., 40.1 ft.; now 56" stump, in place, scribes
T23S R10W S11 BT visible.
4"x4"x72" WPCP bears S.64°E., 2.6 ft.; found, in place.
Rewitnessed from above 1 1/2" x 36" G.I.P. a:
57" Fir stump bears S.87°W., 15.8 ft. to face; scribed T23S R10W
S15 BT RS359.
63" Fir stump (original) bears S.9°E., 55.0 ft. to face; scribed
T23S R10W S11 BT.
Oregon State Forestry Department metal location poster on 4" x 4" x 72"
WPCP S.64°E., 2.6 ft.

6/14/76

101

NE Corner for Sec. 36.
Set - 2" Gal. I.P. with brass cap
From Which:
A 12" Chinquapin, scribed BT, bears N.57°W., 16.7 ft.
A 10" Chinquapin, scribed BT, bears S.41°E., 9.6 ft.
A 10" Fir, scribed BT, bears S.87°W., 15.2 ft.
A 14" Fir, scribed BT, bears N.35°W., 11.2 ft.

*FD OK 5/71
M113-34 AFB*

12/1/76

102

North 1/4 Corner for Sec. 36
Found - 3" square fir stake
From which:
A 20" Hemlock stub, badly rotted bears S.20°E., 8.5 ft. (Rec. 36",
S.20°E. 12 links)
An 18" Hemlock stub, badly rotted bears N.20°W., 22.6 ft. (Rec. 30"
Hemlock N.20°W., 30 links.)
Set - I placed a 2" Gal. I.P. with brass cap at the point mkd. by the
stake from which:
A 16" Hemlock scribed BT bears S.61°E., 21.4 ft.
A 14" Fir scribed BT bears N.45°W., 9.1 ft.

*FD OK 8/96
T. Hostetter M126-31*

12/1/76

103

Witness Corner to Meander Corner Secs. 1 and 12
Set - 2 1/2" Brass cap on 1" I. Pipe 8" above ground and marked:
T23S R10W Wit. Cor. to MC S1 S12 1977.
BT's- 30" D. Fir bears N.20 1/2°E., 11.5 ft. scribed "WC S1 BT"
5" D. Fir bears S.74 1/2°E., 9.0 ft. scribed "WC S12 BT".
Corner lies 100 ft. East of paved road on E-W timberline.

4/77

*Jan 78
1-79*

Michael S. McDowell
For: Weyerhaeuser Company
December 1, 1976
M 62 - 48
C.S. 58/128

Glenn Baughman
For: Richard Harder
April, 1977
M 65 - 28
C.S. 58/144

3-77