

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
August 25, 1960
C. S. File No. 52/42

Thomas W. Coiner, R.S. 413
For Bohemia Lumber Co., Inc., Culp Creek, Ore.
August 24, 1961
C. S. File No. 51/209

1
 $\frac{1}{4}$ Section Corner to Sections 29 and 32.
 Found - Orig. 12", now 14" Cedar North 2.0 ft., shows good scribing " $\frac{1}{4}$ S".
 Orig. 12", now partly rotted Stump, shows good scribing, " $\frac{1}{4}$ S" S.22°E. 25.1 ft.
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S29	T24S	RLW	101
S32			

 New BT's: 12" Hemlock bears S.10°E. 33.4 ft. scribed $\frac{1}{4}$ S32 CS BT.
 11" Hemlock bears N. 1°W. 27.1 ft. scribed $\frac{1}{4}$ S29 CS BT.

2
 Section Corner to Sections 28, 29, 32, and 33.
 Found - Three Orig. BT's, check bearing & distance.
 S. W. BT. gone. N.E. & N.W. show scribing.
 S. E. BT. shows good face but no scribing.
 I scribe this BT., S.28 $\frac{1}{2}$ °E. 16.5 ft. S33 T24S RLW.
 Note - Centerline Logging Road N.40°W. 13 feet.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S29	S28	T24S	RLW	104
S32	S33			

 15" Pine bears S.54°W. 27.9 ft. scribed S32 T24S RLW CS BT.

3
 Section Corner to Sections 29, 30, 31 and 32.
 Found - Orig. 10", now 12" Fir Snag N.62°E. 12.5 ft, shows good scribing.
 Orig. 8", now 16" Fir N.83°W. 19.8 ft., shows good scar.
 Orig. 8", now 10" Fir Snag, shows good scribe mkd., S.75°E. 9.2 ft.
 Orig. 8", now 12" Fir Snag S.26°W. 8.6 ft., shows good scribe marks.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S30	S29	T24S	RLW	#145
S31	S32			

 New BT's: 12" R.Fir bears N.29°E. 53.0 ft. scribed S29 T24S RLW CS BT.
 8" R.Fir bears S.54°E. 30.5 ft. scribed S32 T24S RLW CS BT.
 18" R.Fir bears S.81°W. 22.3 ft. scribed S31 T24S RLW CS BT.

4
 $\frac{1}{4}$ Corner of Sections 11 and 12.
 Determined from the Stump of one of the Orig. BT's:
 A D. Fir Stump, 38", bears N.57°E. 33 ft., blaze healed.
 New BT: A D. Fir 26", bears N.52 $\frac{1}{2}$ °E. 106.8 ft. mkd. $\frac{1}{4}$ S12 BT.
 A D. Fir 28", bears S.05°W. 140 ft. mkd. S11 $\frac{1}{4}$ BT.
 At the corner point: Set Iron Pipe 30" x 2" x 16" in the ground, with mound of stone to top, with aluminum bronze cap mkd: $\frac{1}{4}$ S11/S12.

5
 $\frac{1}{4}$ Corner to Sections 11 & 14. Determined from the Orig. BT's and the hole where the Orig. Post was Set. Post down but intact.
 At the corner point: Set Iron Pipe in old post hole, 30"x2"x12" in the ground with aluminum bronze cap Mkd: $\frac{1}{4}$ S11

S11	S14
S14	S11

 from which:
 A. D. Fir 20" bears N.40°E. 4 ft. blaze healed.
 A D. Fir 36" bears S.40°W. 31 ft. blaze healed.

6
 Section Corner common to Sections 11 - 12 - 13 - 14.
 Point at prop. dist. There is no evidence of the Orig. Corner.
 Set an I. P. 30" x 2" x 6" in the ground, with a mound of stone to top and aluminum bronze cap mkd:

11	12
14	13

 from which:
 Andesite boulder 6x5x2.5 ft. above ground bears N.49°E. 24 ft. Mkd: X BT T24S RLS S12
 Breccia Boulder 5x3.5x3.5 ft. above ground bears N.10°W. 1.0 ft. mkd: X BO T24S RLW S11.
 Sugar Pine 30", bears S.83°13'E. 282.2 ft. mkd. T24S RLW S14 BT.
 D. Fir 32", bears S.8°43'W. 228.8 ft. mkd: T24S RLW S14 BT.