

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 1 R. W. W. M.

Section Corner to Sections 20 - 21 - 29 - 28. 7

Found - Orig. Rock with 4 notches on E. & 2 Notches on E. edges,
Rock lying loose on top of ground.
Fir Tree, now 27", N.14 $\frac{1}{2}$ °E. 21.1 ft. Has been opened recently,
good scribing "T24SRLW S21 BT" plainly visible.
Fir Tree, now 12", N. 4°W. 16.4 ft. (instead of 17.8 ft.) has
been opened several years ago, scribing visible "24SRW20"
Face shows signs of decay although tree is alive.
Fir Tree, now 44", S.10°W. (instead of S.4°W.) 31.0 ft.,
recently opened, good scribing "T24SRLWS29BT" visible.
Fir Tree, now 45", S.10°E (instead of S14°E) 37.0 ft., shows
good axe scar, did not open.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24S RLW

S20	S21
S29	S28

New BT's: 40" Fir N.22°W. 10.3 ft. Mkd: T24S RLW S20 CS BT. FD. OK. V.R.T. MAY 1970

$\frac{1}{4}$ Corner to Sections 20 and 21. 8

Found - Dead Fir Snag, now 15", N.7°E. 29.0 ft., not completely grown
over, good scribing " $\frac{1}{4}$ S BT", plainly visible.
Fir Tree, approx. 38", N.14 $\frac{1}{2}$ °W. 23.1 ft. (to center of tree)
Very good axe scar, did not open.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24S RLW $\frac{1}{4}$ S20/S21. 105

New BT's: 10" Hemlock N. 8°E. 13.0 ft. Mkd: $\frac{1}{4}$ S21 CS BT.
7" Yew N.82°W. 3.7 ft. Mkd: $\frac{1}{4}$ S20 CS BT.

$\frac{1}{4}$ Corner to Sections 32 and 33. 9

Found - Fir, now 20", N.45°E. 4.6 ft., Tree uprooted, down & dead.
Opened scar & found good scribing "T".
Pine Snag, now 16", S.18°W. 5.3 ft. has been previously
opened & good scribing "S" visible.

Did not find corner Rock.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24S RLW $\frac{1}{4}$ S32/S33. #103

New BT's: 7" D.Fir N.70°E. 19.7 ft. Mkd: $\frac{1}{4}$ S33 CS BT.
12" D.Fir N.78 $\frac{1}{2}$ °W. 21.5 ft. (to base) Mkd: $\frac{1}{4}$ S32 BT CS.

Section Corner to Sections 17 - 16 - 20 - 21. 10

Found - Pine Tree, now 21", N.40°E. 50.3 ft. (instead of 52.1 ft)
shows good scar, did not open.
Fir Tree, now 30", N.43°W. 11.2 ft., shows good scar, did
not open. (These 2 on steep slope)
Hemlock Tree, now 26", S.80°W. 62.7 ft. Scar opened previously
& scribing visible, "24 1W S20". These 3 trees in good condition.
Hemlock Tree, now 28", S.27°E. 33.3 ft. (instead of 35.6 ft.)
opened previously & scribing visible "4S S21" Top of tree
dead, will probably not last many more years.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24S RLW

S17	S16
S20	S21

New BT: 13" Hemlock S. 7 $\frac{1}{2}$ °E. 31.9 ft. Mkd: T24S RLW S21 CS BT.

$\frac{1}{4}$ Corner to Sections 29 and 28. 11

Found - Fir Tree, now 18", S.74°W. 22.4 ft. has been opened previously.
good scribing " $\frac{1}{4}$ S" visible.

Fir Tree, now 40", S.74°E. 7.9 ft. Good axe scar, did not chop open.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24SRLW $\frac{1}{4}$ S29/S28. #159

Both Orig. Trees in good condition. Did not mark new Trees.

$\frac{1}{4}$ Corner to Sections 8 and 17. 12

Found - Fir Tree, now 30", S. 3°W. 21.8 ft., shows good scars-Didn't open.
Hemlock Tree, now 13", N.65°W (instead of N.72°W) 5.9 ft., cut
open & fd. good scribing "S".

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T24S RLW $\frac{1}{4}$

S 8	S17
-----	-----

Both Old Bearing Trees in good condition - Did not mark any new trees.

FD. OK 10/76 M 62-35 BY NICK JULIANO

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Clete Putnam
October 1961 - C. S. File No. 52/42

RE-RENEWED CORNER NO. #103

RE-RENEWED CORNER NO. #159