

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

58

Vernon "Ray" Tracy
Jack Heritage & E. West
Nov. 3, 1966
C. S. File No. 52/30

Township Corner: $\begin{array}{c} T24S \text{ RLW } \frac{S \ 36}{S \ 1} \mid \frac{S \ 31}{S \ 6} \text{ RLE} \\ T25S \end{array}$

Found - Orig. 18", now 28" Cedar, N. 64° E. 11.2 ft., prev. opened many years ago, "S E S3" scribe visible on nearly rehealed blaze. Rescribe "T24S RLE S31 DCS BT".

Orig. 28", now 36" Fir S. 37° E. 43.6 ft. Alive & in good condition, shows very good scar.

Orig., 30", now 36" Fir, S. 86° W. 33.0 ft. Alive & in good cond., shows very good scar.

Orig. 18", now 21" Fir N. 25° W. 31.0 ft. Alive, good cond. shows very good scar.

Set - Brass Cap at Cor. Mkd. Doug. Co. Surveyor's Office, 1966 $\begin{array}{c} T24S \text{ RLW } \frac{S \ 36}{S \ 1} \mid \frac{S \ 31}{S \ 6} \text{ RLE} \\ T25S \end{array}$

New BT: 10" Hemlock N. 60° W. 34.8 ft. mkd. T24S RLW S36 DCS BT.

Note - No smaller trees close to SE. or SW. *Fo. O.K. MAY 1970 V.R.T.*

This corner is on Douglas - Lane County Line.

59

$\frac{1}{4}$ Corner to Sec. 33, T24-1W. & Sec. 4, T25-1W.

Found - Orig. 14" Yew S. 82° E. 17.8 ft., scribe visible on unhealed blaze. 36" W. Fir, now 25* high Snag, N. 55° W. 11.2 ft. scribe visible. No trace of Brass Cap as recorded in Ren. #32. Due to logging, Hemlock BT. now knocked over.

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 $\begin{array}{c} T24S \ \frac{1}{4} \ \frac{S \ 33}{S \ 4} \ \text{RLW} \\ T25S \end{array}$

New BT's: 6" Hemlock S. 29° W. 39.9 ft. mkd. $\frac{1}{4}$ S 4 CS BT.
11" Hemlock N. 83° E. 60.4 ft. mkd. $\frac{1}{4}$ S33 CS BT.

Note - This corner lies on E-W cutting line cut off to N., approx. 300' E. of small creek, course S.W.

60

Sec. Cor. to Secs. 33 & 34, T24-1W. & Secs. 3 & 4, T25-1W. #151

Found - Orig. 48", now 53" Fir, N. 18° E. 44.2 ft. Open & find "34" scribe. Orig. 6", now 24" Fir S. 29° E. 29.1 ft. (not 27.7 ft.) shows scar. Orig. 48", now 58" Fir, S. 35° W. 24.4 ft. (not 28.3 ft.) shows scar. Orig. 36", now 54" Fir, N. 24° W. 42.2 ft. Alive, shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 $\begin{array}{c} T24S \ \text{RLW} \ \frac{S \ 33}{S \ 4} \ \frac{S \ 34}{S \ 3} \\ T25S \end{array}$

New BT's: 8" W. Fir N. 40° W. 8.2 ft. mkd. T24S RLW S33 CS BT.
8" W. Fir N. 56 $\frac{1}{2}$ ° E. 13.2 ft. mkd. T24S RLW S34 CS BT.

Note - Corner lies on steep, East slope.

61

$\frac{1}{4}$ Corner to Sec. 32, T24-1W. & Sec. 5, T25-1W. #130

Found - Orig. 14", now 17" Cedar, N. 43° W. 5.3 ft. Open & find scribing. Orig. 36", now 40" Fir, S. 74° E. 18.5 ft. Alive, shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 $\begin{array}{c} T24S \ \text{RLW} \ \frac{1}{4} \ \frac{S \ 32}{S \ 5} \\ T25S \end{array}$

New BT's: 6" Hemlock N. 52° W. 26.7 ft. mkd. $\frac{1}{4}$ S 32 CS BT. *Fo. O.K. V.R.T. MAY 1970*
5" Hemlock S. 49° E. 32.5 ft. mkd. $\frac{1}{4}$ S 5 CS BT.

62

$\frac{1}{4}$ Corner to Sec. 34, T24-1W. & Sec. 3, T25-1W.

Found - Orig. 24", now 36" Fir N. 50° E. 28.3 ft. Open & find "B" scribe. Orig. 42", now 48" Fir, S. 42° W. 23.1 ft. Alive, shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 $\begin{array}{c} T24S \ \text{RLW} \ \frac{1}{4} \ \frac{S \ 34}{S \ 3} \\ T25S \end{array}$

New sBT's; 12" Hemlock N. 31° W. 9.2 ft. mkd. $\frac{1}{4}$ S34 CS BT.
8" Hemlock S. 2° W. 3.3 ft. mkd. $\frac{1}{4}$ S 3 CS BT.!

Note - This corner lies N. of Grizzly Creek approx. 250' on bench.

~~$\frac{1}{4}$ Corner to Sec. 36, T24-1W. & Sec. 1, T25-1W.~~

~~Found - Orig. 12", now 23" Fir, S. 70° E. 11.2 ft. Open & shows "BT" scribe. Orig. 24", now 30" Fir, N. 75° W. 10.6 ft. shows good scar. Do not open. Alive.~~