

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

63

1/4 Corner to Sec. 36, T24-1W. & Sec. 1, T25-1W.
Found - Orig. 12", now 23" Fir, S. 70° E. 11.2 ft. Opened & shows
"BT" scribe. Alive.
Orig. 24", now 30" Fir, N. 75° W. 10.6 ft., shows good scar.
Alive. Do not open.

No trace of Stone called for at corner.

Set - Brass Cap at Cor. Mkd: County Surveyors T24S RLW 1/4 S 36
(in Mound of Stone) Office, 1966 T25S S 1
New BT's: 24" D. Fir S. 20° W. 35.3 ft. mkd. 1/4 S1 CS BT.
7" Laurel N. 4° W. 19.3 ft. mkd. 1/4 S 36 CS BT.

Note - This corner lies on S. side of small creek, course S.W. on
very steep, westerly slope in area of several small bluffs.
Nov. 14, 1966

1/4 Corner to Sections 14 and 23.

Found - Orig. 16", now 32", Cedar, N. 5° W. 36.3 ft. Open & find
"4 S" Scribe & reverse.

No trace of other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyors T24S RLW 1/4 S 14
Office, 1966 S 23

New BT's: 8" Chinq. S. 88° W. 18.3 ft. mkd. 1/4 S23 CS BT.
8" D. Fir N. 24° E. 6.3 ft. mkd. 1/4 S14 CS BT.

Note - This corner lies very near the top of spur, ridge, course S.W.
Oct. 26, 1966

1/4 Corner to Sections 26 and 35. (Witness Corner)

Found - Orig. 16" Cedar, Alive, N. 25° E. 17.2 ft., shows good scar, sets
in edge of fill for new logging road.

6" W. Fir (not Hemlock) N. 72° E. 35.7 ft. Alive at foot of fill,
scribe visible. See Ren. #37.

8" Hemlock S. 26° W. 81.4 ft. Alive, scribe visible on upper
side of road. Actual Corner falls in Road.

Set - 3/4" I.R. flush with road & surface & Witness Corner 70 ft. West.

Brass Cap at Cor. Mkd: County Surveyors T24S RLW
Office Wit. Cor. 1/4 S 26
1966 S 35

70 ft. E. to Corner.

New BT'S: 13" D. Fir N. 7° E. 12.6 ft. mkd. W.C. 1/4 S 26 CS BT.

18" D. Fir S. 1° W. 3.8 ft. mkd. W. C. 1/4 S 35 CS BT.

(Apr. '70 - Straighten Cap & Set 6' Steel Fence Post alongside) C.S. 54/27

Sec. Cor. to Sections 19 - 20 - 29 - 30.

Found - Original Corner Stone 12" x 8" x 8" mkd. with 2 notches on S. &
5 notches on E.

Orig. 20", now 30" Fir, N. 73!° E. 25.7 ft., shows good scar. Alive.

Orig. 16", now 22" Fir, S. 45° E. 25.7 ft., shows good scar. Alive.

Orig. 8", now 12" Fir, S. 27° W. 14.5 ft. Alive, shows good scar.

(Rescribe "T24S RLW S30 CS BT".

Orig. 20", now 26" Cedar N. 33° W. 6.6 ft. Alive, shows good scar,

Set - Brass Cap at Cor. Mkd: County Surveyors T24S RLW
Office S 19 | S 20
1966 S 30 | S 29

New BT: 8" Hemlock N. 9° W. 23.1 ft. mkd. T24S RLW S19 CS BT.

Note - This corner lies on N.E. slope of spur, approx. 90 ft. off top.

1/4 Corner to Sections 30 and 29.

Found - Orig. 30", now 48" Fir, N. 38° E. 17.8 ft. Alive, shows good scar.

Orig. 15", now 28" Fir, N. 36° W. 9.2 ft. Alive, Open & find "1/4" scribe.

Set - Brass Cap at Cor. Mkd: County Surveyors T24S RLW 1/4 S 30/S 29
Office, 1966

New BT's: 15" I. Cedar N. 59° W. 14.2 ft. mkd. 1/4 S30 CS BT.

14" D. Fir N. 45° E. 23.6 ft. mkd. 1/4 S29 CS BT.

Note - This corner lies on top of ridge, sloping west.

Vernon "Ray" Tracy
Jack Heritage and E. West
October and November, 1966
C. S. File No. 5242

66

67

FOK
MAY 1970
V.R.T.
F.B.A.K.
11/25/73
V.R.T.