

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21891

68

Sec. Cor. to Secs. 31 & 32, T24-1W. & Secs. 5 & 6, T25-1W.
Found - Orig. 12", now 17" Fir Stump, S. $87\frac{1}{2}^\circ$ W. 46.2 ft. We open & find "S6 Rlw" scribe & reverse. Bearing & approx. distances fit holes of other Original bearing trees, down & out of position.

Set - Brass Cap at Cor. Mkd: County Surveyors Office 1966

T24S R1W	
S 31	S 32
S 6	S 5

New BT's: 6" Hemlock N. 73° W. 52.0 ft. mkd. T24S R1W S31 CS BT.
12" Yew S. $66\frac{1}{2}^\circ$ W. 16.8 ft. mkd. T25S R1W S 6 CS BT.
11" Yew S. 25° E. 24.4 ft. mkd. T25S R1W S 5 CS BT.
8" Hemlock N. 29° E. 59.8 ft. mkd. T24S R1W S32 CS BT.

Note - This corner lies on N.E. slope in logged unit. Dec., 1966

Vernon "Ray" Tracy
J. Heritage & E. West
1966 & May, 1967
C. S. File No. 52/30

69

Closing Corner T24S R1W S 31 T24-1W / T25S S 1 S 6 T25-1W

Found - 1951 Cad. Brass Cap, properly mkd. & BT's. down & out of place.
New BT's: 8" Cedar S. 64° W. 114.6 ft. mkd. T25S R2W S1 CC CS BT.
34" D. Fir S. $79\frac{1}{2}^\circ$ E. 41.6 ft. mkd. T25S R1W S6 CC CS BT.

Found - I.P. & Steel Cap (See Ren. #11-A) bears N. 21° W. 2.8 ft. The BT's. for this corner are also dead. \rightarrow T. 25-1

Note - Cadastral corner lies on east slope on cutting line course E - W. with timber to north. May 5, 1967

Witness Corner to Sections 7 - 8 - 17 - 18.

Found - County Surveyor Brass Cap & BT's. (Ren. #15), all in good condition.

Remove Brass Cap & set Witness Corner 90 ft. West of actual corner for road construction in near future.

Brass Cap now Mkd: County Surveyor's Office 1961

T 24 S R 1 W	90' E. to
W.C. S 7 S 8	Corner.
S 18 S 17	

New BT's: 18" Pine N. 15° W. 51.8 ft. mkd. W.C. T24S R1W S7 CS BT.
20" D. Fir N. 64° E. 11.0 ft. mkd. W.C. T24S R1W S8 CS BT.
36" D. Fir S. 12° E. 7.0 ft. mkd. W.C. T24S R1W S17 CS BT (in bark)
20" D. Fir S. 64° W. 36.0 ft. mkd. W.C. T24S R1W S18 CS BT.

Note - Leave Orig. Stone in old corner locus. Old corner & all BT's. will be removed in construction. May 26, 1967

$\frac{1}{4}$ Corner to Sections 17 and 18.

Found - 1962 Co. Surv. Brass Cap & BT's., properly marked, See Ren. #24. Both Orig. BT's. now turned out & slid down very steep, southeast slope.

21" D. Fir N. 23° E. 24.0 ft., Alive, face pitched over.

New BT: 28" D. Fir S. 40° W. 44.8 ft. mkd: $\frac{1}{4}$ S18 CS BT.

Note - This corner lies on steep, S.E. slope. June 15, 1967

Section Corner to Sections 10 - 11 - 14 - 15.

Found - 16"xl0"xl0" Corner Stone mkd. with 2 notches on N. & r notches on south, firmly set.

Orig. 16", now 24" Pine, N. 39° E. 21.1 ft., alive, scribe visible on unhealed blaze. (Record calls for Fir N. 36° E.)

Orig. 10", now 13" Fir, S. $29\frac{1}{2}^\circ$ E. 17.8 ft., alive, shows scar. (Record bearing S. 34° E.)

Orig. 24", now 31" Fir, S. 5° W. 70.0 ft., alive, shows scar. (Record bearing S. 2° W.)

Orig. 12" (?), now 24" Pine, N. 51° W. 32.3 ft., now snag, scribe visible on unhealed blaze. (Record bearing N. $58\frac{1}{2}^\circ$ W.)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967

T 24 S R 1 W
S 10 S 11
S 15 S 14

(Reset Rock alongside)
New BT's: 8" Hemlock N. 40° W. 16.0 ft. mkd. T24S R1W S10 CS BT.
7" Hemlock S. 54° W. 24.8 ft. mkd. T24S R1W S15 CS BT.
16" Fir N. 49° E. 11.1 ft. mkd. T24S R1W S11 CS BT.

Note - This corner lies on steep, easterly slope. Oct. 12, 1967

Vernon "Ray" Tracy & Crew
May 26, 1967
C.S. file No. 52/42

70

71

72