

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

73

1/4 Corner to Sections 35 and 36.

Found - Orig. 18", now 34" Fir sawed stump, N. 75° E. 24.4 ft., open & find "BT" scribe & reverse.

No trace other Orig. BT now corner stone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T 24 S R 1 W S 35 S 36

New BT's: 14" Cedar N. 75° W. 21.5 ft. mkd. 1/4 S35 CS BT.

12" Hemlock Stump S. 31° E. 9.5 ft. mkd. 1/4 S36 CS BT.

No live trees east of line due to clear-cut logging.

Note - This corner lies on very steep, northerly slope, approx. 270 ft. south of Canton Creek.

Oct. 11, 1967

74

W.C. Sec. Cor. to Secs. 12 & 13, T24-1W. & Secs. 7 & 18, T24-1E.

Found - 16"x12"x12" Corner Stone mkd. with 2 notches on N. and 4 notches on S.

Orig. 14", now 17" Cedar Snag, N. 38° E. 5.9 ft. scribe "S R E S7" visible on unhealed blaze.

Orig. 36", now 42" Cedar, alive, S. 36° E. 16.5 ft., blaze unhealed, face decayed, no scribe.

No trace Orig. N.W. and S.W. BT's.

Since a new logging access road will be constructed through this corner locus, we run West 75.0 ft. & Set Witness Corner.

Set - Brass Cap at W.C. Mkd: Doug. Co. Surveyor's Office 1967 Wit Cor. T 24 S R 1 W S 12 S 7 S 13 S 18

New BT's: 10" Hemlock N. 54° W. 19.3 ft. mkd. W.C. T24S R1W S12 DCS BT.

10" Hemlock S. 37° W. 18.1 ft. mkd. W.C. T24S R1W S13 DCS BT.

Note - This Wit. Cor. is for Douglas-Lane County Line, 30 ft. west of Francis Creek, course S.E.

SEPT. 1969 - FOUND O.K. V.R.T.

Oct. 11, 1967

MICROFILM TO HERE

10/67

75

C1. Corner to Sections 18 and 19.

Found - Orig. 36" D.Fir, now Snag, N. 88° E. 68.0 ft., shows good scar. 16" D.Fir, now down, S. 30° E. 24.3 ft., scribe visible "S" and other marks, See Ren. #39.

Note - 1966 Brass Cap as recorded in Ren. #54, now buried under about 8' of fill. Area covered with logs to be yarded next week.

Do not set new brass cap as it will certainly be destroyed.

Set - 3/4" Iron Rod at corner.

New BT's: 26" D.Fir S. 35° E. 36.5 ft. mkd. T24S R1W S19 CC CS BT.

12" Cedar S. 8 1/2° E. 38.3 ft. mkd. T24S R1W S19 CC CS BT.

Note - No trees available to the north, clear cut unit.

This corner lies approx. 50 ft. W. of creek.

March 27, 1968

76

1/4 Corner to Sections 18 and 19.

Found - 14"x12"x8" Corner Stone, out of position due to S.W. Orig. bearing tree turning out. Stone mkd: "1/4".

Orig. 14" Fir, now 16" Snag, N. 68° E. 11.2 ft., Open & find "BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T24S R1W S 18 S 19

(Reset Orig. Cor. Stone alongside)

New BT's: 8" Hemlock N. 0 1/2° W. 14.9 ft. mkd. 1/4 S18 CS BT.

5" Hemlock S. 43° W. 38.5 ft. mkd. 1/4 S19 CS BT.

Note - This corner lies 35 ft. E. of small creek, course North.

April 2, 1968

77

Center of Section 10.

Set by intersecting staff compass lines, no chain.

12" Hemlock S. 3° E. 8.0 ft., scribed C 1/4 BT with tag.

Oct. 1966

Ronald L. Durham  
For Menasha Corp.  
C.S. File  
55/20  
SEPT. 68