

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

84

Wit. Corner to $\frac{1}{4}$ Corner to Section 18.
Corner Point falls on 30' high road backslope.
Set - 1" Iron Pipe with 3" Brass cap, 50 ft. due west
of true corner location, from which:
18" Madrone bears N.86°W. 37.1 ft. scribed: WC $\frac{1}{4}$ S13 BT.
30" D.Fir bears N.55°W. 21.9 ft. scribed: WC $\frac{1}{4}$ S13 BT.

Dennis O. Bryant
For: Wm. Ply. Co.
M 38 - 63

85

Center $\frac{1}{4}$ Corner Section 18.
Set - 5/8" Iron Rod with Alum. Cap, from which:
A 30" D.Fir bears N.32°46'E. 13.6 ft. scribed C $\frac{1}{4}$ S18 BT.
A 20" D.Fir bears N.80°22'W. 18.9 ft. scribed C $\frac{1}{4}$ S18 BT.
Nov. 1969

Township Corner: T 23 S R 1 W S 36 | S 30 R 1 E 86
T 24 S S 1 | S 6

Found - 1922 GLO Brass Cap on 3" I. Pipe, out of ground.
Orig. 14", now 22" Fir, alive, N.60°E. 17.8 ft., shows good scar, tagged.
Orig. 36", now 40" Fir, alive, S.40°E. 39.6 ft., shows good scar, "
Orig. 40", now 46" Fir, alive, S.34 $\frac{1}{2}$ °W. 31.0 ft., shows good scar, "
1922, 8" Fir, now 8" Snag, N.2°W. (Rec. N8W) 41.6 ft., scribe visible
on unhealed blaze.

Reset - G. L. O. BRASS CAP, in proper place.
New BT: 28" D.Fir North 44.5 ft. mkd: "T23SR1W S36 DCS BT".
This corner lies approx. 100 ft. W. of access road from China Creek,
on very steep, west slope.

4/15/70

87

Sec. Cor. to Secs. 33 & 34, T23-1W. and Secs. 3 & 4, T24-1W.
Found - No trace of corner stone.
Orig. 30" Fir, now decayed stump, N.38°E. 13.9 ft., with scribe vis.
Orig. 30", now 34" Fir, alive, S.27°E. 62.0 ft., shows good scar, we tag.
Orig. 30", now 34" Fir, alive, S.8°W. 23.1 ft. (Rec. 19.8) good scar, we tag.
Orig. 30", now 35" Fir, alive, N.2°W. 19.8 ft. (Rec. 23.1) opened, scribe
visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R1W S 33 | S 34
Office, 1970 T24S S 4 | S 3

New BT's: 6" D.Fir N.52°E. 21.4 ft. mkd: "S34 CS BT".
13" D.Fir N.62°W. 22.3 ft. mkd: "T23S R1W S33 CS BT".
This corner lies on very steep, southerly slope approx. 50 ft.
from S. edge of logging access road.

PD. OK
7/25/73
Y.R.T.

4/16/70

88

$\frac{1}{4}$ Corner to Sec. 35, T23-1W. and Sec. 2, T24-1W.
Found - Old Corner Stone, as called for, mkd: " $\frac{1}{4}$ ".
Orig. 7", now 30" Fir, alive, N.75°E. 20.5 ft., injury over the
old scar. We rescribe " $\frac{1}{4}$ S35 CS BT".
Orig. 8", now 32" Fir, alive, S.44°W. 16.5 ft., shows good scar.
We Rescribe " $\frac{1}{4}$ S2 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R1W $\frac{1}{4}$ S32
(Reset old Stone alongside) Office, 1970 T24S S 5

This corner lies 430 ft. E. of top of spur ridge, sloping S.W.
& approx. 1000 ft. W. of the old Bohemia jeep trail, we put line
tag on jeep trail.

4/17/70

89

$\frac{1}{4}$ Corner to Sec. 25, T24-1W. and Sec. 30, T24-1E.
Found - 1965 C.S. Brass Cap, out of ground, See Ren. #46.
Old Corner Stone, in place.
Orig. 10", now 18" Fir, alive, S.28 $\frac{1}{2}$ °E. 26.4 ft. "4" scribe
visible on blaze, we open in 1965.
Orig. 30", now 37" Fir, alive, N.49°W. 38.3 ft., shows good scar,
broken off about 60 ft. high.
9" Yew, alive, S.21°E. 19.7 ft., scribe O.K., blaze split.
Reset - 1" I. Pipe & Brass Cap at Corner & Reset old Corner Stone
Alongside.

New BT's: 18" Cedar S.18°W. 20.4 ft. mkd: " $\frac{1}{4}$ S25 DCS BT.
16" Cedar S.44°E. 33.2 ft. mkd: " $\frac{1}{4}$ S30 DCS BT.
This cor. lies on N-S cutting line, unit in Sec. 25 & about 400 ft.
North of Chilcoot creek.

5/12/70

Vernon "Ray" Tracy
- C.S. File No. 54/27

FIELD NOTES
SMY
2 BUT CASE
15 FOR
35
2