

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Vincent Perron C. S. File No. 54/27

101
 $\frac{1}{4}$ Corner to Sections 29 and 32.
 Found - 1960 C. S. Brass Cap, bent over, See Ren. #1.
 11" Hemlock N.1°W. 27.1 ft., alive, shows scribe on healing blaze.
 Orig. Cedar, down. No trace of other BT's.
 RESET - Brass Cap & Set 6' Steel Fence Post alongside. #155
 New BT: 6" Hemlock S.86°W. 40.8 ft. mkd: " $\frac{1}{4}$ S32 CS BT".
 This corner lies on E-W cutting line, Section 32 is clearcut.

102
 $\frac{1}{4}$ Corner to Sections 31 and 32.
 Found - Corner Stone mkd: " $\frac{1}{4}$ " on W. face.
 Orig. 10", now 24" Fir, alive, N.52°W. 11.2 ft., shows scars. #146
 We Rescribe " $\frac{1}{4}$ S31 CS BT".
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 1 W
 (Reset old stone alongside) Office, 1970 $\frac{1}{4}$ S 31 | S 32
 New BT: 42" Fir Stump N.11°E. 57.1 ft. mkd: " $\frac{1}{4}$ S32 CS BT".
 There are no trees east of line.
 This corner lies on very steep, S.E. slope on N-S cutting line, S.32 clearcut.
 5/27/70

103
 $\frac{1}{4}$ Corner to Sections 32 and 33.
 Found - 1961 County Brass Cap, in place, See Ren. #9.
 7" D.Fir N.70°E. 19.7 ft. mkd: " $\frac{1}{4}$ S33 CS BT", alive & good condition
 with blaze healing over.
 No trac of N.W. BT. due to logging in area.
 New BT: 7" D.Fir N.18°W. 32.0 ft. mkd: " $\frac{1}{4}$ S 32 CS BT".
 This corner lies on steep westerly slope about 500 ft. East of Scaredman
 access road.
 5/28/70

104
 Witness Corner to Sec. Cor. to 28 - 29 - 32 - 33. #144
 Found - No trace of 1960 County Brass Cap or BT., See Ren. #2.
 Orig. 14", now 20" Pine, good condition, N.60°E. 21.1 ft., Alive.
 Orig. 6" Pine, now 15" Snag, S.28°E. 16.5 ft., scribe visible.
 Other Orig. BT. down.
 Drive 3/4" Iron Rod on very steep, cut bank & measure 60 ft. W. to West
 shoulder of new logging road and Set Witness Corner, as follows:
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 1 W
 (Set 6.0 ft. Steel Fence Office Wit. S 29 | S 28 60' E.
 Post Alongside) 1970 Cor. S 32 | S 33 to Cor.
 New BT's: 10" Pine N.76°W. 15.3 ft. mkd: "WCT24SR1W S29 CS BT".
 11" D.Fir N.37°E. 31.4 ft. mkd: "WCT24S RLWS29 CS BT".
 Road bears N.55°E.-S.55°W. No other trees available.
 5/28/70

105
 $\frac{1}{4}$ Corner to Sections 20 and 21.
 Found - 1961 County Brass Cap, in place, See Ren. #8.
 Orig., now 38" Fir N.14 $\frac{1}{2}$ °W. 29.0 ft., alive, shows scar.
 Other Orig. BT. gone.
 10" Hemlock, alive, N.8°E. 13.0 ft., blaze healing.
 The Yew BT. to N.W., now broken off just above "BT" scribe.
 New BT: 15" Hemlock S.82°W. 43.3 ft. mkd: " $\frac{1}{4}$ S20 CS BT".
 This corner lies approx. 500 ft. E. of Scaredman Access Road & at S. W.
 corner of cutoff unit in Section 21.
 5/28/70

106
 $\frac{1}{4}$ Corner to Sections 13 and 14.
 Found - Corner Stone, in place, with only partial chisel marks on W. side.
 Orig. 36", now 40" Fir, alive, N.33°E. 58.1 ft., shows good scars.
 Orig. 30", now 38" Fir, alive, N.10°W. 18.5 ft., shows good scars.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 1 W
 (Reset Stone Alongside) Office, 1970 $\frac{1}{4}$ S 14 S 13
 New BT: 13" Cedar N.53°E. 23.0 ft. mkd: " $\frac{1}{4}$ S13 CS BT".
 This corner lies on very steep, East slope in old growth timber.
 6/1/70

MIS-NUMBERING ERROR IN 1970- NUMBERS 107 & 108
 VOIDED - NOT USED.
 10/83 J.R.