

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

109

1/4 Corner to Section 16 and Section 21.
Found - Orig. 45", not 54" Fir, S. 21° E. 8.6 ft., shows good scar.
We do not open.
Orig. 6", now 18" Down Pine, we open & find good scribing N. 42° E. 33.0 ft.
Rock, out of ground, which checks record size, no marks found.
Near Corner.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 1 W
Office 1/4 S 16
1970 S 21
New BT's - 12" Hemlock bears S. 84° E. 38.0 ft. scribed "1/4 S21 CS BT".
24" Doug. Fir bears N. 4° E. 49.0 ft. scribed "1/4 S16 CS BT".
8/14/70

James W. Byron
County Surveyor
V. Perron C.S. 54/27

110

Center 1/4 Corner, Section 28
Set - 2 1/2" Aluminum cap
BT's - 18" Hemlock, S. 37 1/2° E. 17.6 ft.
30" D. Fir, S. 57° W. 5.8 ft.
8" Hemlock, N. 11° 30' W., 38.7 ft.
Oct. 1972

Thos. E. Shrum Jr
For: Menasha Corp.
October, 1972
M 50 - 44

111

1/4 Corner for Sections 14 and 15
Found - A stone, 16"x12"x10", loosely set, with a faint "1/4" chiseled
on a face, pointing generally west.
Also find - A 30" now 32" D. Fir showing a good scar. Since it appears
that the orig. stone has been disturbed, we open the BT &
find good scribing.
At the corner point as determined at record bearing and distance from the
only remaining bearing tree, A 30" now 32" D. Fir bearing S. 41° E., 17.2 ft.
we set: A brass cap, flush with the ground mkd:
COUNTY SURVEYORS T 24 S
OFFICE S 15 | S 14
1974 1/4
R 1 W

Gary Langlitz, Surveyors Office
Peter Earle
Clell Goodwin
C.S. 56/51
June 17, 1974

112

Center 1/4 Corner for Section 6.
Set - 1" x 30" I.P.
New BT's - 2" Fir, N. 6° E., 5.3 ft. Scribed C 1/4 S6 BT.
3 34" Fir, S. 3° W., 21.0 ft. Scribed C 1/4 S6 BT.
8" per 243-2

Donald Peel
For: Weyerhaeuser Co
Nov. 1975
RM 3 - 2

113

Section corner for Secs. 14, 13, 23 and 24
Found - 1966 County surveyors office brass cap laying on ground. Ren. #56
An orig. 8" now 16" Fir, N. 26° E., 17.2 ft. alive & well healed.
Lower part of tree cut into.
An orig. 8" now 17" Fir, S. 48° E., 13.9 ft. alive & well healed/
An orig. 30" now 33" Fir snag S. 53° W., 17.8 ft. Visible "T24 R1
S T" on unhealed blaze.
A 8" now 10" D. Fir, S. 50° W., 11.0 ft. Visible "4 1 2 C B"
in good blaze.
Intersected dist. and bearings of the 5 BT's:
Set - At true corner point, the 1966 DCSO Brass cap in mound of stone
4 ft. wide at base and 14" high, stamped "1976 above 1966 at
bottom.
New BT - A 13" D. Fir bears N. 29° W., 32.4 ft. scribed "T24S R1W S14 CS BT" in double
blaze.
Note: Corner lies approx. 300 ft. west of top of N-W ridge. Cor.
also lies approx. 90 ft. west of Rd. #24-1-11.
Compass declination 20° east.

M. Lenora Ladig, Surveyor's Office
Pete Earle
D. Stewart
April 13, 1976
C.S. 59/8

4/13/76

RE-RENEWED, SEE CORNER NO. #131
RE-RENEWED, SEE CORNER NO. #137
RE-RENEWED, SEE CORNER NO. #149