

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21951

128

1/4 Corner for Sec. 24 and Sec. 19 of T.24-1E. Ren. #45
Found - 1965 County Surveyors Office Brass cap torn out of the ground,
properly stamped. While digging to Re-Set brass cap, the orig.
corner stone was found buried upside down, marked "1/4"
Orig. 31" now 36" D. Fir (DBH on high side) bears S.15°W., 10.6 ft
Has a healed blaze and BLM BT sign.
23" D. Fir set in 1965 bears S.82°E. (to base of tree which is
leaning slightly downhill) 24.6 ft. Partly healed blaze with
scribing visible "S19B". Also has BLM BT sign.
Placed County BT signs on both trees. The orig. NE BT is down.
Set - Using both the orig. and the 1965 bearing trees for reference
I Re-set the 1965 brass cap and stamp it "1977".
No new accessories.

9/9/77

129

1/4 Corner for Sec. 13 and sec. 18 of T24-1E.
Found - After a thorough search, did not find the original corner stone.
Orig. 36" Fir is now a 31" snag, 20 ft. high. bears N.25°E.,
31.02 ft. open & find scribing "1/4 S BT".
The orig. 60" Fir has fallen & slid downhill approx. 100 ft. No
scar visible. Stump hole bears S.52°W., 64.68 ft.
Set - Using the orig. BT snag for reference, I SET a 2 1/2" brass cap
on a 1" I.P. at corner point stamped: County Surveyor's Office
T 24 S 1/4 RLW S13 S18 R1E 1978.
BT's - A 18" D. Fir bears N.34°E., 35.0 ft. scribed "1/4 S18 CS BT" on
a double blaze.
A 12" D. Fir bears N.11°30'W., 16.2 ft. scribed "1/4 S13 CS Bt"
on a double blaze.
Placed County BT signs on two new BT's & on orig. BT snag.
Corner falls on a 75% South slope.

5/4/78

130

1/4 Corner for Sec. 32 and Sec. 5 of T25-1
Found - A 1" x 30" I.P. lying on the ground out of position with bras
cap attached marked County Surveyor's Office T24S 1/4 S32 S5
RLW T25S 1966. Ren. #61
An orig. 14" R. Cedar, now a 17" shattered stob, 3 ft. tall
scribing "4S" visible on previously opened blaze on downed
portion of the tree located down hill from the shattered stump,
bears N.43°W., 5.3 ft.
An orig. 36" D. Fir, now 40" and uprooted with well healed blaze,
stump hole bears approx. S.74°E., 18.5 ft.
A 6" now 7" Hemlock, blown down but still alive with scribing
"1/4 S32 CS BT" visible on unhealed double blaze, bears
N.56 1/2°W., 26.7 ft. (Rec. N.52°W., 26.7 ft.).
A 5" now 6" Hemlock, alive with scribing "1/4 S 5 CS BT" visible
on unhealed double blaze, bears S.44 1/2°E., 32.5 ft. (rec.
S.49°E., 32.5 ft.)
Set - At a location which agrees with the measurements listed for the
previously described corner accessories, WE RESET the 1966
County Surveyors brass cap 28" in the ground on a steep
North slope and add the markings "Reset 1978" to the brass
New Accessories:
A boat spike marked "BT 1" set near the heart on top of a 54"
S. Pine stump bears S.87°W., 32.3 ft.
Corner is located in cut-over area.

5/1/78

131

1/4 Corner for Secs. 16 and 21.
Found - A basalt stone 12" x 8" x 8" with no marks at approx. cor. location
A 1" x 36" I. Pipe with brass cap marked County Surveyor Office
1/4 T24S S16 S21 RLW 1970., lying on the ground near cor. #109
An orig. 54" diam. fir, now a 45" diam., 3 ft. high stump bears
S.21°E., 8.6 ft. dist. shows a good scar and has been capped.
An orig. 6" Pine now 17" and down, root hole bears N.42°E., 33.0 ft
partially opened blaze reveals "BT".
A 12" Hemlock, now 14" with visible scribing "4 S21 CS BT" in
double blaze bears S.84°E., 37.5 ft. dist. (Rec. 38.0 ft.)
A 24" fir, now 26" 4 ft. high stump with visible scribing "1/4 S16
CS BT" in a partially healed double blaze. bears N.3°E., 49.0 ft.
(Rec. N.4°E. Ren. #109).

CONT. NEXT PAGE - - -

Dennis Gaylord U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Sept. 9, 1977
C.S. 59/40
Witness: Travis Worthen

Dennis Gaylord
U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Roland Simshauser
May 4, 1978
C.S. 60/11

Gary L. Langlitz
Doug. Co. Surveyors
Office
Frank C. Silagy
May 1, 1978
C.S. 60/11

K. Reed; Doug. Co.
Surveyors Office
P. Earle; F. Silagy
Oct. 15, 1979
C.S. 60/34

1-79