

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24 T. S. R 1 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21001

131

C O N T. - - -
Karen Reed, Doug. Co.
Surveyors Office
P. Earle
F. Silagy
Oct. 15, 1979
C.S. 60/34

Set - Reset 1" x 36" I. Pipe with brass cap at record bearing and dist. from orig. stump (S.21°E., 8.6 ft.) and mark "Reset 1979" on cap. Place stone north side of cap.
New Accessories:
A 48" sugar pine scribed "1/4 S21 CS BT" in a double blaze bears S.86°W., 115.1 ft. dist.
Set boat spike on northerly side of tree marked "DCSO" Measurement taken to B.S. Also center of tree.
Corner on east slope of spur in clearcut

10/15/79

132

Howard Johnstone
LS#498
For: Rsbg. Lmbr.
Co.
May 1980
M 83 - 62

Section Corner for Sections 8,9, 16 and 17
Fd - A 1/2" Iron pipe in rock mound. (Unrecorded)
A original 14" dia. Hemlock, now 30" dia. bears N.38°E., 4.0 ft.
A original 6" dia. Fir, now 18" dia. bears S.60°E., 19.1 ft.
A original 6" dia. Fir, now 8" stump bears S.24°W., 17.2 ft.
A original 6" dia. Fir, now 20" dia. bears N.58°W., 14.5 ft.
Set - A 5/8" x 30" Iron rod and alum. cap.

Glenn Baughman
For: U.S. Forest
Service
Oct. 1980
C.S. 58/229

1/4 Corner for Sec. 36; and Sec. 31 of T.24-1E.
Found - A 30" D. Fir stump, orig. BT. I opened to find scribe marks "BT" bears N.55°W., 12.5 ft.
A 26" D. Fir, orig. BT. I opened to find scribe marks "4S" bears S.26°E., 21.8 ft. (Rec. N.26°E.)
Set - A 2 1/2" x 30" iron pipe in the ground in a 3 ft. diam. mound of stone with a 3" brass cap marked: T24S 1/4 RLW S36 S31 R1E 1980 LS 536.
New BT's- A 11" D. Fir bears N.38°E., 33.6 ft. marked "1/4 S31 BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.
A 13" D. Fir, bears N.11°W., 59.9 ft. marked: "1/4 S36 BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.

10/80

134

Steven Ness
For: Guistina Bros. Lbr.
d Doug. Co. Lbr.
Witness: David Taylor
Oct. 29, 1980
M 86 - 10
C.S. 58/245

1/4 Corner for Sec. 7 and Sec. 12 of T.24-2.
Found - No evidence found. A thorough search for evidence was made after the proportional position was determined. No evidence was found of the two line trees called, nor were any original blazes found along the line. As mentioned in my survey, topographic calls were of no help in determining the corner's position.
Set - 5/8" x 30" iron pin with unmarked 2" alum. cap. The pin is set 6" into rock. The monument is about 24 ft. above the base of a rock bluff. The position was determined by proportion.
New BT's- A 40" D. Fir, bears N.52 1/2°E., 62.8 ft.
A 4" Yew bears S.41°E., 38.1 ft.
Both BT's marked 1/4 S7 BT.

10/29/80

135

Thomas E. Shrum Jr.
For: Champion
International
Nov. 1980
M 84 - 55

1/4 Corner for Sections 9 and 16
Set - Alum. cap in 1979 (no previous record)
Found - B.T., Original
16" D. Fir bears S.79°W., 16.5 ft.
6" Fir snag, bears N.37°E., 9.2 ft.

11/80

Glen Mc Chesney
For: Weyerhaeuser Co.
March 10, 1980
C.S. 58/8

Township corner for Sec. 6; and Sec. 1 of T.24-2; Sec. 31 of T.23-1 and Sec. 36 of T.23-2
Found - 1964 BLM brass cap not disturbed by adjacent timber felling.
50" Fir stump, S.48°E., 22.0 ft. to face, 24.0 ft. center measurement; no scribing found.
36" Hemlock, S.38°W., 18.0 ft. to face. 19.3 ft. center measurement; scribing visible on mostly healed face.
32" White fir snag, N.66°W., 20.8 ft. to face, 21.9 ft. center measurement; scribing, extremely fine, on round surface of tree, not on a flat face.
18" White fir, N.34°E., 30.7 ft. center measurement; scribing visible.

136