

Douglas County Surveyor's Record of
Government Corners Renewed

T 24

T. S. R 1

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Larry E. Monrean, Deputy Douglas Co. Surveyors Office

Sept. 30, 1983

J. Powell

Sept. 28, 1983

J. Powell and J. Lundeen

C. S. 62/9

Larry E. Monrean, Deputy

Doug. Co. Surveyors Office

Randall Smith

Oct. 18, 1983

C.S. 62/7

(Note: Cor. lies on steep northwesterly slope approx. 200 ft. easterly of the end of BLM Rd. #25-1-5.4. Cor. lies in cutting lines. Clear cut NW of corner.)

1/4 Corner for Secs. 27 and 28.

143

Found - 1" x 1" chisled "+" and "1/4" on top of a boulder
18' x 6' x 6' above ground. Original notes call chisled "+" 1/4" on west face of boulder 6' x 6' x 6' above ground.
Orig. 60" fir with well healed blaze bears N.40°E., 19.8 ft.
(M 50-44 shows 30 ft. This probably mistaken for 30 links per original.)
Orig. 6" chinquapin not found.

New Accessories:

12" fir, double blazed and scribed "1/4 S27 CS BT" bears S.58 1/2°E., 17.7 ft.
Set a 1/2" x 8" spike in top of an 18" hemlock stump, bears N.73 1/2°W., 39.1 ft. Spike set through a Douglas County Surveyors Office bearing tree tag.
Set a 1/2" x 8" spike in top of a 20" hemlock stump bears S.41 1/2°W., 60.3 ft. Spike set through a Douglas County Surveyors Office bearing tree tag.

Note: Corner is on a north slope in a N-S cutting line, clear cut to the west.

Section corner for Sections 28, 29, 32 and 33.

144

(Did not find County cap per Ren. #2 or 3/4" I.rod per Ren. #104).

Found - Orig. 6" pine, now 18" stump with the lower portion of Byron's rescribing visible. (Rec. S.28 1/2°E., 25 lks.)
Orig. 6" pine (rec. N.39°W., 44 lks.) falls in road bed. Gone.
Orig. 6" pine (Rec. S.42 1/2°W., 15 lks.) Gone.
Orig. 14" pine (rec. N.60°E., 32 lks.) Gone, down and across road.

Byron's 15" pine (Rec. S.54°W., 27.9 ft.) lying dead on edge of bank.

1970 County Surveyors brass cap for witness corner marked T24S Wit. Cor. S29 S28 S32 S33 60 ft. E to cor. RLW 1970, bears S.89°W., 60 ft. from corner. (Rec. West, 60 ft.).

10" pine, now snag, bears N.76°W., 14.5 ft. (15.3) from W.C.

11" D. fir, now snag, bears N.38 1/2°E., 31.3 ft. (31.4) from W.C.

Set - Using found orig. 6" pine (now 18" stump), we pull record S.28 1/2°E., 16.5 ft. and set brass cap in drill hole flush with rock on a steep cut bank. Material will slough off bank and cover cap. (BLM notified us in 9/83 that they disagree with the record bearing from the corner to the W.C. We find that the W.C. is S.89°W., 60 ft. from corner.)

New Accessories:

Boat spike in 48" fir stump bears S.76°E., 34.5 ft.
Boat spike in 14" white pine stump, bears N.20°W., 53.6 ft.

Section corner for Secs. 30, 29, 31 and 32.

145

Found - 1960 County brass cap on iron pipe, properly mkd., protruding 6 inches above ground. Ren. #3

Orig. 10" fir, now 12" downed fir, root crown bears N.62°E., 12.5 ft. well healed blaze.

Orig. 8" fir now 12" dia. 7 ft. high stump bears S.69°E., 9.5 (Rec. S.75°E., 9.2 ft.) Partially healed blaze, scribing legible (1, S, 3)

Orig. 8" fir now 8' dia. 4 ft. high stump bears S.17°W., 8.5 ft. (Rec. S.26°W., 8.6 ft.) Scribing legible (24 S, RLW, S31 BT)

Orig. 8" fir now 2 stumps, are close to bearing and dist. (Rec. N.83°W., 19.8 ft.)

A 12" fir, now 12" fir, bears N.29°E., 53.0 ft. Double blaze nearly healed. Ren. #3

18" fir, now 15" dia. snag, 15 ft. high, bears S.81°W., 22.3 ft. Partially healed blaze, scribing visible. Ren. #3

8" fir destroyed.

New Accessories:

9" fir, double blazed & scribed "T24S RLW S29 CS BT" bears N.83°E., 57.2 ft.

14" fir, double blazed & scribed "T24S RLW S31 CS BT" bears S.22°W 42.0 ft.

Set a 8"x 1/2" spike in a 18" fir stump, bears N.86°W., 19.1 ft. Spike set through a "Doug. Co. Surveyors Office" bearing tree tag in center of stump (stump is possible orig. 8" fir BT)

10/18/83