

Douglas County Surveyor's Record of
Government Corners Renewed

T 24

T. S.

R 1

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

154

Section Corner for Sections 7 and 18; and 12& 13 of T.24-2
CONDITION REPORT ONLY

- Found - A 2½" brass cap on an iron pipe set approx. flush with ground.
(1969 County cap Ren. #81)
- Orig. BT, a 24" fir now 30" dia. 1½ ft. tall stump with no bark
scribing visible bears N.75°E., 17.9 ft. dist. (Rec. N.75°E
17.2 ft. probable face measurement)
- Orig. BT, a 30" fir now a 36" dia. 3½ ft. tall fir stump with
no bark scribing visible bears S.81°E., 20.7 ft. (Rec. S.81°E.,
19.8 ft. probable face measurement)
- Orig. BT, a 32" hemlock now a 38" DBH hemlock with illegible
scribing visible in a partially healed single blaze bears
S.79°W., 30.4 ft. (Rec.S.75°W., 30.4 ft.)
- Orig. BT, a 20" fir now a 20" dia. 1½ ft. tall rotted fir stu
with no bark scribing visible bears N.59°W., 35.3 ft.
(Rec. N.61°W., 33.0 ft.)
- A 10" hemlock now an 11" DBH 6 ft. tall metal capped hemlock
stump with the scribing 24S R2W S12 CS BT visible in a partially
healed single blaze bears N.6°W., 22.3 ft. (as per rec. Ren.81
- A 22" hemlock now a 22" 4½ ft. tall metal capped hemlock stump
with the scribing t24S R1W S18 CS BT visible in a partially
healed single blaze bears S.43°E., 59.5 ft. Ren. No.81
(NE bearing tree gone due to a road work)

No suitable line trees nearby. All foundstumps are in good condition except
one rotted stump as noted. Cap lies on steep northerly slope above cut
bank for logging spur road.

Douglas County
Surveyors Office
Stephen Flause
Terrie Frannsen
Nov. 8, 1990
C.S. 64/11

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Oct. 3 1996
C.S. File 65/9-20

155

1/4 Corner for Sections 29 and 32

Found - 2½" dia. brass cap on a 1½" O.D. iron pipe, protrudes 14"
above ground. See renewal #1

Accessories Found -

No O.B.T.'s Found.

SE BT from ren. #1 not found.

11" now 10" dia. 7 ft. high Hemlock stump, with a partially
healed blaze, scribing visible "¼ S29 CS BT" bears N.1°W.,
27.1 ft. (agrees with rec.) Ren. #1

8" now 19" dia. Hemlock, with a fully healed single blaze,
bears S.86°W., 40.8 ft. (agrees with rec.) See ren. #101

New Accessories -

11" D.Fir, double blazed and scribed "¼ S32 CS BT" bears
S.15½°W., 16.7 ft.

7" D.Fir, double blazed and scribed "¼ S29 CS BT" bears
N.70°W., 9.7 ft.

6" D.Fir, double blazed and scribed "¼ S29 CS BT" bears
N.50½°E., 53.2 ft.

Note - Corner lies approx. 25 ft. west of a gravel road.

1/4 Corner for Sections 27 and 34

Found - 2½" brass cap on a 1½" O.D. iron pipe, protrudes 12" above
ground. (DCSO) See renewal # 30

A 15" x 11" x 8" stone marked "1/4" 4 ft. down hill,
southeasterly of BC/IP out of ground.

Accessories Found -

10" now 21" dia. rotted 2 ft. high D.Fir stump with a healed
blaze. Bears N.46°E., 10.6 ft. (agrees w/orig rec.) O.B.T.

Orig. SE BT not found.

Monument Set - Orig. stone is placed along southerly edge of BC/IP.

New Accessories -

6" dia. D.Fir, double blazed and scribed "¼ S34 CS BT" bears
S.32½°W., 30.2 ft.

9" dia. Hemlock, double blazed and scribed "¼ S34 CS BT"
bears S.26°E., 35.2 ft.

3" dia. D.Fir, double blazed and scribed "X BT" bears
N.50°E., 17.9 ft.

6" dia. Chinquapin, double blazed and scribed "¼ S27 CS BT"
bears N.70½°W., 28.3 ft.

Note - Corner lies on a steep southeasterly slope.

156

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Oct. 28, 1996
C.S. File 65/9-21