

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21081

Dennis O. Bryant
For: Winchester
Plywood
C.S. File
No. 55/55

39

$\frac{1}{4}$ Corner to Sections 24 and 25.
Locate a basalt Stone with two chisel marks from which:
14", now 40" Madrone(Laurel) bears N.78°30'E. 6.6 ft.
14", now 22" Madrone(Laurel) bears S.78°W. 8.6 ft.
I set a 1" diam. Iron Bolt from which:
Marked: 7" DBH D. F. " $\frac{1}{4}$ " S25 BT" which is S. 45°E. 6.3 ft.
11" DBH D. F. " $\frac{1}{4}$ " S24 BT" which is N. 45° E. 25.8 ft.

Note - See Search by Tracy C.S. 52/42.

Nov. 1967

40

$\frac{1}{4}$ Corner to Sec. 7, T24-2W. & Sec. 12, T24-3W.
Found - 1" Alum. Pipe set at corner point, See Ren. #19.
14" Hemlock, now stump, S.61°E. 60.2 ft. with "W" nail & tag.
62" Fir, now stump, N.57°W. 112.0 ft. (Rec.102.9) with "W" nail
& tag, dist. on tag was changed since being recorded.
Orig.24", now 34" Hemlock, down, N.40°E. 19.8 ft., prev.opnd.& shows scribe.
Set - Brass Cap at Cor.Mkd: County Surveyors R T 24 S R
(Reset Alum.Pipe alongside) Office, 1968 3W $\frac{1}{4}$ S 12 | S 7 2W
New BT's: 11" Hemlock N.11 $\frac{1}{2}$ °E. 54.2 ft. mkd. $\frac{1}{4}$ S7 CS BT.
11" Hemlock Stump N.68°W. 19.2 ft. mkd. " $\frac{1}{4}$ " S12 CS BT.

Note - This corner lies 10 ft. S. of old Cat. Logging Road in cut off area.
3/4/68

41

Section Corner to Secs. 18 & 19, T24-2W. and Secs. 13 & 24, T24-3W.
Found-1" x 30" Alum.Pipe & BT's/ as recorded in Ren. #45, Pipe bent over
under log.
REN #31-T 24-2 T24-3W

Orig.30", now 44" Cedar S.30°W. 26.4 ft., axe notch on reverse face.
(Rescribed "T24S R3W S24 66 BT")

Orig.20", now 42" Cedar N.82°E. 15.2 ft., open & find "B/" scribe.
(Rescribed "T24S R2W S18 CS BT")

No trace Orig. N.W. BT., S.E. BT., down.

36" Hemlock Stump N.88°W. 25.3 ft. (to "W" nail). We mark "T24SR3WS13CSBT"
68" D.Fir Stump N.28°E. 35.9 ft. (to "W" Nail). This area clear cut,
No live trees.

Set - Brass Cap at Cor. Mkd: County Surveyors R T 24 S R
(Reset Alum.Pipe alongside) Office 3 S 13 | S 18 2
1968 W S 24 | S 19 W

Note - This corner lies 20 ft. S. of Cat. Logging Road, Course N.W.

42

$\frac{1}{4}$ Corner to Sec. 19, T24-2W. & Sec. 24, T24-3W.
Found - $\frac{1}{2}$ " I.P. set at corner & "W" method BT, unrecorded.
Orig.12", now 14" Hemlock S.35°E. 15.8 ft., now down & out of position,
we find probable Stump Hole, face rotted, no scribe.
Orig.12", now 14" Hemlock, S.88°W. 17.2 ft., now stump, leaning,
"BT" scribe visible on previously opened blaze.
"W" BT: 30" D.Fir Stump S.48°W. 15.0 ft., "W" nail & tag,
we mark " $\frac{1}{4}$ " S24 CS BT".

Set = Brass Cap at Cor. Mkd: County Surveyors R T 24 S R
(Reset I.P. alongside) Office, 1968 3W $\frac{1}{4}$ S 24 | S 19 2W
New BT: 20" Cedar Stump S.28°E. 40.1 ft. mkd. " $\frac{1}{4}$ " S19 CS BT".

Note - This corner lies on moderate N.W. slope changing to very
steep N.W. slope.
3/6/68

43

Cl. Corner to Sections 18 & 19, T24-1W.
Found - Orig. 36" D.Fir, now Snag, N.88°E. 68.0 ft., shows good scar.
16" D.Fir, now down, S.30°E. 24.3 ft., scribe visible & other marks.
1966 Brass Cap, See Ren. #36, now buried under about 8' of fill.
Area covered with logs to be yarded in a week.

Do not set new Brass Cap as it would certainly be destroyed.

Set - $\frac{3}{4}$ " Iron Rod at corner.

New BT's: 26" D.Fir S.35°E. 36.5 ft. mkd. T24S RLW S19 CCCS BT.
12" Cedar S.8 $\frac{1}{2}$ °E. 38.3 ft. mkd. T24S RLW S19 CC CS BT.

Note - No trees available to the N., clear cut unit.
This corner lies approx. 50 ft. W. of Creek.

3/27/68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March, 1968
C. S. File No. 54/27