

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21981

N. W. Corner Tract #39.
Found - Cadastral Brass Cap, bent over & buried.
Reset in proper place from BT's., as follows:
9", now 10" Sugar Pine N. 34 1/2° E. 35.0 ft., alive, scribe visible on partially healed blaze.
15" Fir, now shattered stump, S. 39 1/4° E. 40.9 ft., scribe visible.
New BT: 8" D. Fir S. 63° E. 42.5 ft. mkd. TR.39 S35 CS BT.
Note - This corner lies approx. 350 ft. N. of Twin Cedar Springs Road on section line between sections 34 and 35.

44

C. S. File No. 54/27

3/12/68

Southeast Corner of Section 36, T23-3W.
Found - 1/2" I.P. "W" method., See C.S. File No. 53/107.
Orig. 26" Now 42" Fir Stump, N. 45° W. 8.6 ft., old bark scribe visible in poor condition. Also "W" Nail.
40" Fir Stump N. 47° E. 13.7 ft., "W" Nail & Tag. R R
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 S 36 2
(Reset I.P. alongside) Office, 1968 T24S W W
New BT: 60" Fir Stump N. 47° W. 26.1 ft. mkd. T23S R3W S36 CS BT.
Note - This corner lies on SE. slope on top of cut bank of old cat road in logged-off area.

45

Closing Corner to Sec. 31, T23-2W. & Sec. 6, T24-2W.
Found - 1/2" Tubing at corner & 1/2" I.P. for marker with Orig. BT's., & "W" method BT., as recorded in Ren. #3, T23-2W., C.S. 53/106.
Orig. 16", now 24" Cedar Stump, 5' high, N. 10° E. 27.7 ft., scribing visible on nearly healed blaze.
Orig. 60" Fir, now 64" Stump, 2 ft. high, S. 57° E. 25.1 ft., top of blaze visible on top of stump.
26" Hemlock Stump S. 50° W. 18.1 ft., "W" Nail & Tag.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R3 C S 31 R2
(Reset 1/2" Tube alongside) Office, 1968 T24S W C S 6 W
New BT: 9" Cedar Snag N. 44° E. 28.9 ft. mkd. T23S R2W S31 CC CS BT.
Note - This corner lies on E. side of spur, ridge sloping south about 50 ft. E. of top.

46

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April, 1968
C. S. File No. 54/27

Closing Corner to Sec. 1, T24-3W. & Sec. 6, T24-2W.
Found - 1/2" I.P. at corner & "W" BT's. as rec. in Ren. #39, T24-3W.
Orig. 18", now 20" Yew, alive, S. 30° W. 39.0 ft., scribe marks visible on old blaze. Rescribe: "T24S R3W S1 CC CS BT".
Orig. 60" Fir, now 62" Stump, slightly out of position, S. 70° E. 37.0 ft., shows good scar. No trace N.W. Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R C.C. R
(Reset I.P. alongside) Office, 1968 T24S 3W S 1 S 6 2W
New BT: 14" Yew S. 50° E. 54.8 ft. mkd. T24S R2W S6 CC CS BT.
Note - All "W" BT's., now stumps. No other trees suitable for BT's.
This corner lies on bench sloping S.W. in logged-off area.

47

1/4 Corner to Sections 13 and 24.
Found - Locate a pile of Stone and two original BT's., as follows:
18", now 30" Hemlock bears S. 63° W. 16.5 ft.
30" D. Fir, now a snag, bears N. 55° 30' W. 21.78 ft.
Set - 1" Iron pipe with Brass Cap in mound of stone.
Establish one New BT: 8" Hemlock bears N. 25° E. 8.5 ft. mkd: "1/4 S S13 BT".
7-12-68. Found O.K. VRT. June, 1968

48

By: Dennis O. Bryant
For: Win. Plywood
C.S. 55/55

Section Corner to Sections 14 - 15 - 22 - 23.
Found - 2" Iron Pipe & BT's., as recorded in Ren. #5.
28", now 29" Hemlock, alive, S. 56 1/2° E. 77.9 ft., scribe visible on unhealed blaze.
30", now 31" Cedar, alive, S. 15° W. 15.8 ft., scribe in poor condition. Rescribe "T24S R2W S22 CS BT".
12" Yew, alive, N. 70° W. 75.4 ft., scribe visible on unhealed blaze.
No trees available to N.E.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office S 15 S 14
1968 S 22 S 23
This corner lies 50 ft. N. of small creek 3 ft. wide, course S. 60° W.

49

V. Tracy & Crew
July, 1968
C. S. File No. 54/27