

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21001

1/4 Corner to Sections 2 and 11. 55
Found - Orig. 24", now 40" Hemlock, alive, S. 52°W. 17.2 ft., open
and scribe visible.

No trace of Vine Maple Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office 1969

1	S	2
4	S	11

New BT's: 9" Hemlock N. 56°W. 69.9 ft. mkd: "1/4 S 2 CS BT".
13" Hemlock S. 42°E. 45.0 ft. mkd: "1/4 S 11 CS BT".
This corner lies on south edge of west end of new jeep road.
7/18/69

C.S. File
No.
54/27

1/4 Corner to Sec. 3, T24-2W and Sec. 34, T23-2W. 56
Found - Corner Stone with partial "1/4", "4" chipped off & 1894 BT's:
Orig. 20", now 30" Hemlock, alive, S. 76 1/2°E. 12.5 ft., shows good scar.
Orig. 18", now 22" Hemlock, dead, N. 4°W. 5.3 ft., scribe visible on
unhealed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W 1/4 S 34
(Reset stone alongside) Office, 1969 T24S R2W 1/4 S 3
New BT's: 8" Hemlock N. 22°W. 49.4 ft. mkd: "1/4 S 34 CS BT".
12" Hemlock S. 82°W. 28.1 ft. mkd: "1/4 S 3 CS BT".
No other trees available.

Brass Cap lies toward easterly end of root-wad of N.E. Orig. BT.
7/18/69

Section Corner to Secs. 3 & 4, T24-2W and Secs. 33 & 34, T23-2W. 57
Found - Orig. 36", now 48" Fir, alive, S. 25°E. 46.2 ft., open & scrb. vis.
Orig. 18" Hemlock N. 11°E. 5.3 ft., down, face up.
Other Original BT's gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W 1/4 S 33 | S 34
Office, 1969 T24S R2W 1/4 S 4 | S 3
New BT's: 8" Hemlock N. 49°E. 45.0 ft. mkd: "T23S R2W S 34 CS BT".
10" Hemlock S. 7°W. 45.5 ft. mkd: "T24S R2W S 4 CSBT".
No other suitable trees available.

Brass Cap lies toward easterly end of root-wad of N.E. Orig. BT.
7/18/69

Section Corner to Secs. 3 & 2, T24-2W and Secs. 34 & 35, T23-2W. 58
Found - Orig. 8", now 12" Chinquapin, alive, N. 85°E. 13.2 ft., scribe
visible.
Orig. 24", now 30" Fir, alive, S. 48°E (Rec. S68E) 21.1 ft.,
shows good scar.

Orig. 24", now 28" Fir, alive, S. 38°W. 11.9 ft., shows good scar.
We Rescribe: "T24S R2W S 3 CS BT".
Orig. 24", now 28" Fir, alive, N. 46 1/2°W. 25.1 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R2W S 34 | S 35
Office, 1969 T24S R2W S 3 | S 2
New BT: 34" D. Fir N. 66°E. 28.0 ft. mkd: "T23S R2W S 35 CS BT".
This corner lies on very steep, southerly slope in dense rhododendron,
vinemaple and old growth fir.

7/29/69

Section Corner to Sections 23 - 24 - 25 - 26. 59
Found - Orig. 40", now 48" Fir, N. 29°W. 41.6 ft., alive, scribe visible.
No trace of 1" I. Pipe called for in Ren. #15.
24" D. Fir S. 58°E. 31.4 ft., alive, good condition.
10" D. fir N. 47°E. 33.0 ft., alive, good condition.
14" D. Fir S. 5°W. 40.0 ft., alive, good condition, (record dist. 37')

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office 1969

S 23	S 24
S 26	S 25

(in mound of stone)

This corner lies in cutting corner, clear cut in section 24 at present.
7/29/69

1/4 Corner to Sections 26 and 35. 60
Found - 1951 Cad. Brass Cap, in place, properly marked. open.
26", now 27" Fir, low cut stump, N. 42 3/4°E. 67.3 ft., find scribe.
40", now 41" Fir, alive, S. 14 1/2°E. 64.7 ft., pitched blaze.

New BT: 9" Hemlock N. 83°W. 24.1 ft. mkd: "1/4 S 26 CS BT".
This corner lies 5 ft. south of cat fir trail for recent logging in Sec. 26.
8/20/69

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July, 1969
C.S. File No. 54/27

RE-RENEWED, SEE CORNER NO #100