

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Jack Heritage & V. Perron
August, 1969
C. S. File No. 54/27

61
 $\frac{1}{4}$ Corner to Sections 13 and 14.
 Found - Orig. 7", now 13" Fir, alive, S.49°E. 3.3 ft., open & find scribe
 & reverse under approx. 70 years overgrowth.
 No trace other Orig. BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W.
 Office, 1969 $\frac{1}{4}$ S 14 | S 13
 New BT's: 13" D. Fir N.75°E. 15.5 ft. mkd: " $\frac{1}{4}$ S13 CS BT".
 14" D. Fir S.12°W. 61.6 ft. mkd: " $\frac{1}{4}$ S14 CS BT".
 This corner lies on westerly slope about 660 ft. south of ridge top.

62
 Section Corner to Sections 10 - 11 - 14 - 15.
 Found - Orig. 30", now 34" Fir sawed stump, mostly buried in log landing,
 S. 20°E. 21.8 ft.
 No trace other Orig. BT's. due to old logging.
 40" Fir, down, S.86°W. approx. 42.0 ft., notch for "W" nail
 on under side, plate still attached. See Ren. #20.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
 (6' steel fence post Office S 10 | S 11
 1.0' W. of Brass Cap) 1969 S 15 | S 14
 New BT's: 50" D. Fir N.67°W. 60.0 ft. mkd: "T24S R2W S10 CSBT".
 40" D. Fir S.78°W. 86.6 ft. mkd: T24S R2W S15 CS BT.
 No other trees available.
 This corner lies on log landing 60 ft. E. of old growth timber, course N-S.

63
 $\frac{1}{4}$ Corner to Sections 21 and 28.
 Found - Orig. 16", now 18" Fir decayed stump, S.20°E. 16.5 ft., open &
 find " $\frac{1}{4}$ S" scribe.
 No trace other Orig. BT. - Weyerhaeuser reference trees now burned stumps
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W.
 (6' steel fence post Office $\frac{1}{4}$ S 21
 set alongside B. C.) 1969 S 28
 No trees nor solid stumps available, we set:
 $\frac{3}{4}$ " x 30" I. Rod North 10.0 ft.
 $\frac{3}{4}$ " x 30" I. Rod west 20.0 ft. as reference to $\frac{1}{4}$ corner.
 This corner lies in old clear cut unit in greasewood.

64
 $\frac{1}{4}$ Corner to Section 11 and 14.
 Found - No trace of Corner Stone.
 Orig. 30", now 35" Fir, alive, S.52°E. 29.7 ft., shows good scars.
 We Rescribe " $\frac{1}{4}$ S14 CS BT".
 Orig. 6", now 6" Chinquapin Snag, N.28°E. 18.5 ft., fragmentary
 scribe visible on decayed axe blaze.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
 Office $\frac{1}{4}$ S 11
 1969 S 14
 New BT: 8" Cedar N.86°W. 33.9 ft. mkd: " $\frac{1}{4}$ S11 CS BT".
 This corner lies on bench, gently sloping S.W.

65
 Section Corner to Sections 11 - 12 - 13 - 14.
 Found - Orig. Corner Stone with 4 notches on South & 1 notch on East edges.
 Orig. 36", now 42" Fir, alive, N.85°E. 22.4 ft., bark scribed.
 Orig. ?, now 32" Fir, S.33°E. 34.3 ft., alive, shows good scar.
 Orig. 6", now 13" Maple, alive, S.38°W. 22.4 ft., shows good axe scar.
 We Rescribe "T24S R2W S14 CS BT". (Record, Fir)
 Orig. 8", now 15" Maple, N.73°W. 38.3 ft. (Rec. 18.5 ft) face down & under
 logs, shows scar & was tagged, apparent 30 lk. error.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
 (Reset Corner Stone Office S 11 | S 12
 Alongside) 1969 S 14 | S 13
 New BT's: 20" Hemlock N.27°W. 29.9 ft. mkd: "T24S R2W S11 CS BT".
 8" Hemlock N.54°E. 28.8 ft. mkd: "T24S R2W S12 CS BT".