

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

John M. Powell
W. Penley & J. Heritage
August, 1970 C.S. File No. 54/27

V. "Ray" Tracy
V. Perron & G. McChesney
(Weyerhaeuser)
C.S. File No. 54/27

$\frac{1}{4}$ Corner to Sections 3 and 2.

Found - 30", now 42" Fir, N.29°W. 26.4 ft., shows good scar.
40", now 58" Fir, N.78 $\frac{1}{2}$ °E. 6.6 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office, 1970 $\frac{1}{4}$ S 3 | S 2

Bearing Trees O. K. and Tagged.

8/28/70

83

$\frac{1}{4}$ Corner to Sections 3 and 10.

Found - Unrecorded 1" Iron Pipe at $\frac{1}{4}$ corner.
24", now 27" Hemlock, S.26°E. 5.9 ft., scribe visible " $\frac{1}{4}$ ", Tree opened.
30", now 32" Hemlock N.71 $\frac{1}{2}$ °E. 8.6 ft., scribe visible " $\frac{1}{4}$ ", Tree opened.
15x10x8 Stone lying on side at $\frac{1}{4}$ corner, mkd: " $\frac{1}{4}$ ".

Set - Brass Cap at Cor. Mkd: County Surveyor's T24 S R 2 W
Office S 3
1970 S 10

Reblzd. & Resbd: 32" Hemlock N.71 $\frac{1}{2}$ °E. 8.6 ft. scribed " $\frac{1}{4}$ S3 CS BT".
This corner lies on steep, west slope about 240 ft. E. of Rock Creek.

8/28/70

84

$\frac{1}{4}$ Corner to Sections 10 and 11.

Found - 6", now 9" Yew, S.70°E. (Rec.S85E) 21.8 ft., shows old aze work, rotten face.
7", now 12" Yew, N.20°W. 13.9 ft., scribing found, "T" & other marks, rotten face.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office, 1970 $\frac{1}{4}$ S 10 | S 11

Rebzd. & Resbd: 9" Yew S.70°E. 21.8 ft. mkd: " $\frac{1}{4}$ S11 CS BT".
12" Yew N.20°W. 13.9 ft. mkd: " $\frac{1}{4}$ S10 CS BT".

Topography sheet for this corner is way off. Calls on creek & Top of Ridge D.K.

9/11/70

Also see notes in C.S. 59/11 - FO. OK WEYERHAEUSER

FO. OK 3/17/92
B.L.M.
C.S. 63/140

85

$\frac{1}{4}$ Corner to Sections 27 and 26.

Found - 16", now 24" D. Fir, N.33°E. 46.0 ft., faces badly burnt, scribe legible
BT, other marks not legible.

No trace of N.W. BT or Corner Stone, due to Skid Road, Ren. #2.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office, 1970 $\frac{1}{4}$ S 27 | S 26

New BT: 13" Cedar S.70°W. 47.9 ft. mkd: " $\frac{1}{4}$ S27 CS BT".

Reblzd. & Rescbd: 24" D. Fir N.33°E. 46.0 ft. mkd: " $\frac{1}{4}$ S26 CS BT".

8/26/70

RE-RENEWED, SEE CORNER NO. #112

86

Section Corner to Section 9 - 10 - 15 - 16.

Found - Orig. 30", now 34" Hemlock, N.35°E. 8.6 ft. (Rec.74.6), ring
count difficult, very fine, about 60 to 80 years, open, scribe
visible.

Orig. 24", now 36" Cedar, down, S.55°W. 34.3 ft., open & find scribe.

No trace of Yew wood BT. to N.W.

Decayed Stub at locus of S.E. Vine Maple BT.

Old blazed lines N-S-E & W would also bear out this location.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
Office S 9 | S 10
1970 S 16 | S 15

New BT's: 61" D. Fir N.41°W. 23.6 ft. mkd: "T24S R2W S9 CS BT."
(21.2 ft. to "W" Nail)

8" Hemlock S. 6° E. 33.8 ft. "T24S R2W S16 CS BT".

Add "W" to Orig. BT. to N.E. - This area to be clear cut in future.

10/16/70

87

Section Corner to Sections 5 - 6 - 7 - 8.

Found - Unrecorded $\frac{1}{2}$ " Monel Pipe for Corner & a $\frac{1}{2}$ " x 10' high marked
pipe set from 3 original BT's, (Weyerhaeuser Corner)

Orig. 10", now 14" Fir sawed stump N. 27 $\frac{1}{2}$ °E. 35.0 ft.

Orig. 10", now 32" Fir sawed stump, S.39°W. 27.7 ft., good scar.

Orig. 36", now 40" Fir sawed stump, N.58°W. 35.0 ft., scribed reverse
found. Record bearing N.19 $\frac{1}{2}$ °W. No trace Orig. BT. to S.E.

8/15/69

88

MARCH 71