

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 2 R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

89

Section Corner Secs. 28, 27, 33, 34

Found - One BT intact, a 22" now 24" Hemlock snag mkd. by BLM crews in 1951 during a resurvey. This area has experienced landslie activity and as a result, there is no other evidence of the orig. or subsequent surveys.

We therefore set a witness corner 85 ft. south of the true corner point as determined from the only remaining BT a 24" Hemlock snag bearing N.9 1/4°E., 55.4 ft. with scribing "T24 S R2W S27 BT plainly visible on an unhealed blaze.

Set - At the witness corner we set a 1" x 30" Iron pipe, 28" in the ground with a brass cap attached mkd.

COUNTY SURVEYORS	T 24 S R 2 W
OFFICE	S 28 S 34
1974	S 33 S 34

Witness Cor.
85 ft, North
to true Cor.

New BT's - A 12" Red cedar bears N.35°E., 30.3 ft. scribed "WC T24S R2W S33 CS BT"

An 18" D.Fir bears S.54°W., 23.9 ft. scribed "WC T24S R2W S33 CS BT"

A 26" Hemlock bears N.64°W., 42.5 ft. scribed "WC T24S R2W S33 CS BT"

10/14/74

Gary L. Langlitz, Surveyors Office
Peter L. Earle
CS 57/8
Oct. 14, 1974

JAN 75

90

1/4 Corner for Secs. 17 and 20.

Found - A 15" x 12" x 6" Basalt stone with "1/4" chiseled on north face
From which:

An orig. 36" now 42" D. Fir bears N.20°W., 7.3 ft. dist. A scribed "S" is visible on partly opened blaze. Tree is dead.
An orig. 30" now 42" D. Fir bears S.50°W., 7.3 ft. dist. Tree has healed over blaze and is alive and well.

Set - 1" x 30" Iron pipe with brass cap stamped:

Douglas County Surveyors	T24S R2W
1976	S 17
	S 20

New BT - A 25" D. Fir bears S.29°E., 24.1 ft. mkd. "1/4 S20 CS BT" in a double blaze.

Note: We replace orig. stone on north side of brass cap.
Compass dec. 20° east.

4/26/76

A. Victor Gangie, Surveyor's Office
G. Langlitz
D. Stewart
April 26, 1976
C.S. 59/8

91

1/4 Corner for Secs. 15 and 16.

Found - An orig. 60" D.Fir, now 60" stump, with scribing "1/4S" visible on previously opened blaze. Ring count indicates approx. 80 yrs. of growth and six inch increase in diameter.

We do not find any evidence of the orig. NW BT or the orig. corner monument.

At the true corner point as determined by the record bearing and distance, N.10°E., 14.5 ft. to the found OBT:

We Set - A 1"x30" Iron pipe 26" in the ground with brass cap attached mkd.
Douglas County Surveyor T 24 S R 2 W
1976 S 16 S 15
1/4

From which we note the following bearing objects:

A "Weyerhaeuser nail" driven in a notch on the face of the orig. BT stump, bears N.10°E., 11.7 ft.

A 42" D. Fir stump bears S.78°W., 9.0 ft. ("Weyerhaeuser nail" in this stump bears S.82°W., 7.7 ft.)

We also find an unrecorded 3/4" x 30" Alum pipe at corner point. We place it alongside the brass cap.

9/1/76

Gary L. Langlitz, Doug. Co. Surveyors
Mike Tompkins
Sept. 1, 1976
C.S. 59/24