

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Gary L. Langlitz, Do. Co. Surveyors Off.  
Karen Cheney  
Sept. 22, 1976  
C.S. 59/24

Witness Corner for SEcs. 19, 20, 30 and 29.  
Found - Orig. NW BT, now stump, situated on top edge of road cut & slid out of orig. position.  
No trace of other orig. evidence.  
40" D.Fir stump with railroad spike in center, bears S.50°W., 40.6 ft. (Weyerhaeuser record, S.50°W., 40.6 ft.)  
36" Hemlock stump with "W" nail, bears S.67°W., 28.3 ft.  
44" D.Fir stump with "W" nail bears S.62°W., 124.7 ft.  
40" D.Fir stump with "W" nail bears S.86°W., 79.3 ft.  
48" D.Fir stump with "W" nail bears N.49°W., 125.0 ft.  
We do not find the 1/2" I.P. set by Weyerhaeuser Co.

See 1972 Weyerhaeuser notes in C.S. 59/24.  
Since this cor. position falls on the road cutbank, WE SET a witness cor. 50' West of the true corner.

Set - A 1"x30" I. Pipe, 24" in the ground with brass cap attached mkd.  
Douglas Co. Surveyor Wit. Cor.  
1976 East 50 ft. to  
T24S R2W  
S 19 | S 20  
S 30 | S 29

From which we note the following bearing objects:

The aforementioned railroad spike set in a 36" D.Fir stump bears S.34 1/2°E., 33.6 ft. from the witness corner.  
A 5/8" x 30" I. Rod driven 16" deep in the center of a 38" Hemlock stump, bears S.36°W., 39.2 ft. with alum. cap attached, mkd. "Douglas County Surveyor WC RP2". This stump has been notched for use as a logging anchor.  
A bridge spike driven in the center of a 38" D.Fir stump marked "WC RP 3 bears N.36°E., 10.6 ft.

Note: This corner is located approx. 50 ft. west of Weyerhaeuser Rd. #317.  
9/22/76

1/4 to T24-2W. Sec. 1, and T23-2W. Sec. 36.

Found- Stone 20"x12"x7" mkd.: "1/4", tipped out.  
Orig, 12" now 13" Hemlock, alive, N64°W., 6.6 ft., scribe visible on nearly healed blaze. Rescribed "1/4 S36 CS BT".  
Orig. 10", now 11", Hemlock, alive, S6°W., 16.5 ft., scribe visible on previously opened blaze. Rescribed "1/4 S1 CS BT".

Set - Brass cap at corner mkd. County Surveyor's T23S R2W 1/4 S36  
( Reset old cornerstone Office, 1969 T24S R2W 1/4 S31  
along-side )

This corner lies 15ft. S. and 30 ft. E. of small creek flowing SW.

Sec. Cor. to Secs. 1 & 2, T24-2W. and Secs. 35 & 36 T23-2W.  
Found - Orig 18", now 20" Fir snag, N 53°E., 13.9 ft., open scribe visible.

Orig 30", now 40" Fir, alive, S29°E., 37.8 ft., ( Rec. S49°E )  
Shows good scar.

Orig. 48", now 58" Fir, alive, S 25° W, 21.1 ft., shows good scar.

Orig. 30", now 38" Fir, alive, N28° W, 19.1 ft., shows good scar.

Set- Brass Cap at corner mkd. County Surveyor's T23S R2W S 35 | S 36  
Office, 1969 T24S R2W S 2 | S 1

New BT: 52" D. Fir N 13° E., 74.4 ft., mkd. " T23S R2W S36 CS BT".

No smaller trees available. This corner lies on moderate S. W. slope in old growth timber.  
7/8/69

Northwest corner of Tract 37. (in Sec. 33)

Found - 1963 GLO brass cap.  
10" Hemlock, now 12" bears N.83°E. (Rec. N.81 1/2°E.) 62.6 ft. (Rec. 62.0 ft.) scribing visible with BT tag.

9" Yew, now 10" bears S.46°E., (Rec. S.47 1/2°E.) 68.3 ft. (Rec. 67.3 ft.) scribing visible with BT tag.

New BT's- 46" Fir bears S.42°E., 57.6 ft. with "W" nail and plate.

58" Fir bears S.87°E., 65.4 ft. with "W" nail and plate.

12/20/75

Vernon "Ray" Tracy  
Jack Heritage and V. Pexron  
July, 1969 C. S. 54/27

3/77

Frank O. Williams  
y: Glen McChesney  
or: Weyerhaeuser Co.  
ec. 20, 1975  
.S. 58/8

Jan 78

92

93

94

95