

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 2 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

116

Northwest corner, Tract 40. (Section 35)

Found - 1963 GLO 2½" dia. by 28" long I.P. with brass cap out of ground leaning against NE BT. (Cap properly marked)

32" now 33" dia. 5 ft. high D. fir stump with a fully healed single blaze that we partially open and find scribing "BT" bears N.61 3/4°E., 35.0 ft. (agrees with record)

30" now 31" dia. D. fir with a fully healed single blaze bears S.23½°E., 23.8 ft. (Rec. S.21½°E., 23.8 ft.)

Douglas County
Surveyors Office
Randall Smith
Stephen Flauser
Dec. 9, 1986
C.S. 62/38

Set - Brass cap/I.P. set at position determined by intersecting distances and bearings (SE BTs bearing slightly different than record) Old flagging was found approx. 1 ft. under ground in hole dug to reset BC/IP. We stamp 1963 BLM cap "RESET 1986". BC/IP protrudes 10" above ground, surrounded by a 2½ ft. dia. mound of stone.

The Northeast corner TR 39, a 2½ dia. I. pipe and brass cap, bears N.21½°E., 64.7 ft.

New BTs - 9" maple double blazed and scribed "S36 CS BT" bears N.81½°E., 23.0 ft.

20" D. fir double blazed and scribed "TR 39 CS BT" bears S.55°W., 14.0 ft.

Corner lies at SW corner of new clearcut on steep NW slope.

12/9/86

Section Corner for Sections 12 and 13; and 7 & 18 of T.24-1
CONDITION REPORT ONLY

117

Found - A 2½" brass cap on an iron pipe set approx flush with ground. (1969 County cap, Ren. #70)

Orig. BT, a 24" fir now 30" dia. 1½ ft. tall stump with no bark scribing visible bears N.75°E., 17.9 ft. dist. (Rec. N.75°E., 17.2 ft. probable face measurement)

Orig. BT, a 30" fir now a 36" dia. 3½ ft. tall fir stump with no bark scribing visible bears S.81°E., 20.7 ft. (Rec. S.81°E., 19.8 ft. probable face measurement)

Orig. BT, a 32" hemlock now a 38" DBH hemlock with illegible scribing visible in a partially healed single blaze bears S.79°W., 30.4 ft. (Rec. S.75°W., 30.4 ft.)

Orig. BT, a 20" fir now a 20" dia. 1½ ft. tall rotted fir stump with no bark scribing visible bears N.59°W., 35.3 ft. (Rec. N.61°W., 33.0 ft.)

A 10" hemlock now an 11" DBH 6 ft. tall metal capped hemlock stump with the scribing 24S R2W S12 CS BT visible in a partially healed single blaze bears N.6°W., 22.3 ft. Ren. No. 70

A 22" hemlock now a 22" 4½ ft. tall metal capped hemlock stump with the scribing T24S R1W S18 CS BT visible in a partially healed single blaze bears S.43°E., 59.5 ft. Ren. No. 70

(NE bearing tree gone due to a road work)

No suitable line trees nearby. All found stumps are in good condition except one rotted stump as noted. Cap lies on steep northerly slope above cut bank for logging spur road.

11/8/90

Section Corner for Sections 26, 27, 34 & 35.

118

Found - 2½" dia. G.L.O. brass cap on a 2" O.D. iron pipe, protruding 6" above ground. BC/IP leans 4" southwest of plumb. Cap is marked "U.S. General Land Office T.24S R.2W S 27 S28 S34 S35 1951 Survey"

Accessories Found -

16" now 30" dia 25 ft. high Hemlock snag with scribing visible on an opened blaze 'S26' bears N.16½°E., 21.6 ft. (rec. N.16½°E., 19.8')

10" now 20" dia. 2 ft. high Hemlock stump with scribing '35' visible on a rotted blaze. Bears S.31½°E., 42.9 ft. Orig. BT'S

18" now 28" dia. 15 ft. high Cedar snag with scribing visible '2W' on an opened blaze. Bears S.26½°W., 19.1 ft. Orig. BT.

20" now 26" dia. 25 ft. high Cedar snag, no blazes or scribing visible. Bears N.9½°W., 16.8 ft. (1951 GLO rec. N.9½°W., 15.8 ft) Orig. BT.

Monument Set -

Returned 1951 G.L.O. BC/IP to plumb position, protrudes 6" above ground

New Accessories -

7" dia. Hemlock double blazed and scribed 'T24S R2W S27 CS BT' bears N.16½°W., 33.3 ft.

7" dia. D. Fir double blazed and scribed 'T24S R2W S26 CS BT' bears N.61°E., 31.6 ft.

-CONTINUED NEXT PAGE-