

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

ROBE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Corner to Sec. 34, T24-3W. & Sec. 3, T25-3W.  
Found - GLO Brass Cap mkd. 1944 with steel fence post set alongside. *Found. O.K. by B. Holt 12-81 SEE M 90-16*  
Orig. 30", now 42" I. Cedar, N. 4° W. 13.2 ft., prev. opened & face rotted away.  
Orig. 48", now 52" Fir; S. 68° W. 7.3 ft., now broken Stub, 10' high, shows good scar. We do not open.  
34", now 40" I. Cedar, N. 37 $\frac{1}{2}$ ° W. 25.7 ft. (recorded as 27.1 ft.)  
Alive, shows good scar. We do not open.  
New BT's: 12" D. Fir S. 31 $\frac{1}{2}$ ° W. 34.2 ft. Mkd:  $\frac{1}{4}$  S 3 CS BT.  
9" D. Fir N. 36 $\frac{1}{2}$ ° E. 17.0 ft. mkd:  $\frac{1}{4}$  S34 CS BT.  
Note - Norman Price called for distances to be reversed on Orig. BT's., but we find corner to be set as called for using Orig. distances of Orig. BT's., only bearings differ.

50

Sec. Cor. to Secs. 33 & 34, T24-3W. & Secs. 4 & 3, T25-3W.  
Found - GLO Brass Cap mkd. in 1943. *Found. O.K. by B. Holt 12-81 SEE M 90-16*  
50", now 54" Fir, N. 58° E. 8.3 ft. Alive, shows good scar & old bark scribe.  
48", now 51" Fir, South 35.6 ft. Alive, shows good scar.  
38" Fir Stub, very badly decayed, N. 44° W. 32.3 ft.  
5", now 7" Fir, S. 29 $\frac{1}{2}$ ° E. 13.2 ft. Alive, shows good scar.  
6", now 8" Fir N. 39 $\frac{1}{2}$ ° W. 33.0 ft. Alive, shows good scar.  
The largest firs are marketable Trees so we mark New BT's:  
8" D. Fir N. 13° E. 17.5 ft. mkd. T24S R3W S34 CS BT  
8" Live Oak S. 46° W. 29.2 ft. mkd: T25S R3W S 4 CS BT.  
Note - This corner lies on West Slope approx. 75 ft. west of Rock Bluff, 40 ft. high. See Ren. #3, T25-3W.

51

$\frac{1}{4}$  Corner to Sec. 33, T24-3W. & Sec. 4, T25-3W.  
Found - GLO Brass Cap mkd. 1944, set in concrete in basalt basset.  
Orig. 20", now 28" Madrone S. 67 $\frac{1}{2}$ ° W. 48.2 ft. Alive, prev. opened, rotting inside.  
36", now 37" Snag, Fir, N. 26 $\frac{1}{2}$ ° W. 31.7 ft., shows good scar, also " $\frac{1}{4}$  S BT" in bark. See Ren. # 1, T25-3W.  
36", now 37" Fir, shattered Stump, S. 51 $\frac{1}{2}$ ° E. 17.8 ft., shows "4 BT".  
New BT's: 8" Madrone S. 27° E. 21.3 ft. mkd;  $\frac{1}{4}$  S 4 CS BT.  
12" Chinquapin N. 85° E. 19.1 ft. Mkd:  $\frac{1}{4}$  S 33 CS BT.  
Note - Corner lies on S. W. slope.

52

Sec. Cor. to Secs. 34 & 35, T24-3W. & Sec. 3 & 2, T25-3W.  
Found - GLO Brass Cap mkd. in 1944 with steel fence post set alongside, and bent over. (Reset Fence Post alongside Cap)  
60" Fir Stump N. 33 $\frac{1}{2}$ ° E. 52.1 ft., shows "T24SR3W S35BT" scribe on unhealed blaze.  
12", now 20" R. Cedar S. 29° E. 4.6 ft., shows good scar. *Found. O.K. by B. Holt 12-81 M 90-16*  
Rescribed - "T25S R3W S 2. CS BT".  
6", now 16" Fir S. 48 $\frac{1}{2}$ ° W. 40.3 ft., 48" log lying against scar, only top of scar visible.  
8", now 14" R. Cedar Snag N. 51 $\frac{1}{2}$ ° W. 37.6 ft., Dead & burned, no scribe.  
New BT's: 6" D. Fir N. 10° E. 23.9 ft. mkd. T24S R3W S35 CS BT.  
17" R. Cedar N. 69° W. 35.6 ft. mkd: T24SR3W S 34 CS BT.  
Note - Corner lies on moderate west slope approx. 120 ft. W. of top of spur.

53

Section Corner to Sections 15 - 16 - 21 - 22.  
Found - 1950 Cad. Brass Cap, firmly set & properly marked.  
Do not find mound of stone called for.  
Find BT's. as recorded in Ren. #6. &  $\frac{1}{2}$ " monal pipe set alongside. *# 99*  
New BT's: 5" Maple N. 79° W. 22.5 ft. mkd. "S16 CS BT".  
6" Maple N. 8° W. 14.0 ft. mkd. "S16 CS BT".  
Note - These are the only trees available. Corner is also marked by  $\frac{1}{2}$ " I. P. 10 ft. long, 7 ft. above ground.

54

Vernon "Ray" Tracy  
Jack Heritage  
Sept., 1966  
C. S. File No. 54/27

RE-NEWED CORNER NO. # 99  
Aug. 29, 1967